



## **BRA and Lead Evaluation Status**

### **Fort Ord HTW BCT**

**14 March 2019**

#### **Basewide Range Assessment**

- KEMRON is resolving Army comments on the draft final sampling report for Units 1, 2, 3, 7, 10, 33, and WGBA.
- KEMRON submitted the draft final sampling results report for Units 25 and 28. DTSC has no additional comments. FOCAG comments received and RTCs are in progress.
- KEMRON is resolving comments on the HAs addressed under the current contract for the update to the Comprehensive BRA Report.
- KEMRON conducted a site reconnaissance in BLM Area B accessible areas in January and has prepared a description of the findings.

#### **Lead Evaluation Sites**

- KEMRON plans to meet with DTSC to discuss the cleanup level for the ESD.

#### **Site 39 Erosion Control**

- KEMRON is monitoring Site 39 areas throughout the Impact Area MRA for erosion issues.
- KEMRON is addressing maintenance issues at erosion control sites.

#### **Building Demolition Project**

- Please see attached table, figures, and pictures from the building demolition project.

KEMRON Range Structure Removal Schedule March 1st, 2019  
19 of 33 Structures Demolished

|             | ID  | Structure               | Burn Unit | Comp     | ACM       | Structure Status  |
|-------------|-----|-------------------------|-----------|----------|-----------|---|
| IMPACT AREA | 1   | Latrine                 | 1         | Wood     | confirmed |   |
|             | 2   | Latrine                 | 1         | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 3   | Canopy                  | 1         | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 4   | Latrine                 | 4         | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 5   | Range House             | 4         | Block    | confirmed |   |
|             | 6   | Range House             | 4         | Block    |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 7*  | Observation Deck        | 5         | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 8   | Observation Tower       | 6         | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 9   | Latrine                 | 6         | Wood     | confirmed |   |
|             | 10  | Canopy                  | 6         | Steel    |           | Structure removed and placed in A&S Metals salvage container  |
|             | 11  | Canopy                  | 6         | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 12  | Canopy                  | 9         | Steel    |           | Structure removed and placed in A&S Metals salvage container  |
|             | 13  | Latrine R9322           | 13        | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 14  | Latrine R9320           | 13        | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 15  | Observation Tower       | 18        | Wood     |           |   |
|             | 16* | Unknown Box             | 21        | Wood     |           |   |
|             | 17  | Training Building       | 21        | Wood     | confirmed | On deck   |
|             | 18  | Observation Tower       | 21        | Wood     | confirmed | On deck   |
|             | 19  | Observation Tower       | 21        | Wood     | confirmed |   |
|             | 20  | Observation Tower R9386 | 34        | Wood     |           |   |
|             | 21  | Observation Tower       | 34        | Wood     | confirmed |   |
|             | 22  | Latrine R9382           | 21        | Wood     |           |   |
|             | 23  | Latrine R9381           | 34        | Wood     | confirmed |   |
|             | 24  | Latrine R9380           | 34        | Wood     |           |   |
|             | 25  | Canopy                  | 34        | Wood     |           |   |
|             | 26  | Canopy                  | 5A        | Metal    |           | Structure removed and placed in A&S Metals salvage container  |
|             | 27  | Latrine                 | 5A        | Wood     | confirmed | Mastic with ACM was cut out and left for Abatement contractor - structure removed to the Iron Triangle    |
|             | 28* | Latrine (AD exempt)     | 5A        | Wood     |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
|             | 29  | Range House             | 5A        | Block    |           | Demolition completed/site restored. Debris is staged at the Iron Triangle                                 |
| BLM Area B  | 30  | Latrine                 | B3W       | Wood     |           | Demolition completed/site restored and debris stockpiled at the OU2 landfill Area E - ready for placement |
|             | 31  | Latrine                 | B3W       | Wood     |           | Demolition completed/site restored and debris stockpiled at the OU2 landfill Area E - ready for placement |
|             | 32  | Canopy                  | B3W       | Wood     |           | Demolition completed/site restored and debris stockpiled at the OU2 landfill Area E - ready for placement |
|             | 33  | Concrete Pad            | B3W       | Concrete |           | Concrete removed and used as fill in Item 31 latrine pit.   |

BLM has requested demolition of these structures to facilitate future management of the Units noted; these structures are in burn or cut units where MEC cleanup has occurred and no habitat burn is required as part of the CERCLA remedy but future prescribed burns by BLM may be accomplished, DGM mapping has not been accomplished below the footprint of these structures.

\* Indicates an item designated as 'not regulated' by MBARD



Confirmed for the presence of Asbestos Construction Material

Structure Demolition and removal complete

**ID Structure**

- 1 Latrine
- 2 Latrine
- 3 Canopy
- 4 Latrine
- 5 Range House
- 6 Range House
- 7 Observation Deck
- 8 Observation Tower
- 9 Latrine
- 10 Canopy
- 11 Canopy
- 12 Canopy
- 13 Latrine R9322
- 14 Latrine R9320
- 15 Observation Tower
- 16 Unknown Box
- 17 Training Building
- 18 Observation Tower
- 19 Observation Tower
- 20 Observation Tower R9386
- 21 Observation Tower
- 22 Latrine R9382
- 23 Latrine R9381
- 24 Latrine R9380
- 25 Canopy
- 26 Canopy
- 27 Latrine
- 28 Latrine
- 29 Range House

Week Ending March 01, 2019  
 19 of 33 Structures Complete  
 Buildings 30 -33  
 B3 West Not Shown



Field Work Variance No. 023  
 FORMER FORT ORD  
 MONTEREY COUNTY, CALIFORNIA

**Figure 1**  
 Impact Area MRA  
 Structures Designated for Removal  
 Location Map



A) Workers spent several days gaining entrance to the structures in Unit 13 by clearing the old access road.

B) Construction workers slid the latrine to a location where it was easier to demo.