



Photograph 1: January 16, 2008. Projectile, 75mm, shrapnel, MK I (unfuzed). Recovered during roadway alignment clearing and grubbing activities north of MRS-15SEA.4.



Photograph 2: January 25, 2008. Grenade, hand, practice, MK II. Recovered during roadway alignment clearing and grubbing activities on MRS-15SEA.1.



Photograph 3: January 29, 2008. Projectile, 57mm, HE M306 (unfuzed). Recovered during roadway alignment clearing and grubbing activities north of MRS-15SEA.4.



Photograph 4: January 30, 2008. Grenade, hand, smoke, M18 (green). Recovered during roadway alignment clearing and grubbing activities north of MRS-15SEA.3.



Photograph 5: January 30, 2008. Grenade, M69, practice. Recovered during roadway alignment clearing and grubbing activities north of MRS-SEA15.3.



Photograph 6: February 6, 2008. Grenade, hand, smoke, M18 (purple). Recovered during roadway alignment clearing and grubbing activities north of MRS-15SEA.4.



Photograph 7: May 28, 2008. Cap, blasting, electrical, M6. Recovered during soil sifting activities for soil from MRS-15SEA.1.



Photograph 8: May 30, 2008. Charge, 2.5 lbs, demolition, TNT. Recovered during DGM anomaly investigation in hillside west of GJMB.



Photograph 9: June 4, 2008. Cartridge, 57mm, TP M306A1 (includes projectile, unfuzed). Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 10: June 10, 2008. Fuze, mine, antitank, practice, M1A1 (safety clip in place). Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 11: June 12, 2008. Fuze, PD, French No. 5. Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 12: June 12, 2008. Projectile, 57mm, TP M306 (unfuzed, unfired with possible spotting charge). Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 13: June 13, 2008. Fuze, mine, antitank, practice, M1A1 (safety clip in place). Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 14: June 13, 2008. Burster tube. Recovered during DGM anomaly investigation in SCA_W048 on MRS-15SEA.1.



Photograph 15: June 17, 2008. Cartridge, 57mm, M60A1 (no projectile, primer live). Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 16: June 18, 2008. M407A1, 40mm, practice. Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 17: June 24, 2008. One of two Igniter, flame throwers. Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 18: June 26, 2008. Hand grenade fuze. Recovered during DGM anomaly investigation in hillside west of GJMB.



Photograph 19: July 15, 2008. Rocket, 35mm, subcaliber, practice, M73. Recovered during soil sifting activities for soil from MRS-15SEA.4.



Photograph 20: July 22, 2008. Projectile, 57mm, HE M306. Recovered during DGM anomaly investigation in SCA_W140 on MRS-15SEA.4.



Photograph 21: August 11, 2008. M407A1, 40mm, practice. Recovered during placement of oversize material in roadway repair work by Army.