



Photo 1. Well location MW-D (MW-OU1-85-A) looking west before clearing.



Photo 2. Well location MW-D (MW-OU1-85-A) looking west after clearing. See photo 8 for oak tree view after trimming.



Photo 3. Woodrat nest located near well location MW-G (MW-OU1-82-A).



Photo 4. Sandmat manzanita observed at well location IW-OU1-74-A.



Photo 5. Oak tree on western edge of well location IW-OU1-73-A that required trimming. See photos 14 and 15 for post-trimming view.