

Photo 11. Woodrat nest left intact on northern border of well location MW-E (MW-OU1-84-A).



Photo 12. Woodrat nest before dismantling on well location IW-OU1-73-A. See photo 16 for post-dismantling view.



Photo 13. Woodrat nest before dismantling on well location IW-OU1-73-A. See photo 17 for post-dismantling view.



Photo 14. Well location IW-OU1-73-A after clearing looking west.



Photo 15. Well location IW-OU1-73-A after clearing looking south to north.

Attachment

A

FONR OU-1 Environmental Monitoring Report Site Pictures

Page