

Photo 36. Finished well location MW-A (MW-OU1-88-A).



Photo 38. FONR staging area looking east after de-mobilization



Photo 37. FONR staging area looking west after de-mobilization.



Photo 39. EW-OU1-71-A representative of wells surrounded by a depression after settling of concrete. All depressions were subsequently filled by HGL field staff.

Attachment A

FONR OU-1 Environmental Monitoring Report Site Pictures

Page