
WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B7		
SCA'S IN GRID	W140, W122		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A246		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Krear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B6		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Klean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, aluminum, nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A245		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.08

UXO QC Specialist Signature _____ Date 7-28-08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7.28.2008
GRID ID	C2A24		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C 2A2A3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Keeun

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	BZJ2J4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008
Dan Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J2J3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J212		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	BZJ211		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1H0		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstadt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008

Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1G9		
SCA'S IN GRID	W059, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1H9		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scraps

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2 J168		
SCA'S IN GRID	W058, W140		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor Wire, Metal Scrap, Aluminum Cans

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1F7		
SCA'S IN GRID	W014, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2 J1E6		
SCA'S IN GRID	W014, W057		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008

Dan Keam

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2JF6		
SCA'S IN GRID	W014, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7/28/2008
GRID ID	B2J1E5		
SCA'S IN GRID	W001, W056, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1F5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Shonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1E4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7-28-08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7/28/2008
GRID ID	B2J1C4		
SCA'S IN GRID	W055		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.08
GRID ID	B2J1C3		
SCA'S IN GRID	W055		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.08

UXO QC Specialist Signature _____ Date 7.28.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2 J1 D3		
SCA'S IN GRID	W055, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7.28.2008
GRID ID	B2J1E3		
SCA'S IN GRID	W140, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7.28.2008
GRID ID	B2J1D2		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Winstanson	DATE	7/28/2008
GRID ID	B2J1E2		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7/28/2008
GRID ID	B2J1D1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7/28/2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7.28.2008
GRID ID	BDJ1E1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Christensen	DATE	7/28/2008
GRID ID	B15ODO		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7/28/2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE 7/28/2008
GRID ID	BIJOE0	
SCA'S IN GRID	W140	
INSTRUMENT(S) USED	Schonstedt	

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7/28/2008

UXO QC Specialist Signature _____ Date 7/28/08
Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7/28/2008
GRID ID	B1JOD9		
SCA'S IN GRID	W015		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jade Kristensen	DATE	7.28.2008
GRID ID	B1J0E9		
SCA'S IN GRID	W000, W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08
Don Krear


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Christenson	DATE	7/28/2008
GRID ID	BIJOD8		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7/28/2008
GRID ID	B1JOE8		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B1J0D7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7/28/2008
GRID ID	BIJOE7		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.08
GRID ID	B1J0E6		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A410		
SCA'S IN GRID	W087, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature TRCl Date 7-28-08


UXO QC Specialist Signature Don Krean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A4JO		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Krean Date 7.28.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-28-08
GRID ID	C244H9		
SCA'S IN GRID	W087		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature DK Date 7-28-08
Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony L Clark	**DATE**	7-28-08
GRID ID	C 2 A 4 1 9		
SCA'S IN GRID	W087, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A418		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature DJK Date 7.28.08

Don Kraus

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R. Clark	**DATE**	7-28-08
GRID ID	C2A4H8		
SCA'S IN GRID	W087, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	CZ4467		
SCA'S IN GRID	W074		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Dan Kream Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Barbed wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A4H7		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SCL		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-28-08
GRID ID	C2A4G6		
SCA'S IN GRID	W074, W140		
INSTRUMENT(S) USED	Sc4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-28-08
GRID ID	C2A4H6		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7-28-08
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-28-08
GRID ID	C2A4G5		
SCA'S IN GRID	W074, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-28-08
GRID ID	C2A4G4		
SCA'S IN GRID	W074 W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

John Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Clear

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2A4F3		
SCA'S IN GRID	W074		
INSTRUMENT(S) USED	Sc &		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-28-08
GRID ID	C2 A4G3		
SCA'S IN GRID	W074, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A4F2		
SCA'S IN GRID	W074, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Dan Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A4G2		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature Tony R Clark Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A4F1		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Dan Kean Date 7-28-08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A3F0		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7-28-08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R. Clark	**DATE**	7-28-08
GRID ID	C2A3F9		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sc 4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A3E8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Dan Kean Date 7-28-08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A3F8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08.

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Q1 Win

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	JACK KRISTENSEN	**DATE**	7.28.08
GRID ID	C2A3E7		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.28.08
GRID ID	C2A3E6		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.08

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.08
GRID ID	C21305		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3E5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7-28-08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C24304		
SCA'S IN GRID	W067, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Keam

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3E4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Krear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C 2 A3D3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3C2		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C 29302		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C243C1		
SCA'S IN GRID	W131, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3D1		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B0		
SCA'S IN GRID	W131		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2C0		
SCA'S IN GRID	W131, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature JK Date 7.28.2008

UXO QC Specialist Signature JK Don Kean Date 7.28.2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B9		
SCA'S IN GRID	W131		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2C9		
SCA'S IN GRID	W131, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C21C8		
SCA'S IN GRID	W140,		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008

Don Keam

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	CZA2B8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.28.2008

UXO QC Specialist Signature _____ Date 7.28.2008

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BID8A2		
SCA'S IN GRID	EW048		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(3) Wire


(1) Small metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1D8A1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	SCL		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Wire


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1D7A0		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1D7A9		
SCA'S IN GRID	W140, WOW		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(4) Barbed wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C8J1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.8

Don Kran


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1C7J0		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-20

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Iron scrap

(1) Asphalt

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7J9		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Doug Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7-20
GRID ID	B1C7J8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7-20

UXO QC Specialist Signature _____ Date 7/20/08

Don Kream


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7 I0		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7I9		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature _____ Date 7.20


UXO QC Specialist Signature _____ Date 7/23/08
Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	BIC718		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature TRCK Date 7.20

UXO QC Specialist Signature Donkean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) J wire

(2) Barbed wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	BIC7H0		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/06

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	BIC7H9		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-20

UXO QC Specialist Signature _____ Date 7/20/08

Dan Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Frag Scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7H8		
SCA'S IN GRID	W003, W140		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Frag Scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7H7		
SCA'S IN GRID	W003, W140		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Krause

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	BIC769		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/25/08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7G8		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C767		
SCA'S IN GRID	W140, W165		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Barbed wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7F9		
SCA'S IN GRID	W018		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date _____

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Wire

(2) metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7F8		
SCA'S IN GRID	W018, W048, W164		
INSTRUMENT(S) USED	SCL		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature T Clark Date 7.20

UXO QC Specialist Signature Don Kean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(5) Metal scrap


(2) Asphalt

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7F7		
SCA'S IN GRID	W048, W165		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7F6		
SCA'S IN GRID	W140, W165		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	BIC7E9		
SCA'S IN GRID	W135		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7E8		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7E7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


Don Kraus

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7E6		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7D5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SCN		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7D6		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1C7D7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7C6		
SCA'S IN GRID	W044, W163		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7C5		
SCA'S IN GRID	W048, W137, W140		
INSTRUMENT(S) USED	SCA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08
Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	BLC7B8		
SCA'S IN GRID	WO 37		
INSTRUMENT(S) USED	SCA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	BIC 787		
SCA'S IN GRID	W037		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7B6		
SCA'S IN GRID	W037, W048, W163		
INSTRUMENT(S) USED	SUH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Short cable

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7B5		
SCA'S IN GRID	W048, W163		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7A5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1C7A4		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	3ch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08
Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B/B 7J5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	scn		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑
N

UXO Technician Inspector Signature _____ Date 7.20


UXO QC Specialist Signature _____ Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1B7J4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1B7I5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCA.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

G1 / Barbed wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.30
GRID ID	B1B7I4		
SCA'S IN GRID	W035, W048		
INSTRUMENT(S) USED	Scn.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Rear sight

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1B7I3		
SCA'S IN GRID	W035, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Iron Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1B7H4		
SCA'S IN GRID	W035, W048, W130		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


2/Bolts

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1B7H3		
SCA'S IN GRID	W035, W048, W140		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1B765		
SCA'S IN GRID	W034, W130		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Dan Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1B764		
SCA'S IN GRID	W130		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Dan Kream


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	J. Clark	DATE	7.20
GRID ID	BIB763		
SCA'S IN GRID	W048, W153		
INSTRUMENT(S) USED	Scn.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Dan Bean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) wires

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1B7F5		
SCA'S IN GRID	W130		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1B7F3		
SCA'S IN GRID	W048, W153		
INSTRUMENT(S) USED	SCA.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


4 / Nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Llanez	DATE	7.20
GRID ID	B1B7E5		
SCA'S IN GRID	W151		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08


Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7.20
GRID ID	B187C1		
SCA'S IN GRID	W048, W124		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	**DATE**	7.20
GRID ID	B1B7B1		
SCA'S IN GRID	W124, W141		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20


UXO QC Specialist Signature _____ Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7.20
GRID ID	B1 BBAO		
SCA'S IN GRID	W140, W141		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08
Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Llanes	DATE	7.20
GRID ID	B1A6J0		
SCA'S IN GRID	W029, W141		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kream


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Chark	**DATE**	7.20
GRID ID	B1A6I9		
SCA'S IN GRID	W004, W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Aluminum Cans

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B1A6H9		
SCA'S IN GRID	W141		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Chanik	DATE	7.20
GRID ID	B1A6H8		
SCA'S IN GRID	W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	**DATE**	7.20
GRID ID	B116G8		
SCA'S IN GRID	SCAIs W123, W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

Dan Kream


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-20
GRID ID	B1A7F1		
SCA'S IN GRID	W030		
INSTRUMENT(S) USED	Schonstedt.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08


Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-20
GRID ID	B1A6F8		
SCA'S IN GRID	W123, W141		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20

UXO QC Specialist Signature _____ Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Barbed wire


(2) Nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	JACK KRISTENSEN	DATE	7.20.08
GRID ID	BID 7B9		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


RAZOR WIRE & WIRE

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.08
GRID ID	B1D7B0		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8B1		
SCA'S IN GRID	W0W, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Christensen	DATE	7.20.2008
GRID ID	B1D8B2		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8B3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B107CO		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Joe Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION

Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8C1		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8C2		
SCA'S IN GRID	W140, WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8C3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Doy Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B107D0		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, barbed wire, metal scrap, nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8D1		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, brass casings, aluminum, nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8D2		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, WIRE

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8D3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature Don Klean Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8D4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D7E0		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8E1		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Rebar, nails, wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B108E2		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, nails, wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8E3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8E4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kraus

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8F1		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.2008

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8F2		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8F3		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8G2		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B108G3		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B108G4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/8

Don Kraan


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	BID865		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑
N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap, barbed wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8H2		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, Aluminum, barbed wire.


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8H3		
SCA'S IN GRID	W140, W0N		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/24/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8H4		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	BID 845		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

DON KEAN


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8I2		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Dan Klecan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7.20.2008
GRID ID	B1D8I3		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kraus

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8I4		
SCA'S IN GRID	W039, W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, rebar

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8I5		
SCA'S IN GRID	W048, W134		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Fence material, razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8J2		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kraus


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, wire, metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1D8J3		
SCA'S IN GRID	W140, WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kraus

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8J4		
SCA'S IN GRID	W039, W048, W140, W162		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature JK Date 7.20.2008

UXO QC Specialist Signature JK Don Kream Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, household garbage.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8J5		
SCA'S IN GRID	W048, W134		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8A3		
SCA'S IN GRID	W140, W162, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/24/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.20.2008
GRID ID	B1E8A4		
SCA'S IN GRID	W048, W140, W162		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8B3		
SCA'S IN GRID	W140, W162		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8B4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	BJE8C4		
SCA'S IN GRID	W048 W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E805		
SCA'S IN GRID	W048, W125		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Doug Kreen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8E5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8F5		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kraan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8F6		
SCA'S IN GRID	W133, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8G6		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7/20/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8H6		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, metal scrap, Aluminum cans

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E817		
SCA'S IN GRID	W005, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap, razor wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E818		
SCA'S IN GRID	W005		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8I9		
SCA'S IN GRID	W005		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap, razor wire, aluminum cans

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E8I0		
SCA'S IN GRID	W005		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.20.2008

UXO QC Specialist Signature _____ Date 7.20.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7.21
GRID ID	B1H9B6		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Fh		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Nail

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1H9B9		
SCA'S IN GRID	W157		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1H9B0		
SCA'S IN GRID	W160, W161		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1H9A9		
SCA'S IN GRID	W157, W160		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7-21-08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1H9A6		
SCA'S IN GRID	W048, W128,		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7-21-08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9J9		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Screw

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-24-08
GRID ID	B1G9J8		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature _____ Date 7-24-08

UXO QC Specialist Signature _____ Date 7-21-08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G918		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Sc4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9J6		
SCA'S IN GRID	W128, W048		
INSTRUMENT(S) USED	Eq		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Mark	DATE	7-21-08
GRID ID	B1G915		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9H5		
SCA'S IN GRID	40048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7-21-08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Mark	DATE	7-21-08
GRID ID	B1G9G6		
SCA'S IN GRID	W043		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7-21-08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G965		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Iron Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9G4		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9F4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9E4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	BIG9E3		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	9-21-08
GRID ID	B1G9D3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	[illegible] Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [illegible] Date 9-21-08

UXO QC Specialist Signature [illegible] Don Kean Date 7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9C3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9B3		
SCA'S IN GRID	W127		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRM Date 7-21-08

UXO QC Specialist Signature Don Kean Date 7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(3) Nails

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1G9B2		
SCA'S IN GRID	W048, W127, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kream


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	BIG 9A 2		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(3) Barbed wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-24-08
GRID ID	B1F9J2		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-24-08

UXO QC Specialist Signature _____ Date 7/21/08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F9J1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Sc4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Klean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Bolts

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F9I1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Alt Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(3) Wire


(1) Nail

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F8H1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature Tony Clark Date 7-21-08

UXO QC Specialist Signature Don Freeman Date 7/21/08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F860		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F8F0		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F8 F9		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-21-08
GRID ID	B1F8E9		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	S4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature T. R. Clark Date 7-21-08

UXO QC Specialist Signature Don Kean Date 7/21/08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F8D9		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sc1		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Iron Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-21-08
GRID ID	B1F8C9		
SCA'S IN GRID	W048, W126		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F8C8		
SCA'S IN GRID	W048, W126		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Nil

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-21-08
GRID ID	B1F8B8		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-21-08
GRID ID	B1F8A8		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sc1		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRC Date 7-21-08

UXO QC Specialist Signature Don Kream Date 7.21.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R. Clark	DATE	7-21-08
GRID ID	B1F8A7		
SCA'S IN GRID	W041, W048, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-21-08
GRID ID	B1E8J9		
SCA'S IN GRID	W005		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Barbed Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-21-08
GRID ID	B1E8J8		
SCA'S IN GRID	W005		
INSTRUMENT(S) USED	SA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7-21-08

UXO QC Specialist Signature _____ Date 7.21.08

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Cobb	**DATE**	7.21
GRID ID	B1E8J7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature TRC Date 7.21

UXO QC Specialist Signature Don Frean Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Metal Scraps

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1 JOD6		
SCA'S IN GRID	W048, W140, W143		
INSTRUMENT(S) USED	schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE 7.21.2008
GRID ID	B1J0D5	
SCA'S IN GRID	W048, W140	
INSTRUMENT(S) USED	Schonstedt	

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1JOC6		
SCA'S IN GRID	W012, W013, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1J0C5		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08
Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1J0B5		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1J0B4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1J0A5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor WIRE

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1JO A4		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Aluminum cans, metal scrap, wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B110J5		
SCA'S IN GRID	W010		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Wire

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B110J4		
SCA'S IN GRID	W010, W048, W140,		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1 10J3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B11014		
SCA'S IN GRID	B11014 – W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B11013		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kearn

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire, Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110H4		
SCA'S IN GRID	W140, W129		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110H3		
SCA'S IN GRID	W048, W129, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION

Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110H2		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B11063		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Wire


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION

Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1106Z		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110F3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110F2		
SCA'S IN GRID	W007, W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110E2		
SCA'S IN GRID	W048, W080, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110E1		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110D2		
SCA'S IN GRID	W140, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110D1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION

Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110C2		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found.


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION

Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110C1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110B2		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kream

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110B1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature Jack Kristensen Date 7.21.2008

UXO QC Specialist Signature Don Krean Date 7.21.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110A2		
SCA'S IN GRID	W142		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B110A1		
SCA'S IN GRID	W006, W046, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Kraan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B119A0		
SCA'S IN GRID	W046, W048, W121, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H0J1		
SCA'S IN GRID	W045, W046		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H9J0		
SCA'S IN GRID	W046, W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H910		
SCA'S IN GRID	W048, W049		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H919		
SCA'S IN GRID	W140, WQ48		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9H0		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9H9		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H969		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08
Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Scrap metal, wire, aluminum

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H9G8		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7-21-2008
GRID ID	B1HOF1		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1F9H8		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7-21-08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H0E1		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap, aluminum cans

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9E0		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

a-/kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9E9		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Razor wire, wire, aluminum

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H9E8		
SCA'S IN GRID	W047, W048, W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9D0		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9D9		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	**DATE**	7.21.2008
GRID ID	B1H9D8		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor WIRE

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9D7		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ N

UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing Found

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristenson	DATE	7.21.2008
GRID ID	B1H9C0		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Nothing found.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9C9		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Krear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H4C8		
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7/21/08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1H9C7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7.21.2008

UXO QC Specialist Signature _____ Date 7.21.08

Dan Klein

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Metal Scrap

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.28
GRID ID	C2B6F6		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Nail

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6E6		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6F7		
SCA'S IN GRID	W120, W140		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Dan Kean Date 7/28/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-28-08
GRID ID	C2B6G7		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(2) UXO

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony S Clark	DATE	7-28-08
GRID ID	C2B6G8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Don Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony L Clark	**DATE**	7-28-08
GRID ID	C2B6F8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2 B6 E5		
SCA'S IN GRID	W119, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Krean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2 B6E5		
SCA'S IN GRID	W119, W140		
INSTRUMENT(S) USED	Sh		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Keen


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6D4		
SCA'S IN GRID	W118		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	[signature]	**DATE**	7-28-08
GRID ID	C2B6E4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ **N**

UXO Technician Inspector Signature [signature] Date 7-28-08

UXO QC Specialist Signature [signature] Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


Q/W.n

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2B6D3		
SCA'S IN GRID	W117, W118, W140		
INSTRUMENT(S) USED	Sh		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6C2		
SCA'S IN GRID	W117, W118		
INSTRUMENT(S) USED	Sc1		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Dan Keem


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6D2		
SCA'S IN GRID	W118, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7/28/08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6E3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Krean Date 7/28/08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6E2		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7/28/08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2B6C1		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sh		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Doug Krause


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B6D1		
SCA'S IN GRID	W118, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Don Keeran


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B5C0		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sh		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature Tony R Clark Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C 2B5D0		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sc4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRCk Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C 2B5 B9		
SCA'S IN GRID	W111		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



N

UXO Technician Inspector Signature TRCK Date 7-28-08


UXO QC Specialist Signature Don Keen Date 7.28.2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2B5C9		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑
N

UXO Technician Inspector Signature T R C Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7/28/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Razor wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2B508		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.2008

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B5C8		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sc4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B5B7		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kern


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B5A6		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Dan Krewson Date 7.28.08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2B5B6		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	**DATE**	7-28-08
GRID ID	GZBJA5		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TRCk Date 7-28-08

UXO QC Specialist Signature DJK Date 7.28.08
Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-28-08
GRID ID	C2B5B5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Dan Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-28-08
GRID ID	C2A5J4		
SCA'S IN GRID	W107		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-28-08
GRID ID	C2B5A4		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Krean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(1) Barbed wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-28-08
GRID ID	C2A5J3		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 7-28-08

UXO QC Specialist Signature _____ Date 7-28-08

Don Krein

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2B5A3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 7-28.08

UXO QC Specialist Signature _____ Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A5J2		
SCA'S IN GRID	W111, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**



UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Krean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Wire

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	DATE	7-28-08
GRID ID	C2A511		
SCA'S IN GRID	W087, W095, W096, W101, W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TRC Date 7-28-08

UXO QC Specialist Signature Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	7-28-08
GRID ID	C2A5J1		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature TRC Date 7-28-08


UXO QC Specialist Signature Don Krean Date 7-28-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R. Clark	**DATE**	25 JULY 08
GRID ID	DATA GAPS ALONG FENCELINE WITHIN ROADWAY ALIGNMENT W140 MRS-1		
SCA'S IN GRID			
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 25 JULY 08

UXO QC Specialist Signature _____ Date 25 July 08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Barbed wire 1146

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	25 July 08
GRID ID	~~DATA GAPS~~ Along Fenceline within Roadway Alignment W140 MRS-2		
SCA'S IN GRID			
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑ **N**

UXO Technician Inspector Signature _____ Date 25 July 08

UXO QC Specialist Signature _____ Date 7/25/08

Dan Krean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


(3) Wire clips 1Lh L

WESTON SOLUTIONS

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	25 July 08
GRID ID	~~DATA~~ GPOS Along Fenceline within Roadway Alignment W140 MRS-3		
SCA'S IN GRID			
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



↑ N

UXO Technician Inspector Signature TRC Date 25 July 08

UXO QC Specialist Signature Don Kearn Date 25 July 08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Barbed wire 1Lb L
(4) wire clips

QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony R Clark	**DATE**	25 July 08
GRID ID	~~DATA~~ Gaps Along Fenceline within Roadway Alignment W140 MRS-4		
SCA'S IN GRID			
INSTRUMENT(S) USED	Sc L		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____ Date 25 July 08

UXO QC Specialist Signature _____ Date 25 July 08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Wire clips 1Lb L