



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C 2 A 2 B 7</i>		
SCA'S IN GRID	<i>W140, W122</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*
Don Kean

Date *7.28.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2A2A6</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2A2B6</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap, aluminum, nails



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2 A2 B5</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*
Don Kean

Date *7.28.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C 24245		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature

Date 7.28.08

UXO QC Specialist Signature

Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2A2A4</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C 2 A 2 A 3</i>		
SCA'S IN GRID	<i>W 1 4 0</i>		
INSTRUMENT(S) USED	<i>Schensted</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____

Date *7.28.2008*

UXO QC Specialist Signature _____

Date *7.28.08*

[Handwritten signatures]
Dan Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2J2J4</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.2008*

Don Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J2J3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____

Date 7.28.2008

UXO QC Specialist Signature Dan Kean

Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B 2J 212</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Sehonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*

UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B25211</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J140		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature  Date 7.28.2008
UXO QC Specialist Signature  Date 7.28.2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J169		
SCA'S IN GRID	W059, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008

UXO QC Specialist Signature [Signature] Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing Found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2J1H9</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2 J168</i>		
SCA'S IN GRID	<i>w058, w140</i>		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, Metal Scrap, Aluminum Cans



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2J1F7		
SCA'S IN GRID	W014, W140		
INSTRUMENT(S) USED	Schmidt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7.28.2008

UXO QC Specialist Signature [Signature]

Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2 JIE6		
SCA'S IN GRID	w014, w057		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7.28.2008

UXO QC Specialist Signature [Signature]

Date 7.28.2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2 JIF6</i>		
SCA'S IN GRID	<i>W014, W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.2008*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7/28/2008
GRID ID	B2JIE5		
SCA'S IN GRID	W001, W036, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7.28.2008

UXO QC Specialist Signature [Signature]

Date 7.28.2008

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2J1F5</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Shorstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B231E4</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*

UXO QC Specialist Signature *[Signature]* Date *7-28-08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing Found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7/28/2008</i>
GRID ID	<i>B2J1C4</i>		
SCA'S IN GRID	<i>W055</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.08</i>
GRID ID	<i>B2J1C3</i>		
SCA'S IN GRID	<i>W055</i>		
INSTRUMENT(S) USED	<i>Schmidt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature _____

Date *7.28.08*

UXO QC Specialist Signature _____

Date *7.28.08*

[Handwritten signatures]
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B2 J1D3		
SCA'S IN GRID	W055, W048		
INSTRUMENT(S) USED	Schinstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature  Date 7.28.2008
UXO QC Specialist Signature  Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristenson</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2J1E3</i>		
SCA'S IN GRID	<i>w140, w048</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B2J1D2</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7/28/2008
GRID ID	B2J1E2		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7.28.2008

UXO QC Specialist Signature [Signature]

Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7/28/2008</i>
GRID ID	<i>B2J1 D1</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7/28/2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	BDJ1E1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.28.2008

UXO QC Specialist Signature [Signature] Date 7.28.08
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7/28/2008</i>
GRID ID	<i>B150D0</i>		
SCA'S IN GRID	<i>w140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7/28/2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7/28/2008
GRID ID B1J0E0
SCA'S IN GRID W140
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7/28/2008
UXO QC Specialist Signature [Signature] Date 7/28/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7/28/2008
GRID ID B1 J0D9
SCA'S IN GRID W015
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>B150E9</i>			
SCA'S IN GRID	<i>w000, w048, w140</i>			
INSTRUMENT(S) USED	<i>Schmidt</i>			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature	<i>[Signature]</i>	Date	<i>7.28.2008</i>
UXO QC Specialist Signature	<i>[Signature]</i> <i>Don Kean</i>	Date	<i>7-28-08</i>

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7/28/2008
GRID ID B1J0D8
SCA'S IN GRID W048
INSTRUMENT(S) USED Sehonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7/28/2008
GRID ID B1J0E8
SCA'S IN GRID w048, w140
INSTRUMENT(S) USED Sehongedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	B1J0D7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7/28/2008</i>
GRID ID	<i>BIJOE7</i>		
SCA'S IN GRID	<i>W048, W140</i>		
INSTRUMENT(S) USED	<i>Schwabedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature	<i>[Signature]</i>	Date	<i>7.28.2008</i>
UXO QC Specialist Signature	<i>[Signature]</i> <i>Don Kean</i>	Date	<i>7/28/08</i>

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.08</i>
GRID ID	<i>B1J0E6</i>		
SCA'S IN GRID	<i>W048, W140</i>		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature	<i>[Signature]</i>	Date	<i>7.28.2008</i>
UXO QC Specialist Signature	<i>[Signature]</i>	Date	<i>7.28.08</i>

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found