


Operable Unit 1 (OU1)



- Soil and groundwater contamination resulted from firefighter training during which flammable liquids were poured on the ground, ignited, and then extinguished.
- The 1995 Record of Decision confirmed that soil treatment was complete and identified ten chemicals of concern in groundwater. However, since 2006, trichloroethene, or TCE, is the only contaminant found in groundwater at OU1.
- Groundwater from all monitoring wells has remained below aquifer cleanup levels (ACLs) since September 2014. Groundwater cleanup completion now requires documentation. The map above shows the maximum extent of the groundwater contamination plume.
- The Army is preparing site close-out documentation. In the interim, attainment monitoring continues. The treatment system is on standby during attainment monitoring. The treatment system will be decommissioned once the site is closed.