



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 052008R1A
Location: 052008R1A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 052008R2A
Location: 052008R2A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 052708R1A
Location: 052708R1A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 060308R1A
Location: 060308R1A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 060908R1A
Location: 060908R1A
Operator: BG Date: 2008/07/28

— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded





Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 061608R1A
Location: 061608R1A
Operator: BG Date: 2008/07/28

— Repeated Profile
— Original Profile



▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 061908R1A
Location: 061908R1A
Operator: BG Date: 2008/07/28

— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded





Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062308R1A
Location: 062308R1A
Operator: BG Date: 2008/07/28

— Repeated Profile
— Original Profile



▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062508R1A
Location: 062508R1A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062508R2A
Location: 062508R2A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062508R3A
Location: 062508R3A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062508R3B
Location: 062508R3B
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062508R5A
Location: 062508R5A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062508R7A
Location: 062508R7A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 0626083RA
Location: 0626083RA
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062608R1A
Location: 062608R1A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062608R3A
Location: 062608R3A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062608R4A
Location: 062608R4A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 062608R6A
Location: 062608R6A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 0627086RA
Location: 0627086RA
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070708R1A
Location: 070708R1A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070808R1A
Location: 070808R1A
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070808R2A
Location: 070808R2A
Operator: BG Date: 2008/07/28



— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070808R3A
Location: 070808R3A
Operator: BG Date: 2008/07/28

— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded





Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070808R4A
Location: 070808R4A
Operator: BG Date: 2008/07/28

— Repeated Profile
— Original Profile



▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070908R1A
Location: 070908R1A
Operator: BG Date: 2008/07/28

— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded





Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070908R2A
Location: 070908R2A
Operator: BG Date: 2008/07/28

— Repeated Profile
— Original Profile

▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded





Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 070908R3A
Location: 070908R3A
Operator: BG Date: 2008/07/28

— Repeated Profile
— Original Profile



▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 071108R3B
Location: 071108R3B
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 071108R5B
Location: 071108R5B
Operator: BG Date: 2008/07/28



— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 071208R1B
Location: 071208R1B
Operator: BG Date: 2008/07/28

— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded





Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 071508R1A
Location: 071508R1A
Operator: BG Date: 2008/07/28

Repeated Profile
Original Profile







Lateral tolerance exceeded
Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 2008/06/04
Location:
Operator: BG Date: 2008/06/04







— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 2008/06/05
Location:
Operator: BG Date: 2008/06/05







— Repeated Profile
— Original Profile
▲ Lateral tolerance exceeded
▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort ord
 Instrument: EM-61 Mark II
 Tolerance (% Amplitude) :20.00
 Grid name: 2008/07/03
 Location:
 Operator: BG Date: 2008/07/03







— Repeated Profile ▲ Lateral tolerance exceeded
 — Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 2008/07/07
Location:
Operator: BG Date: 2008/07/07







— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 2008/07/08
Location:
Operator: BG Date: 2008/07/30







— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 2008/07/10
Location:
Operator: BG Date: 2008/07/10

— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded



Repeatability Test

Project: Fort Ord
Instrument: EM-61 Mark II
Tolerance (% Amplitude) :20.00
Grid name: 2008/07/11
Location:
Operator: BG Date: 2008/07/11

— Repeated Profile ▲ Lateral tolerance exceeded
— Original Profile ▲ Amplitude tolerance exceeded

