



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1D8A2		
SCA'S IN GRID	E0048		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(3) Wire
(1) Small metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1D8A1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	SLL		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20
UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1D7A0		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20
UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1D7A9		
SCA'S IN GRID	W140, W00		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(4) Barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1C8J1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.8

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7-20
GRID ID	B1C7J0		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature JRC Date 7-20

UXO QC Specialist Signature D. Kean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Iron scrap
(1) Asphalt



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1C7J9		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) wires



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7-20
GRID ID	B1C7J8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. Clark

Date 7-20

UXO QC Specialist Signature Don Kean

Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

--



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC7 I O		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Clark* Date 7.20

UXO QC Specialist Signature *Don Kean* Date 7/20/08

List any findings. GPS locations of MLC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C7I9		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	gch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC718		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature JRC Date 7.20

UXO QC Specialist Signature DK Date 7/20/08
Donkhan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) wire

(2) Barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC 7 H 0		
SCA'S IN GRID	W 0 4 8		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/06

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC7H9		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-20

UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Frag SCRAP



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C7H8		
SCA'S IN GRID	W003, W140		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Flaw Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC7H7		
SCA'S IN GRID	W003, W140		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature Date 7.20

UXO QC Specialist Signature Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC769		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCN		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC768		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. Clark Date 7.20

UXO QC Specialist Signature Don Kean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C767		
SCA'S IN GRID	W140, W165		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08
Donkhan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	J. Clark	DATE	7.20
GRID ID	B1C7F9		
SCA'S IN GRID	W018		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date _____
Donkhan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) wire
(2) metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. L Lank	DATE	7.20
GRID ID	B1C7F8		
SCA'S IN GRID	W018, W048, W164		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(5) Metal scraps
 (2) Asphalt



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7-20
GRID ID	B1C7F7		
SCA'S IN GRID	W048, W165		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-20

UXO QC Specialist Signature [Signature] Date 7/20/08
Donkhan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C7F6		
SCA'S IN GRID	W140, W165		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
 Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>T. Llanck</i>	DATE	<i>7.20</i>
GRID ID	<i>BIC7E9</i>		
SCA'S IN GRID	<i>W135</i>		
INSTRUMENT(S) USED	<i>scu</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Llanck* Date *7.20*

UXO QC Specialist Signature *Don Kean* Date *7/20/08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	BIC7E8		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08
Don/Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	BIC 7E7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7.20

UXO QC Specialist Signature *[Signature]* Date 7/20/08
Donkhan

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1C7E6		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7.20

UXO QC Specialist Signature *[Signature]* Date 7/20/08
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B127D5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	SLN		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TRA Date 7.20

UXO QC Specialist Signature Doukhan Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C7D6		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature T. Clark Date 7.20
UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clank	DATE	7.20
GRID ID	B1C7D7		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TRA Date 7.20

UXO QC Specialist Signature Don Kean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C7C6		
SCA'S IN GRID	W040, W163		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7.20

UXO QC Specialist Signature *[Signature]* Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MB. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	J. CLARK	DATE	7.20
GRID ID	B1C7C5		
SCA'S IN GRID	W048, W137, W140		
INSTRUMENT(S) USED	SLA		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1L7B8		
SCA'S IN GRID	4037		
INSTRUMENT(S) USED	SC4		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. LLANK	DATE	7.20
GRID ID	BIC 7B7		
SCA'S IN GRID	W037		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Llanck* Date 7.20

UXO QC Specialist Signature *Don Kean* Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7-20
GRID ID	B1C7B6		
SCA'S IN GRID	W037, W048, W163		
INSTRUMENT(S) USED	SLH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7-20

UXO QC Specialist Signature *[Signature]* Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Short cable



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>T. CLARK</i>	DATE	<i>7.20</i>
GRID ID	<i>B1C7B5</i>		
SCA'S IN GRID	<i>W048, W163</i>		
INSTRUMENT(S) USED	<i>SLH.</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20*

UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don/bean

List any findings. GPS locations of MEC/MØ. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1C7A5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7/20/08
Don/Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. LIANE	DATE	7.20
GRID ID	B1C7A4		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. Liane Date 7.20

UXO QC Specialist Signature Don Kean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
1) wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1B7J5		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	SCN		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7.20

UXO QC Specialist Signature *[Signature]* Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>T. Clark</i>	DATE	<i>7.20</i>
GRID ID	<i>B1B7J4</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>sch.</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20*

UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don/Keane

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>T. CLARK</i>	DATE	<i>7.20</i>
GRID ID	<i>B1B7I5</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>SAH.</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Clark* Date *7.20*

UXO QC Specialist Signature *Don Kean* Date *7.20.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(3) Barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.30
GRID ID	B1B7I4		
SCA'S IN GRID	W035, W048		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7.20

UXO QC Specialist Signature *[Signature]* Date 7.20.08
Don't hear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) 1220 wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. L Lank	DATE	7.20
GRID ID	B1B7I3		
SCA'S IN GRID	W035, W140		
INSTRUMENT(S) USED	SCH		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. L Lank Date 7.20

UXO QC Specialist Signature Don Hean Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Iron scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1B7H4		
SCA'S IN GRID	W035, W048, W130		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Clark* Date 7.20

UXO QC Specialist Signature *Don Kean* Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

2/Bolts



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1B7H3		
SCA'S IN GRID	W035, W048, W140		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Clark* Date 7.20
UXO QC Specialist Signature *Don Hean* Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>T. Llanik</i>	DATE	<i>7.20</i>
GRID ID	<i>B1B765</i>		
SCA'S IN GRID	<i>W034, W130</i>		
INSTRUMENT(S) USED	<i>SC4</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20*

UXO QC Specialist Signature *[Signature]* Date *7.2.08*
Don't mean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1B764		
SCA'S IN GRID	W130		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MO. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1B763		
SCA'S IN GRID	W048, W153		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. Clark Date 7.20

UXO QC Specialist Signature Don Keenan Date 7.20.08

List any findings. GPS locations of MEC/MID. Add additional pages if needed.
(2) wires



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B187F5		
SCA'S IN GRID	W130		
INSTRUMENT(S) USED	SL4.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1B7F3		
SCA'S IN GRID	W048, W153		
INSTRUMENT(S) USED	SCH.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. Clark Date 7.20

UXO QC Specialist Signature Danbean Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(4) Nails



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Llanik	DATE	7.20
GRID ID	B1B7E5		
SCA'S IN GRID	W151		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08
Doy Kean

List any findings. GPS locations of MECMD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Llanck	DATE	7.20
GRID ID	B187C1		
SCA'S IN GRID	W048, W124		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7.20

UXO QC Specialist Signature *[Signature]* Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B1B7B1		
SCA'S IN GRID	W124, W141		
INSTRUMENT(S) USED	Sch		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature JRA Date 7.20

UXO QC Specialist Signature Don Kean Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7.20
GRID ID	B1B6A0		
SCA'S IN GRID	W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
 Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7.20</i>
GRID ID	<i>B1A6J0</i>		
SCA'S IN GRID	<i>W029 , W141</i>		
INSTRUMENT(S) USED	<i>Sch.</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20*
 UXO QC Specialist Signature *[Signature]* Date *7.20.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Clark	DATE	7.20
GRID ID	B1A6I9		
SCA'S IN GRID	W004, W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T. Clark Date 7.20

UXO QC Specialist Signature Don Kean Date 7.20.08

List any findings. GPS locations of MBC/MD. Add additional pages if needed.

(2) Aluminum Cans



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>T. Link</i>	DATE	<i>7.20</i>
GRID ID	<i>B1A6H9</i>		
SCA'S IN GRID	<i>W141</i>		
INSTRUMENT(S) USED	<i>Sch.</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20*

UXO QC Specialist Signature *[Signature]* Date *7.20.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. Chark	DATE	7.20
GRID ID	B1A6H8		
SCA'S IN GRID	W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *T. Chark* Date 7.20

UXO QC Specialist Signature *Don Keen* Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Nails



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	T. CLARK	DATE	7.20
GRID ID	B11668		
SCA'S IN GRID	SCA'S W123, W140, W141		
INSTRUMENT(S) USED	Sch.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20

UXO QC Specialist Signature [Signature] Date 7.20.08
[Signature]

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Tony Clark	DATE	7-20
GRID ID	B1A7F1		
SCA'S IN GRID	W030		
INSTRUMENT(S) USED	Schonstedt.		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7.20

UXO QC Specialist Signature [Signature]
Don Kean

Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-20</i>
GRID ID	<i>B1A6F8</i>		
SCA'S IN GRID	<i>W123, W141</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20*

UXO QC Specialist Signature *[Signature]* Date *7-20-08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

- (1) Barbed wire*
- (2) Nails*