



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	JACK KRISTENSEN	DATE	7.20.08
GRID ID	BID 7B9		
SCA'S IN GRID	WOW		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.08
UXO QC Specialist Signature [Signature] Date 7.20.08
Don't know

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor WIRE & WIRE





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.08
GRID ID	B1D7B0		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature  Date 7.20.2008
UXO QC Specialist Signature  Date 7.20.08
Don Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8B1		
SCA'S IN GRID	now, w140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08
Doyle Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8B2		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8B3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Don't mean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B107C0		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Bob Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8C1		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Sehonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature Date 7.20.2008
UXO QC Specialist Signature Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8C2		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B108c3		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08
[Signature: Boykeman]

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B107D0		
SCA'S IN GRID	60W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire, barbed wire, metal scrap, nails



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8D1		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Don't bear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap, brass casings, aluminum, nails





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8D2		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature  Date 7.20.2008
UXO QC Specialist Signature  Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap, WIRE



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8D3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8D4		
SCA'S IN GRID	W040		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08
[Signature: Dan Kean]

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D7E0		
SCA'S IN GRID	Wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Bean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B108E1		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Day Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Rebar, nails, wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B108E2		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap, nails, wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8E3		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8E4		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7.20.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8F1		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008

UXO QC Specialist Signature [Signature] Date 7.20.2008
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8F2		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature

Date 7.20.2008

UXO QC Specialist Signature

Date 7.20.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B108F3		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7.20.2008

UXO QC Specialist Signature [Signature]

Date 7/20/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap.





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B10862		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature  Date 7.20.2008
UXO QC Specialist Signature  Date 7/20/08
Don Kean

List any findings. GPS locations of MFC/MD. Add additional pages if needed.
Razor wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B10863		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7/20/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B10864		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7.20.2008

UXO QC Specialist Signature [Signature]
Don Keane

Date 7/20/8

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D865		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008
 UXO QC Specialist Signature [Signature] Date 7/20/08
 Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
 Razor wire, metal scrap, barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8H2		
SCA'S IN GRID	wow		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7/20/08
Don Kean

List any findings. GPS locations of MECMD. Add additional pages if needed.
Razor wire, Aluminum, barbed wire.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8H3		
SCA'S IN GRID	W140, W02		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature

Date 7.20.2008

UXO QC Specialist Signature

Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8H4		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature

Date 7.20.2008

UXO QC Specialist Signature

Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	BID 845		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7/20/08
DON KEAN

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1D8I2</i>		
SCA'S IN GRID	<i>wow</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*

UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap, razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1D8I3</i>		
SCA'S IN GRID	<i>wow</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature

Date

7.20.2008

UXO QC Specialist Signature

Don Kean

Date

7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8I4		
SCA'S IN GRID	w039, w048, w140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008
 UXO QC Specialist Signature [Signature] Date 7/20/08
 Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
 Razor wire, rebar



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1D8I5</i>		
SCA'S IN GRID	<i>W048, W134</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature

Date

7.20.2008

UXO QC Specialist Signature

Date

7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Fence material, razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B108J2</i>		
SCA'S IN GRID	<i>wow</i>		
INSTRUMENT(S) USED	<i>Schongstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire, wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1D8J3		
SCA'S IN GRID	W140, W0W		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.20.2008
UXO QC Specialist Signature [Signature] Date 7/20/08
Don/Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1D854</i>		
SCA'S IN GRID	<i>w039, w048, w140, w162</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *AK* Date *7.20.2008*
 UXO QC Specialist Signature *DK* Date *7/20/08*
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap, household garbage.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B108J5</i>		
SCA'S IN GRID	<i>w048, w134</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
 UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Keane

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>BIEBA3</i>		
SCA'S IN GRID	<i>w140, w162, w0w</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>BIE8A4</i>			
SCA'S IN GRID	<i>w048, w140, w162</i>			
INSTRUMENT(S) USED		<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
 UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8B3</i>		
SCA'S IN GRID	<i>w140, w162</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8B4</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Schunstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature

Date *7.20.2008*

UXO QC Specialist Signature

Don Kean

Date *7/20/08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8C4</i>			
SCA'S IN GRID	<i>W048 W140</i>			
INSTRUMENT(S) USED		<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]*

Date *7.20.2008*

UXO QC Specialist Signature *[Signature]*

Date *7/20/08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.20.2008
GRID ID	B1E805		
SCA'S IN GRID	W048, W125		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7.20.2008

UXO QC Specialist Signature [Signature]

Date 7/20/08

Doyle Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap




QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Jack Kristensen</u>	DATE	<u>7.20.2008</u>
GRID ID	<u>B1E8E5</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED	<u>Schonstedt</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature 

Date 7.20.2008

UXO QC Specialist Signature 
Dan Kean

Date 7/20/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8F5</i>			
SCA'S IN GRID	<i>w048, w140</i>			
INSTRUMENT(S) USED		<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*

UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8F6</i>			
SCA'S IN GRID	<i>W133, W140</i>			
INSTRUMENT(S) USED		<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8G6</i>		
SCA'S IN GRID	<i>4048</i>		
INSTRUMENT(S) USED	<i>Schonsedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7/20/08*
Don Keane

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8H6</i>		
SCA'S IN GRID	<i>W048, W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*

UXO QC Specialist Signature *[Signature]* Date *7.20.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire, metal scrap, Aluminum cans



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E817</i>		
SCA'S IN GRID	<i>W005, W048</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7.20.08*
Don Kean

List any findings. GPS locations of MECMD. Add additional pages if needed.
Metal scrap, razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E818</i>		
SCA'S IN GRID	<i>4005</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7.20.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E8I9</i>		
SCA'S IN GRID	<i>6005</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]*

Date *7.20.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.20.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap, razor wire, aluminum cans



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.20.2008</i>
GRID ID	<i>B1E810</i>		
SCA'S IN GRID	<i>4005</i>		
INSTRUMENT(S) USED	<i>Schonstadt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7.20.2008*
UXO QC Specialist Signature *[Signature]* Date *7.20.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire, metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	TONY CLARK	DATE	7.21
GRID ID	B1H9B6		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	SL		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21
UXO QC Specialist Signature [Signature] Date 7-21-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) None



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1H9B9</i>		
SCA'S IN GRID	<i>W157</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *Tony Clark* Date *7-21-08*

UXO QC Specialist Signature *Don Vean* Date *7-21-08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1H9B0</i>		
SCA'S IN GRID	<i>W160, W161</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *JRC*

Date *7-21-08*

UXO QC Specialist Signature *Don Kean*

Date *7/21/08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1H9A9</u>		
SCA'S IN GRID	<u>W157, W160</u>		
INSTRUMENT(S) USED	<u>SEA</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7-21-08

UXO QC Specialist Signature [Signature]
Don Kean

Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1H9A6</u>		
SCA'S IN GRID	<u>W048, W128,</u>		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7-21-08
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B16959</u>		
SCA'S IN GRID	<u>W160</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature JRC Date 7-21-08

UXO QC Specialist Signature Don Hean Date 7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) Screw



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1G9J8</u>		
SCA'S IN GRID	<u>W160</u>		
INSTRUMENT(S) USED	<u>Set</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7-21-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.