



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B16918</i>		
SCA'S IN GRID	<i>W160</i>		
INSTRUMENT(S) USED	<i>Sc4</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *Tony Clark*

Date *7-21-08*

UXO QC Specialist Signature *Don Kean*

Date *7-21-08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1G9J6</i>		
SCA'S IN GRID	<i>W128, W048</i>		
INSTRUMENT(S) USED	<i>EG</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7-21-08*
UXO QC Specialist Signature *[Signature]* Date *7-21-08*
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) None



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B16915</i>		
SCA'S IN GRID	<i>w048, w140</i>		
INSTRUMENT(S) USED	<i>Scn</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7-21-08*

UXO QC Specialist Signature *[Signature]*
Donkhan

Date *7-21-08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1G9H5</i>		
SCA'S IN GRID	<i>6048</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7-21-08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Mark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B16966</i>		
SCA'S IN GRID	<i>W043</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7-21-08*
UXO QC Specialist Signature *[Signature]* Date *7-21-08*
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>BIG965</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7-21-08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) Iron Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B16964</u>		
SCA'S IN GRID	<u>W048, W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature Tony Clark Date 7-21-08
UXO QC Specialist Signature Don Kean Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B169F4</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7/21/08
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B169E4</i>			
SCA'S IN GRID	<i>W048</i>			
INSTRUMENT(S) USED	<i>Sch</i>			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7/21/08*
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Nails



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>BIG 9 E3</i>		
SCA'S IN GRID	<i>W048, W140</i>		
INSTRUMENT(S) USED	<i>Sc4</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7/21/08*
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1G9D3</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>TRR Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *TRR* Date *7-21-08*

UXO QC Specialist Signature *DK* Date *7/21/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1G9C3</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED	<u>Seh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7-21-08

UXO QC Specialist Signature [Signature]

Date 7/21/08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1G9B3</u>		
SCA'S IN GRID	<u>W127</u>		
INSTRUMENT(S) USED	<u>Soh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TJR Date 7-21-08

UXO QC Specialist Signature DK Date 7/21/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(3) Nails



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B16982</u>		
SCA'S IN GRID	<u>w048, w127, w140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7.21.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Randy Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>BIG 9A 2</i>			
SCA'S IN GRID	<i>W04B</i>			
INSTRUMENT(S) USED		<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7/21/08*
Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(3) Barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1F9J2</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *JRC* Date *7-21-08*
UXO QC Specialist Signature *[Signature]* Date *7/21/08*
Don't mean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F9J1</u>		
SCA'S IN GRID	<u>W048, W140</u>		
INSTRUMENT(S) USED	<u>Scn</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7/21/08
Don Hearn

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Boats



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F9I1</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7-21-08

UXO QC Specialist Signature *[Signature]* Date 7-21-08
#1 Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(3) Wire
(1) Nail



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8H1</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME		<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>BIF860</i>			
SCA'S IN GRID	<i>W048</i>			
INSTRUMENT(S) USED		<i>Seh</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7/21/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8F0</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED	<u>Sei</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08
UXO QC Specialist Signature [Signature] Date 7/21/08
Don Kean

List any findings. GPS locations of MEC/MB. Add additional pages if needed.
(1) Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8 F9</u>		
SCA'S IN GRID	<u>W048, W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7/21/08
Don/bean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8E9</u>		
SCA'S IN GRID	<u>w048, w140</u>		
INSTRUMENT(S) USED	<u>EH</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature T.R. Clark Date 7-21-08

UXO QC Specialist Signature Don Kean Date 7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8D9</u>		
SCA'S IN GRID	<u>W048</u>		
INSTRUMENT(S) USED	<u>Ek</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *JRC*

Date 7-21-08

UXO QC Specialist Signature *Don Kean*

Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Iron Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8C9</u>		
SCA'S IN GRID	<u>w048, w126</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7/21/08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1F8C8</i>		
SCA'S IN GRID	<i>W048, W126</i>		
INSTRUMENT(S) USED	<i>Scr</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date *7-21-08*

UXO QC Specialist Signature *[Signature]* Date *7/21/08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(1) Nail



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1F8B8</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *JRC* Date *7-21-08*

UXO QC Specialist Signature *DK* Date *7/21/08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>BIF8A8</u>		
SCA'S IN GRID	<u>w048</u>		
INSTRUMENT(S) USED	<u>Sh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature TRC Date 7-21-08

UXO QC Specialist Signature Don Kean Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R. Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>B1F8A7</u>		
SCA'S IN GRID	<u>w041, w048, w140</u>		
INSTRUMENT(S) USED	<u>Soil</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7-21-08

UXO QC Specialist Signature [Signature] Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>7-21-08</i>
GRID ID	<i>B1E8J9</i>		
SCA'S IN GRID	<i>W005</i>		
INSTRUMENT(S) USED	<i>Seh</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *Tony R Clark*

Date *7-21-08*

UXO QC Specialist Signature *Doug Keenan*

Date *7-21-08*

List any findings. GPS locations of MEC/MID. Add additional pages if needed.

(2) Barbed Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-21-08</u>
GRID ID	<u>BIE8J8</u>		
SCA'S IN GRID	<u>W005</u>		
INSTRUMENT(S) USED	<u>EA</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature Tony R Clark Date 7-21-08

UXO QC Specialist Signature Don Kean Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Chid</i>	DATE	<i>7.21</i>
GRID ID	<i>B1E8J7</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED			

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *T.R.C.* Date *7.21*
UXO QC Specialist Signature *DK* Date *7-21-08*
Donkern

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(1) Metal Scraps



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME JACK KRISTENSEN DATE 7.21.2008
GRID ID B1 J0D6
SCA'S IN GRID W048, W140, W143
INSTRUMENT(S) USED schenstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MECMD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME

Jack Kristensen

DATE

7.20.2008

GRID ID

B1J0D5


SCA'S IN GRID

W048, W140

INSTRUMENT(S) USED

Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature

[Signature]

Date

7.20.2008

UXO QC Specialist Signature

[Signature]
Don Keen

Date

7.21.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B1J0C6</i>		
SCA'S IN GRID	<i>w012, w013, w048</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.21.2008*
UXO QC Specialist Signature *[Signature]* Date *7.21.08*
Dmy Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B1J0C5		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date 7.21.2008
UXO QC Specialist Signature *[Signature]* Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B15 0B5		
SCA'S IN GRID	w048, w140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature		Date	7.21.2008
UXO QC Specialist Signature		Date	7/21/08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008

GRID ID B150B4

SCA'S IN GRID W140

INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008

UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008

GRID ID B1J0A5

SCA'S IN GRID W048

INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008

UXO QC Specialist Signature [Signature] Date 7.21.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008
GRID ID B150 A4
SCA'S IN GRID w048, w140
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Aluminum cans, metal scrap, wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B110J5</i>		
SCA'S IN GRID	<i>W010</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.21.2008*
UXO QC Specialist Signature *[Signature]* Date *7.21.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
None



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B110J4</i>		
SCA'S IN GRID	<i>w010, w048, w140,</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.21.2008*
UXO QC Specialist Signature *[Signature]* Date *7.21.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B1 10J3</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]*

Date *7.21.2008*

UXO QC Specialist Signature *[Signature]*
Don Kean

Date *7.21.08*


List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B11014</i>		
SCA'S IN GRID	<i>B11014 - W048, W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.21.2008*
UXO QC Specialist Signature *[Signature]* Date *7.21.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008
GRID ID B11013
SCA'S IN GRID w048, w140
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Wire, Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110H4		
SCA'S IN GRID	W140, W129		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7-21-2008

GRID ID B110H3

SCA'S IN GRID W048, W129, W140

INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-21-2008

UXO QC Specialist Signature [Signature] Date 7-21-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008
GRID ID B110H2
SCA'S IN GRID W140
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008
GRID ID B11063
SCA'S IN GRID W048, W140
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B11062		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature		Date	7.21.2008
UXO QC Specialist Signature		Date	7.21.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008
GRID ID B110F3
SCA'S IN GRID W048
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B110F2</i>		
SCA'S IN GRID	<i>W007, W048, W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature <i>[Signature]</i>	Date <i>7.21.2008</i>
UXO QC Specialist Signature <i>[Signature]</i> <i>Don Kean</i>	Date <i>7.21.08</i>

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B110E2</i>		
SCA'S IN GRID	<i>w048, w080, w140</i>		
INSTRUMENT(S) USED	<i>Schongstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature	<i>[Signature]</i>	Date	<i>7.21.2008</i>
UXO QC Specialist Signature	<i>[Signature]</i> <i>Don Kean</i>	Date	<i>7.21.08</i>

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110E1		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110D2		
SCA'S IN GRID	W140, W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110D1		
SCA'S IN GRID	W048		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Den Kear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.21.2008</i>
GRID ID	<i>B110C2</i>		
SCA'S IN GRID	<i>W048</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.21.2008*
UXO QC Specialist Signature *[Signature]* Date *7.21.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110C1		
SCA'S IN GRID	W048, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME Jack Kristensen DATE 7.21.2008
GRID ID B110BZ
SCA'S IN GRID W048
INSTRUMENT(S) USED Schonstedt

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.21.2008
UXO QC Specialist Signature [Signature] Date 7.21.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.21.2008
GRID ID	B110B1		
SCA'S IN GRID	w048, w140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature Jack Kristensen Date 7.21.2008
UXO QC Specialist Signature Don Kean Date 7.21.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap