



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A410</u>		
SCA'S IN GRID	<u>W087, W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



N

UXO Technician Inspector Signature [Signature] Date 7-28-08

UXO QC Specialist Signature [Signature] Date 7-28-08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

--



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>C2A4J0</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Seh</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *T R Clark* Date *7-28-08*
UXO QC Specialist Signature *[Signature]* Date *7-28-08*
Don't hear

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4H9</u>		
SCA'S IN GRID	<u>W087</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08
UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C 2 A 4 1 9</u>		
SCA'S IN GRID	<u>W087, W140</u>		
INSTRUMENT(S) USED	<u>Sc4</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7-28-08

UXO QC Specialist Signature [Signature]

Date 7-28-08

Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R. Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A418</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7-28-08

UXO QC Specialist Signature [Signature]

Date 7-28-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

--



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R. Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>C2A4H8</i>		
SCA'S IN GRID	<i>w087, w140</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7-28-08*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>CZ A4G7</i>		
SCA'S IN GRID	<i>W074</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *TRC*

Date *7-28-08*

UXO QC Specialist Signature *DK*

Date *7-28-08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

(2) Barbed wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Ray P Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4H7</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>SCM</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08

UXO QC Specialist Signature [Signature] Date 7-28-08
Don Hean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>C2A466</i>		
SCA'S IN GRID	<i>W074, W140</i>		
INSTRUMENT(S) USED	<i>Sc 4</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7-28-08*

UXO QC Specialist Signature *[Signature]* Date *7-28-08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4H6</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08

UXO QC Specialist Signature [Signature] Date 7-28-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A465</u>		
SCA'S IN GRID	<u>W074, W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08
UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4G4</u>		
SCA'S IN GRID	<u>W074, W140</u>		
INSTRUMENT(S) USED	<u>Seh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08

UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
(2) wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4F3</u>		
SCA'S IN GRID	<u>W074</u>		
INSTRUMENT(S) USED	<u>Sc 6</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08
UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2 A4G3</u>		
SCA'S IN GRID	<u>W074, W140</u>		
INSTRUMENT(S) USED	<u>Seh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08

UXO QC Specialist Signature [Signature] Date 7-28-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>C2A4F2</i>		
SCA'S IN GRID	<i>W074, W140</i>		
INSTRUMENT(S) USED	<i>Sei</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *T.R. Clark*

Date *7-28-08*

UXO QC Specialist Signature *Don Kean*

Date *7.28.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4G2</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>Seh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08
UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A4F1</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7-28-08

UXO QC Specialist Signature [Signature]

Date 7-28-08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

--



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Ray R Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A3F0</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>Sh</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7-28-08
UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R. Clark</u>	DATE	<u>7-28-08</u>
GRID ID	<u>C2A3F9</u>		
SCA'S IN GRID	<u>W140</u>		
INSTRUMENT(S) USED	<u>Sc 4</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]* Date 7-28-08
UXO QC Specialist Signature *[Signature]* Date 7-28-08
Dox Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>C2A3E8</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *T.R.C.* Date *7-28-08*
 UXO QC Specialist Signature *D. Kean* Date *7-28-08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>7-28-08</i>
GRID ID	<i>C2A3F8</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *Tony R Clark* Date *7-28-08*
UXO QC Specialist Signature *Don Kean* Date *7-28-08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
QJWm



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	JACK KRISTENSEN	DATE	7.28.08
GRID ID	C2A3E7		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonsteel		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7.28.08

UXO QC Specialist Signature [Signature]

Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.08
GRID ID	C2A3E6		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date 7.28.08

UXO QC Specialist Signature *[Signature]*

Date 7.28.08

Dr. Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.08
GRID ID	C2A3D5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature  Date 7.28.08
UXO QC Specialist Signature  Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3E5		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7-28-08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C24304		
SCA'S IN GRID	W067, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 7.28.2008

UXO QC Specialist Signature [Signature]

Date 7-28-08

Don Keen

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal scrap





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3E4		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature  Date 7.28.2008
UXO QC Specialist Signature 
Don Kean Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C 2 A 3 D 3</i>		
SCA'S IN GRID	<i>w140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Razor Wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A3C2		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date 7.28.2008
UXO QC Specialist Signature *[Signature]* Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C 29302		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 7.28.2008

UXO QC Specialist Signature [Signature]
Don Kean

Date 7.28.08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Nothing Found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C293C1		
SCA'S IN GRID	W131, W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7.28.08
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2 A3D1</i>		
SCA'S IN GRID	<i>W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.28.2008*
UXO QC Specialist Signature *[Signature]* Date *7.28.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Razor wire



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2A2B0</i>		
SCA'S IN GRID	<i>W131</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*

Date *7.28.08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.28.2008</i>
GRID ID	<i>C2A2C0</i>		
SCA'S IN GRID	<i>W131, W140</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.28.2008*

UXO QC Specialist Signature *[Signature]*
Don Kean

Date *7.28.2008*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B9		
SCA'S IN GRID	W131		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
 UXO QC Specialist Signature [Signature] Date 7.28.2008
 Dan Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
 Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2C9		
SCA'S IN GRID	W131, W140		
INSTRUMENT(S) USED	Schenstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date 7.28.2008

UXO QC Specialist Signature *[Signature]*

Date 7.28.08

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap




QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA


UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C 2 A 2 C 8		
SCA'S IN GRID	W 1 4 0,		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature 

Date 7.28.2008

UXO QC Specialist Signature 
Don Kean

Date 7.28.2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Jack Kristensen	DATE	7.28.2008
GRID ID	C2A2B8		
SCA'S IN GRID	W140		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature] Date 7.28.2008
UXO QC Specialist Signature [Signature] Date 7.28.2008
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Nothing found