



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Matt Larcher</i>	DATE	<i>16 June 08</i>
GRID ID			
SCA'S IN GRID	<i>W160</i>		
INSTRUMENT(S) USED	<i>Schoustedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *16 June 08*

UXO QC Specialist Signature *[Signature]*

Date *16 June 08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean	DATE	16 June 2008
GRID ID			
SCA'S IN GRID	W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature

Date 16 June 08

UXO QC Specialist Signature

Date 16 June 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	MATT LAUCHNER	DATE	16 June 08
GRID ID			
SCA'S IN GRID	W110		
INSTRUMENT(S) USED	schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature  Date 16 June 08
UXO QC Specialist Signature  Date 16 June 08


List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean	DATE	16 June 2008
GRID ID			
SCA'S IN GRID	W110		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____

Date 16 JUNE 08

UXO QC Specialist Signature Don Kean

Date 16 June 2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Matt Lawcher	DATE	20 June 08
GRID ID			
SCA'S IN GRID	W015		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date 20 June 08

UXO QC Specialist Signature *[Signature]*
Don Kean

Date 20 June 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Don Kean</i>	DATE	<i>20 June 2008</i>
GRID ID			
SCA'S IN GRID	W015		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____

Date *20 June 08*

UXO QC Specialist Signature *Don Kean*

Date *20 June 08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>MATT LAUCHER</i>	DATE	<i>16 JUNE 08</i>
GRID ID			
SCA'S IN GRID	<i>W145</i>		
INSTRUMENT(S) USED	<i>schnostedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *16 JUNE 08*

UXO QC Specialist Signature *[Signature]*

Date *16 JUNE 08*

Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

--



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean	DATE	16 June 2008
GRID ID			
SCA'S IN GRID	W145		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 16 June 08

UXO QC Specialist Signature Don Kean UXOQCS

Date 16 June 2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Matt Lauchner	DATE	16 June 08
GRID ID			
SCA'S IN GRID	W158		
INSTRUMENT(S) USED	Schonsted		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 16 June 08

UXO QC Specialist Signature [Signature]

Date 16 June 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

[Empty box for findings and GPS locations]



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean LXOQCS	DATE	16 June 2008
GRID ID			
SCA'S IN GRID	W158		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature _____

Date 16 June 08

UXO QC Specialist Signature Don Kean

Date 16 June 2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Matt Lavelle</u>	DATE	<u>27 May 08</u>
GRID ID			
SCA'S IN GRID	<u>W159</u>		
INSTRUMENT(S) USED	<u>Schnoustedt</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature [Signature]

Date 27 May 08

UXO QC Specialist Signature [Signature]

Date 27 May 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.


--



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean UXO QCS	DATE	27 May 08
GRID ID			
SCA'S IN GRID	W159, W160		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 27 May 08

UXO QC Specialist Signature [Signature: Don Kean]

Date 27 May 2008

List any findings. GPS locations of MECMD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Matt Luehner</i>	DATE	<i>20 June 08</i>
GRID ID			
SCA'S IN GRID	<i>W018</i>		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *20 June 08*

UXO QC Specialist Signature *[Signature]*

Date *20 June 08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean UXOQCS	DATE	20 June 2008
GRID ID			
SCA'S IN GRID	W018		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 20 June 08

UXO QC Specialist Signature [Signature: Don Kean]

Date 20 June 2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.




QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	MATT LAUCHNER	DATE	20 JUNE 08
GRID ID			
SCA'S IN GRID	W068		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature 

Date 20 June 08

UXO QC Specialist Signature 

Date 20 June 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Don Kean UXOQCS</i>	DATE	<i>20 June 2008</i>
GRID ID			
SCA'S IN GRID	W068		
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *20 June 08*

UXO QC Specialist Signature *Don Kean*

Date *20 June 2008*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.





QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Matt Louchart	DATE	20 June 08
GRID ID			
SCA'S IN GRID	W090		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature  Date 20 June 08
UXO QC Specialist Signature  Date 20 June 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	Don Kean LXOQCS	DATE	20 June 2008
GRID ID			
SCA'S IN GRID	W090		
INSTRUMENT(S) USED	Schonstedt		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature

Date 20 JUNE 08

UXO QC Specialist Signature

Date 20 June 2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Matt Lavender</i>	DATE	<i>20 June 08</i>
GRID ID			
SCA'S IN GRID	<i>WD 91</i>		
INSTRUMENT(S) USED	<i>5410NSE40E</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)

↑
N

UXO Technician Inspector Signature *[Signature]*

Date *20 June 08*

UXO QC Specialist Signature *[Signature]*

Date *20 June 08*


List any findings. GPS locations of MEC/MD. Add additional pages if needed.



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Don Kean UXOQCS</u>	DATE	<u>20 June 2008</u>
GRID ID			
SCA'S IN GRID	<u>W091</u>		
INSTRUMENT(S) USED	<u>Schrostedt</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature [Signature]

Date 20 June 08

UXO QC Specialist Signature Don Kean

Date 20 June 2008

List any findings. GPS locations of MEC/MD. Add additional pages if needed.