

Analog Investigation
SCA W048
Seaside MRA, Former Fort Ord



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.25.08</i>
GRID ID	<i>W048 MRS-1 DATA GAPS</i>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.25.08*
UXO QC Specialist Signature *[Signature]* Date *7.25.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap (5) 14



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Knistensen</i>	DATE	<i>7.25.08</i>
GRID ID	<i>W048 MRS-2 DATA GAPS</i>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<i>Sehonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]*

Date *7.25.2008*

UXO QC Specialist Signature *[Signature]*
Tom Kean

Date *7.25.08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

Metal Scrap (4) IL



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Jack Kristensen</i>	DATE	<i>7.25.08</i>
GRID ID	<i>W048 MRS-3 DATA GAPS</i>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)



UXO Technician Inspector Signature *[Signature]* Date *7.25.08*

UXO QC Specialist Signature *[Signature]* Date *7.25.08*
Don Kean

List any findings. GPS locations of MEC/MD. Add additional pages if needed.
Metal Scrap (5) 1L