Daily Reports ECI Daily Field Reports

Parker Flats Phase II MRA, Former Fort Ord

UNIT LOG		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 3/29/2010	3. Time Prepared 1900	
4. Unit Name/Designators		5. Unit Leader (Name and Positio		6. Operational Period	
Brush Clearing (Erik Claus, Crew Boss		0700-1700	
7.			Roster Assigned	L	
	ame		sition	Home Base	
Erik Claus		Crew Boss		Watsonville	
Mike Filbin		Heavy Equipment Opera	itor (HEO)	Santa Cruz	
Michael Pintacu	Jra	Brush Crew		Watsonville	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.		Activity Log	a	I	
Time			Major Events		
0700	Weston Traile	er -Morning safety meeting, in	•	Crew meet SUXO & SHSO. Get radio.	
0730		ness and safety training for bru			
0815				up. Brush cutting specific safety tailboard	
	Begin clearir				
1200	Lunch Break	-			
1230	Resume brus				
1200			adio turned over to UX	O Tech. Move to staging area for	
1700		maintenance and post work of			
1730		site/staging area.			
1700	Bepart Work				
	Work great	Grid C2G7A3 to C2F7I6, 12 gri	ide		
			103		

		1. Project Name/Number	2. Date Prepared	3. Time Prepared
UNIT LOG		5510167-Parker Flats	3/30/2010	1900
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period
Brush Clearing Crew		Mike Filbin, HEO/Crew Boss		0700-1730
7.		Personnel Ros	ter Assigned	
No	ame	Positio	n	Home Base
Mike Filbin		Heavy Equipment Operator	(HEO)	Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
8.		Activity Log		
Time			Major Events	
0700	Weston Trailer -N	Morning safety meeting. Get i	adio.	
0730	Arrive a work ar	ea (Area 8). Brush cutting spe	ecific safety tailboar	d. Begin clearing activities.
1130	Lunch Break			
1200	Resume brush c	learing		
1700	End brush cleari	ing activities for the day. Radi	io turned over to UX	(O Tech. Move to staging area for
	equipment mai	ntenance and post work de-l	orief.	
1730	Depart work site	e/staging area.		
	Work area: Gric	d C2F7H3 to C2F7H6 & C2F7H3	7 to C2G7A8 , 12 gri	ids
9. Prepared by (Nam	e and Position)			
Erik Claus, Crew	Boss (Special Proje	ects Div. Manager)		

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared		
UNI	LOG	5510167-Parker Flats	3/31/2010	1900		
4. Unit Name/Designators		5. Unit Leader (Name and Positior	n)	6. Operational Period		
Brush Clearing Crew		Mike Filbin, HEO		0700-1730		
7.		Personnel R	oster Assigned			
	ame	Posi		Home Base		
Mike Filbin		Heavy Equipment Operate	or (HEO)	Santa Cruz		
Q						
8.		Activity Log				
Time			Major Events			
0700		Morning safety meeting. Ge				
0730		ea (Area 8). Begin finish me	chanical clearing ac	tivities in grids worked Mon & Tues		
1130	Lunch Break					
1200		clearing/finish mastication.				
1700			dio turned over to U	(O Tech. Move to staging area for		
	equipment mai					
1730	Depart work site	e/staging area.				
	Work area: Grid	d C2G7A3 to C2F7H8, 24 gri	ds			
9. Prepared by (Nam	e and Position)					
Erik Claus, Crew	Boss (Special Proje	ects Div. Manager)				

UNI	T LOG	1. Project Name/Number	2. Date Prepared	3. Time Prepared
		5510167-Parker Flats	4/1/2010	1900
4. Unit Name/Design		5. Unit Leader (Name and Positio	,	6. Operational Period
Brush Clearing (Crew	Mike Filbin, HEO/Crew Bo		0700-1730
7.			Roster Assigned	
	ame		sition	Home Base
Erik Claus		Crew Boss		Watsonville
Mike Filbin		Heavy Equipment Operc	itor (HEO)	Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
8.		Activity Lo	q	
Time			Major Events	
0700	Weston Trailer	r -Morning safety meeting. G		
0730				d. Begin clearing activities.
0800	Arrive a work area (Area 8). Brush cutting specific safety tailboard. Begin clearing activities. Erik Claus departs work area. UXO tech notified. Crew Boss responsibility transferred to M. Filbin.			
1130	Lunch Break			
1200	Resume brush	cloaring		
				O Tack Mays to staning grad for
1700				O Tech. Move to staging area for
		aintenance and post work o	de-briet.	
1730	Depart work s	site/staging area.		
	Work area: G	Grid C2G7A9 to C2F8H1 plus	C2F8J2&I2, 14 grids	
9. Prepared by (Nan				

UNIT LOG		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 4/2/2010	3. Time Prepared 1900	
4. Unit Name/Designators		5. Unit Leader (Name and Position		6. Operational Period	
Brush Clearing (Erik Claus, Crew Boss		0700-1530	
7.			Roster Assigned	0,00 1000	
	lame		sition	Home Base	
Erik Claus		Crew Boss		Watsonville	
Mike Filbin		Heavy Equipment Operc	itor (HEO)	Santa Cruz	
Michael Pintac	ura	Brush Crew	. ,	Watsonville	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
3.		Activity Lo	a		
Time		, (0,,) 20	Major Events		
0700	Weston Traile	r -Morning safety meeting. C	Get radio.		
0730		area (Area 8). Brush cutting		d. Begin clearing activities.	
0740		· · · ·		ich grids were completed of clearing.	
				a, including areas cleared by Pacific	
				al mastication work, citing trip hazards	
		quality and fact that large wood debris (LWD) still exisits in work area. E. Claus states that			
	-			and that LWD is yet to be picked up in	
				ction of the client with respect to site	
			-	JXO) and no deficiencies had been	
		to WECI staff.			
0815			rk area, north east side	of former Ft. Ord Nurses quarters. Area is	
				nate to clear this area next. E. Claus	
				await their further instruction as WECI's	
	contractual				
0830	E. Claus rejoi	ns clearing crew and contac	ts M. Filbin to inform of	concerns stated by Matt. M. Filbin &	
	-	to area previously cleared by Pacific Firewood to assess conditions and collect photos of			
		n quality, LWD, size of material/trees removed, etc. Concerns & confusion over final work			
		exist and must be clarified AS			
1200				onmental Awareness Training	
		joins WECI team only for lung	C .		
1230			-	JXO tech informed. M. Filbin assumes	
		sponsibilities. E. Claus to cont			
1500				O Tech. Move to staging area for	
		naintenance and post work of			
1530				8B3 & C2F7H7 to C2G8A2 , 12 grids	

UN	IT LOG	1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 4/5/2010	3. Time Prepared 1800
4. Unit Name/Designators		5. Unit Leader (Name and Positio		6. Operational Period
Brush Clearing		Erik Claus, Crew Boss		0700-1530
-			Roster Assigned	0700-1330
7.	lame		sition	Home Base
Erik Claus	ane	Crew Boss	Shion	Watsonville
Mike Filbin		Heavy Equipment Opera	itor (HEO)	Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez	,	Brush Crew		Watsonville
	·			
-				
8.		Activity Log		
Time			Major Events	
0700		r -Morning safety meeting. G		
0720		area (Area 8). Brush cutting		
0745				3-A7 created to satisfy UXO work req.
~1000	Met up with E	Bruce Moe in southwest quar	ter of Area 8 and revie	wed condition of the work. Bruce was
	satisfied with	the current condition.		
1200	Lunch break			
1230	Brush clearing	g resumes. Mastication focus	ed on areas limbed in [•]	the previous week.
1700	End brush cle	earing activities for the day. R	Radio turned over to UX	O Tech. Move to staging area for
	equipment m	naintenance and post work o	de-brief.	
1730	Depart work	site/staging area.		
	me and Position)			

UNIT LOG		1. Project Name/Number	2. Date Prepared 4/6/2010	3. Time Prepared
4. Unit Name/Designators		5510167-Parker Flats 5. Unit Leader (Name and Positio		6. Operational Period
Brush Clearing (Mike Filbin (HEO), Crew B		0700-1730
7.			Roster Assigned	
	lame		sition	Home Base
-				
Mike Filbin		HEO		Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
3.		Activity Lo	9	
Time		ACTIVITY LO	9 Major Events	
0700	Weston Trailer	r -Morning safety meeting. G		
0725		area (Area 8). Brush cutting		d
0725		g and LWD pickup activities.		u.
1200	Lunch break			
1200		g and LWD pickup resumes.		
1230			Padia turnad over to UV	O Tech. Move to staging area for
1700				
1730		aintenance and post work o		
1730		site/staging area.		
	Work Aroas E	ocur of martication on aring		pickup throughout cleared areas.
	WOIK AIEU. FO	ocus of musication on gript	10w G/C3 - G6C3. LWD	
<u> </u>				

UNIT LOG		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 4/7/2010	3. Time Prepared 1930
4. Unit Name/Designators		5. Unit Leader (Name and Positi		6. Operational Period
Brush Clearing		Mike Filbin (HEO), Crew B		0700-1730
	CIEW			0700-1730
7.	Name		Roster Assigned sition	Home Base
I	NUME	10	511011	
Mike Filbin		HEO		Santa Cruz
MIRETIDIT				
Jose Martinez		Bruch Crow		Watsonville
	_	Brush Crew		
Benito Martinez	2	Brush Crew		Watsonville
8.		Activity Lo	g	
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting. G	Set radio.	
0720	Arrive a work	area (Area 8). Brush cutting	specific safety tailboar	d.
0750	Begin clearing	g and LWD pickup activities.		
0900	Stop masticat	ion work. Limbing continues	s. M. Filbin heads to LFR	trailer for weekly construction meeting.
0930	Construction r	meeting. Brush clearing and	l limbing scope of work	clarified between ARCADIS-WESTON-
	Western ECI. S	Scope of work is greater tha	n what was detailed du	uring the pre-bid tour with respect to
	final condition	n of the masticated materia	I needing to be finer ar	nd the degree to which smaller poison
			_	g is necessary to a height greater than 5
		me locations. Adjustment to		
1030		ns from construction meeting		
1200	Lunch Break		9	
1230		resumes. Heavy oak densit	v of D1-D3 encountered	d slowing progress
1200	biosiricicaning	resones. neavy oak densi	y of DT Do cheodilieres	
1700	End brush clev	aring activities for the day.	Padia turned over to LIX	O Tech. Move to staging area for
1700		aintenance and post work		
1720				
1730		ite/staging area.		
	work Area: Fo	ocus of mastication on grip	10W G/D9 - G8D3. LWD	pickup throughout cleared areas.
	me and Position)		<u></u>	

		1. Project Name/Number	2. Date Prepared	3. Time Prepared
UNIT LOG		5510167-Parker Flats	4/8/2010	1930
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period
Brush Clearing Crew		Mike Filbin (HEO), Crew Boss		0700-1730
7.		Personnel Rost	er Assigned	
	ame	Positio	n	Home Base
Mike Filbin		HEO		Santa Cruz
8.		Activity Log		
Time			Major Events	
0700	Weston Trailer -N	Norning safety meeting. Get r	adio.	
0725				ow mastication work to catch up.
0745		on work in G7C4 to G7C6.		· · · ·
1130	Lunch break			
1200	Mastication wor	rk resumes. G7D3 to G7D6 & E	3-E5. Heavy manzc	nita encountered in D3, E3 & E4.
1700	End brush cleari	ing activities for the day. Radi	o turned over to UX	(O Tech. Move to staging area for
	equipment mai	ntenance.		
1730	Depart work site	e/staging area.		
9. Prepared by (Nam	e and Position)			
Erik Claus, Crew	Boss (Special Proje	ects Div. Manager)		

UNIT LOG		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 4/9/2010	3. Time Prepared 1830
4. Unit Name/Designators		5. Unit Leader (Name and Positio		6. Operational Period
Brush Clearing (Mike Filbin (HEO), Crew B		0700-1530
		· · · ·		0700-1000
7.	ame		Roster Assigned	Home Base
11	une	103	SHOT	nome base
Mike Filbin		HEO		Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
8.		Activity Log	g	•
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting. G		
0720		area (Area 8). Brush cutting		d.
0750	Begin clearing			
1200	Lunch break			
1230	Brush clearing	rosumos		
) a dia turna dia yar ta UV	O Tach Maya ta starting group for
1500				O Tech. Move to staging area for
		aintenance and post work o	de-brief.	
1530	Depart work si	te/staging area.		
	Work Area: Gr	rids G7C7-C9 / D7-D9. Very	heavu manzanita and	thick oak.

UN	IT LOG	1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 4/13/2010	3. Time Prepared 1830
4. Unit Name/Designators		5. Unit Leader (Name and Positio		6. Operational Period
Brush Clearing (Erik Claus, Crew Boss		0700-1730
7.			Roster Assigned	0,00 1,00
	lame		sition	Home Base
Erik Claus	anic	Crew Boss		Watsonville
Mike Filbin		HEO		Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
·				
8.		Activity Lo	g	
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting. G	et radio.	
0720	Arrive a work o	area (Area 8). Brush cutting	specific safety tailboar	d.
0750	Load wood tro	ailer and then begin clearin	g activities.	
1200	Lunch break		-	
1230	Brush clearing	resumes.		
1700			adio turned over to UX	O Tech. Move to staging area for
		aintenance and post work of		
1730		ite/staging area.		
1750				
	Mark Arage N	artharn 1/2 facus an martia	ation of romaining pat	about of manzanita and posion only
		onnem 1/3, locus on masila	calion of remaining par	ches of manzanita and posion oak.
9. Prepared by (Nar				

UNI	T LOG	1. Project Name/Number	2. Date Prepared	3. Time Prepared
4. Unit Name/Designators		5510167-Parker Flats	4/14/2010	6. Operational Period
Brush Clearing (5. Unit Leader (Name and Positi Mike Filbin, Crew Boss	onj	0700-1730
	2161		Destar Assigned	0700-1730
7.	lame		Roster Assigned sition	Home Base
IN	lume	F U.	SIIIOIT	
Mike Filbin		HEO/Crew Boss		Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
3.		Activity Lo	g	
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting. G	Get radio.	
0715		area (Area 8). Brush cutting		d.
0730		ailer and then begin clearin		
1200	Lunch break		0	
1230	Brush clearing	resumes		
1200			Padia turnad ovar ta LIX	O Tech. Move to staging area for
1700				
1720		aintenance and post work (
1730	Depart work si	ite/staging area.		
	Work Area: No	orthern 1/3, Limbing and mi	iastication of limbed mo	aterial.
P. Prepared by (Nan				

UNI	T LOG	1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	4/15/2010	1900	
4. Unit Name/Desigr Brush Clearing (5. Unit Leader (Name and Position Mike Filbin, HEO & Crew B		6. Operational Period 0700-1730	
	JIEW			0700-1730	
7.			Roster Assigned		
IN	lame	P0:	sition	Home Base	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
)			2		
3.		Activity Lo	-		
Time			Major Events		
0700		r -Morning safety meeting. G			
0725	Arrive a work area (Area 8). Brush cutting specific safety tailboard.				
0750	Begin clearing activities.				
1130	Lunch break	Lunch break			
1200	Brush clearing resumes.				
1700	End brush clearing activities for the day. Radio turned over to UXO Tech. Move to staging area				
	equipment m	aintenance and post work a	de-brief.		
1730		site/staging area.			
	Work Aroa: N	lartharn boundary of Arag 9			
	WORK AIEU. N	lorthern boundary of Area 8	•		

UN	IT LOG	1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	4/16/2010	1830	
4. Unit Name/Designators Brush Clearing Crew		5. Unit Leader (Name and Positi Mike Filbin, HEO & Crew		6. Operational Period 0700-1530	
	CIEW			0700-1330	
7.	lamo		Roster Assigned sition	Home Base	
I`	lame	F U.	SIIIOIT	Home Base	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Pruch Crow		Watsonville	
		Brush Crew			
Benito Martinez		Brush Crew		Watsonville	
[
8.		Activity Lo	g		
Time			Major Events		
0700	Weston Trailer	-Morning safety meeting. G	Get radio. Hand crew m	nembers only present at this time.	
	M. Filbin to arri	ve around 0800 with grass r	mowing head. Crew wi	Il specifically be working today on T&M	
	basis against the contingency budget to effect requested grass mowing at the former nur			mowing at the former nurses quarters	
	building yard c	area.			
0730	Hand crew begins limbing up of cypress, trees and brush in the nurses quarters yard area prepping				
	grass mowing equipment.				
0830	M. Filbin arrives at WESTON Trailer, checks in and gets radio.				
0900		ass mwing and brush clear	-	s quarters work area.	
1130	Lunch break.		<u> </u>	·	
1200		continues in the southern p	ortions of Area 8. This w	vork also to be on T&M basis.	
1500				ch. Move to staging area for	
1000		intenance and post work (
1530		e/staging area.			
1550	Depair work si				
1					

UNIT LOG 4. Unit Name/Designators		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared	3. Time Prepared 1900	
		5. Unit Leader (Name and Positio	6/1/2010	6. Operational Period	
Brush Clearing Crew		Erik Claus, Crew Boss		0700-1730	
			Destar Assistanted	0700-1730	
7.	lame		Roster Assigned	Home Base	
Erik Claus	une	Crew Boss	SHOT	Watsonville	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
berino Marinez				Walsonville	
_					
8.		Activity Log			
Time			Major Events		
0700		-Morning safety meeting. G			
0715				rea to review conditions and plan work.	
	UXO Tech to fl	ig the southern limit cash line. Buckets to show the east limit line.			
	Hand crew be	gins limbing.			
0745	Mechanical b	rush clearing starts.			
1045	Constantine w	ire concentration located o	along cash line in grid (C2F8H9. Work here will have to wait until	
	constantine wi	ire is cleared by UXO staff.			
1200	Lunch Break				
1230	Brush clearing	resumes.			
1700	End brush clea	aring activities for the day. R	adio turned over to UX	O Tech. Move to staging area for	
	equipment ma	aintenance and post work a	de-brief.		
1730	Depart work si	te/staging area.			
	Mastication: C	Grids C2F8H2 - C2F8H8 and	C2F8I3 - C2F8I7		
	Hand Work: G	rids C2F8H2 - C2F8H4 and (C2F8I3 - C2F8I6		
9. Prepared by (Nar					

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	6/2/2010	1900	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Mike Filbin, HEO & Crew Boss		0700-1730	
7.		Personnel Roste	er Assigned		
	ame	Position		Home Base	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.		Activity Log			
Time			Major Events		
0700		Norning safety meeting. Get ro	adio.		
0730	Bruah clearing a	activities begin.			
1200	Lunch Break				
1230	-	ictivities resume.			
1700		tivities for the day. Radio turne		h. Move to staging area for	
	equipment mai	ntenance and post work de-b	rief.		
1730	Depart work site	e/staging area.			
	Mastication: Gr	ids C2F8H9 - C2F9H1, C2F8I8 -	C2F9I1, and C2F9J	1	
	Hand Work: Gri	ds C2F8J3 - C2F8J5 and C2G8	A3 - C2G8A5		
9. Prepared by (Name	e and Position)				
		ects Div. Manager)			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	6/3/2010	1800	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Mike Filbin, HEO & Crew Bo	SS	0700-1730	
7.		Personnel Ro	oster Assigned		
N	ame	Posit		Home Base	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.					
ð. Time		Activity Log	Major Events		
0700	Weston Trailer -	Morning safety meeting. Ge	-		
0730	Brush clearing c				
1200	Lunch Break				
1200		activities resume			
1530		Brush clearing activities resume. Hand crew completes activities for the day & departs work area.			
1700				:h. Move to staging area for	
		ntenance and post work de			
1730	Depart work site				
	Mastication: G	rids C2F8J3 - C2F8J5 and C2	G8A3 - C2G8A5		
		ds C2F8H9 - C2F9H1 and C2			
<u> </u>					
9. Prepared by (Nam	ne and Position)				
	Boss (Special Proje	ects Div. Manager)			

ors ew me		,	1830 6. Operational Period 0700-1530 Home Base Santa Cruz Watsonville	
ew.	Mike Filbin, HEO & Crew I Personnel Po: HEO Brush Crew	Boss Roster Assigned	0700-1530 Home Base Santa Cruz	
	Personnel Po: HEO Brush Crew	Roster Assigned	Home Base Santa Cruz	
me	HEO Brush Crew		Santa Cruz	
	Brush Crew		Santa Cruz	
	Brush Crew			
			Watsonville	
			Watsonville	
	Brush Crew			
			Watsonville	
	Activity Lo	0		
		Major Events		
Weston Trailer -	Morning safety meeting. G	,		
Brush clearing activities begin. Lunch Break				
Brush clearing activities resume.				
	e/sidging died.			
Mastication: C	ride COERIE COERIZ and C			
	1103 C2F0J7 - C2F7JT UNU C	,200A0 - C207A1		
		on linalizing cleaning act	infiles in as many grias from the cash	
line north befor	re next work break.			
+				
+				
<u> </u>				
<u> </u>				
 				
 				
 				
<u> </u>				
(equipment ma Depart work sit Mastication: G Hand Work: G Work is progres	equipment maintenance and post work of Depart work site/staging area. Mastication: Grids C2F8I5 - C2F8I7 and C Hand Work: Grids C2F8J7 - C2F9J1 and C	Mastication: Grids C2F8I5 - C2F8I7 and C2F8J3 - C2F8J7 Hand Work: Grids C2F8J7 - C2F9J1 and C2G8A8 - C2G9A1 Work is progressing well. Will be focused on finalizing clearing act	

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared
		5510167-Parker Flats	6/7/2010	1900
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period
Brush Clearing Crew		Mike Filbin, HEO & Crew Boss		0700-1730
7.		Personnel Rost	er Assigned	
No	ame	Positio		Home Base
Mike Filbin		HEO		Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
8.		Activity Log		
Time			Major Events	
0700	Weston Trailer -1	Morning safety meeting. Get r	adio.	
0730	Brush clearing a			
1200	Lunch Break	_		
1230	Brush clearing a	activities resume.		
1700			o turned over to UX	O Tech. Move to staging area for
	equipment maintenance and post work de-brief.			
1730	Depart work site	e/staging area.		
	Mastication: Gr	rids C2G8A3 - C2G8A7 and C	2G8B4 - C2G8B5	
	Hand Work: Gri	ds C2G8B4 - C2G8B0 and C20	G8A6 - C2G8A7	
9. Prepared by (Nam	e and Position)			
Erik Claus, Crew	Boss (Special Proje	ects Div. Manager)		

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	6/8/2010	1900	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Mike Filbin, HEO & Crew Boss		0700-1730	
7.		Personnel Rost	er Assigned		
	ame	Positio		Home Base	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.		Activity Log			
Time			Major Events		
0700	Weston Trailer - <i>I</i>	Morning safety meeting. Get r	adio.		
0730	Brush clearing a	activities begin.			
1200	Lunch Break				
1230	Brush clearing c	activities resume.			
1700	End brush clearing activities for the day. Radio turned over to UXO Tech. Move to staging area for				
	equipment maintenance and post work de-brief.				
1730	Depart work site	e/staging area.			
	Mastication: Gr	rids C2G8B6- C2G9B1			
	Hand Work: Gri	ds C2G8C4 - C2G9C1			
9. Prepared by (Name Frik Claus, Crew		ects Div. Manager)			
LINK CIUUS, CIEW	now isheriai Liale				

UN	IT LOG	1. Project Name/Number	2. Date Prepared	3. Time Prepared	
4. Unit Name/Designators		5510167-Parker Flats 5. Unit Leader (Name and Positi	6/9/2010	6. Operational Period	
Brush Clearing (Mike Filbin, HEO & Crew		0700-1730	
-				0/00-1/30	
7.	lame		Roster Assigned	Home Base	
Erik Claus	ume	Crew Boss	311011	Watsonville	
Mike Filbin		HEO		Santa Cruz	
		Durada Curava		Watsonville	
Jose Martinez		Brush Crew			
Benito Martinez		Brush Crew		Watsonville	
<u> </u>					
8.		Activity Lo	g		
Time			Major Events		
0700	Weston Trailer -Morning safety meeting. Get radio.				
0730	Brush clearing activities begin.				
1200	Lunch Break				
0900	Wood hauling	Wood hauling trailer arrives.			
0930	Begin loading wood trailer.				
1015		trailer departs.			
1230		activities resume.			
1700			Radio turned over to UX	O Tech. Move to staging area for	
.,		aintenance and post work (
1730		te/staging area.			
1766					
		Grids C2G8C4 - C2G9C7 an	IC C2G8B4 - B5		
	Hana Work: G	Grids C2G8D4 - C2G8D8			
9. Prepared by (Nar	me and Position)				
		jects Div. Manager)			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	6/10/2010	1900	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Mike Filbin, HEO & Crew Boss		0700-1730	
7.		Personnel Rost	er Assigned		
	ame	Positio		Home Base	
Mike Filbin		HEO		Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.		Activity Log			
Time			Major Events		
0700		Morning safety meeting. Get r	adio.		
0730	Brush clearing a	activities begin.			
1200	Lunch Break				
1230		activities resume.			
1700	-			(O Tech. Move to staging area for	
	equipment mai	ntenance and post work de-k	orief.		
1730	Depart work site	e/staging area.			
	Mastication: Gr	rids C2G8D4 - C2G8D7 and C	2G8C8 - C2G8C0		
	Hand Work: Gri	ds C2G8D9 - C2G8C0 and C2	2G8E9 - C2G9E1		
9. Prepared by (Nam	e and Position)				
		ects Div. Manager)			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	6/11/2010	1900	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Mike Filbin, HEO & Crew Boss		0700-1530	
7.		Personnel R	oster Assigned		
	ame	Posi		Home Base	
Mike Filbin		HEO		Santa Cruz	
8.		Activity Log			
Time			Major Events		
0700		Morning safety meeting. Ge	et radio.		
0730	Brush clearing a	ictivities begin.			
1200	Lunch Break				
1230		ictivities resume.			
1 500				O Tech. Move to staging area for	
		ntenance and post work d	e-brief.		
1530	Depart work site	e/staging area.			
	Mastication: Gr	rids C2G8E7 - C2G8E0 and	C2G8D8 - C2G9D1		
9. Prepared by (Nam	ne and Position)				
Erik Claus, Crew	Boss (Special Proje	ects Div. Manager)			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared
		5510167-Parker Flats	6/14/10	1700
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period
Brush Clearing Crew		Jose Martinez (Crew Lead)		0700-1530
7.		Personnel Rost	er Assigned	
Nar	ne	Position		Home Base
Jose Martinez		Crew Lead		Watsonville
Benito Martinez		Brush Crew		Watsonville
		DIOSITICIEW		
8.		Activity Log		
Time			Major Events	
0700	Weston Trailer -N	Aorning safety meeting. Get re	adio.	
0715	Begin wood pic	kup operation in the southwes	st corner progressing	g toward the east boundary of Area 4.
1200	Lunch break			
1230	Resume wood p	pickup operations.		
1515	End operations t	for the day. Clean up.		
1530	Depart work are			
9. Prepared by (Name	I and Position)			
Erik Claus, Crew B		ects Div. Manager)		

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	6/15/10	1700	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Cr	ew	Jose Martinez (Crew Lead)		0700-1530	
7.		Personnel Ros	ter Assigned		
	ime	Positio		Home Base	
Jose Martinez		Crew Lead		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
-					
8.		Activity Log			
Time			Major Events		
0700		Aorning safety meeting. Get r			
0715		kup operation in the northerr			
1100				ns to hand clearing of poison oak in	
		le to mower (weed whacking	g).		
1200	Lunch break				
1230		veed whacking operations in			
1530				should now be fully cleared for the	
	purpose of UXO	survey work. Depart work area for the day.			
9. Prepared by (Name	and Position)				
Erik Claus, Crew E	Boss (Special Proje	ects Div. Manager)			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
UNII	LOG	5510167-Parker Flats	6/16/10	1600	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Jose Martinez (Crew Lead)		0700-1330	
7.		Personnel Ros	ster Assigned		
Nc	ame	Positio	on	Home Base	
Jose Martinez		Crew Lead		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.		Activity Log			
Time			Major Events		
0700		Morning safety meeting. Get			
0715	_	acking operations in norther			
1100				. Weed whacking work now complete.	
		a 4 is now clear for UXO surv	ey.		
1200		Lunch break			
1230	-	work picking up minor debri			
1330	Finished operati	ons for the week. Check in with Crew Boss. Inform UXO of departure plans and leave the			
	work area.				
9. Prepared by (Name	e and Position)				
Erik Claus, Crew I	Boss (Special Proje	ects Div. Manager)			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared
UNITLOG		5510167-Parker Flats	07/06/2010	1740
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period
Brush Clearing Crew		Erik Claus		07/06/2010
7.		Personnel Ro	ster Assigned	
N	ame	Positi	on	Home Base
Mike Filbin		Heavy Equipment Operator (HEO)		Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
0		A . 11 11 . 1		
8.		Activity Log		
Time 0700	Master Trailer	Acresian contation Cal	Major Events	
		Morning safety meeting. Get		- tin or De sile sta suis er ersti útiss
0715		ea (area 2). Site waik ana si	re specific safety me	eeting. Begin clearing activities.
1200	Lunch break			
1230		Resume clearing activities.		
1710		Return radio to Weston trailer. Perform equipment maintenance		
1735	Complete work day			
	Work area: Are C2F914	a 2 Grids C2F9H2, C2F9H3, C	2F9H4, C2F9H5, C2F	9H6, C2F9H7, C2F9I7, C2F9I6, C2F9I5,
9. Prepared by (Nam				
Jose Martinez	and rosmony			
SOSO MULTINEZ				

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	07/07/2010	1740	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Erik Claus		07/07/2010	
7.		Personnel Rc	ster Assigned		
	ame	Positi		Home Base	
Mike Filbin		Heavy Equipment Operato	r (HEO)	Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
8.		Activity Log			
Time			Major Events		
0700	Weston Trailer -1	Morning safety meeting. Get	radio.		
0715	Arive at work ar	ea (area 2). site walk and si	e specific safety me	eting. Begin clearing activities.	
1100	Wood pick up, o	and poison oak removal arc	und trees by brush c	rew.	
1200	Lunch break				
1230	Resume woodp	ick up and poison oak rema	oval activities.		
1700	-	Completed wood pick up and poison oak removal for the day.			
1710	-	Return radio to Weston trailer. Perform equipment maintenance. Brush clearing ends.			
1730	Complete work				
1700					
	Work area: Are	a 2 Grids C2F9J7, C2F9I3, C2	F912 C2F912 C2F9H2	2 C2E9H3 C2E9H4 C2E9H5	
9. Prepared by (Name		a 2 Grag GZI / 37 , GZI /10, GZ	,,	-,,,,,,,,,,	
Jose Martinez					

UNIT LOG 4. Unit Name/Designators		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 07/08/2010	3. Time Prepared 1745	
		5. Unit Leader (Name and Positio		6. Operational Period	
Brush Clearing Crew		Erik Claus		07/08/2010	
'.			Roster Assigned	0.,00,20.0	
	lame		sition	Home Base	
<i>A</i> ike Filbin		Heavy Equipment Opera	itor (HEO)	Santa Cruz	
ose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
		Activity Log	g	•	
Time			Major Events		
0700	Weston Trailer -	Morning safety meeting. G	et radio.		
0715	Arive at work c activities.	irea (area 2, Grid C2F9J2).	Site walk and site spec	ific safety meeting. Begin clearing	
0845	B.Martinez was having back pain, stopped work, and took a bro			ak.	
0855	B.Martinez call	ed supervisor M.Pintacura d	due to back pain, unak	ble to work.	
0907	B.Martinez rece	eived a call back from M.Pintacura. B.Martinez instructed to stop working & go to Dr. On			
	Duty, Main St. V	Watsonville for medical attention.			
0932	Brush crew check out with Weston trailer. Headed to Watsonvill				
1010	B.Martinez drop	oped off at Dr. On Duty. Jo	se Martinez return to Po	arker Flats	
1101	J. Martinez resume clearing activities.				
1200	Lunch break				
1230	Resume clearir	ng activities.			
1700	Return radio to	Weston trailer. Perform eq	uipment maintenance	•	
1736	Complete wor	k day.			
	Work area: Are	ea 2 Grids C2F9J2, C2G9A2	2, C2G9A3,C2G9A4, C2	G9A5, C2F9J7	
. Prepared by (Nar					

			07/09/2010	1700	
. Unit Name/Design	nators	5510167-Parker Flats 5. Unit Leader (Name and Positi		6. Operational Period	
Brush Clearing Crew		Erik Claus	,	07/09/2010	
·		Personnel	Roster Assigned		
	lame		sition	Home Base	
Aike Filbin		Heavy Equipment Operc	ator (HEO)	Santa Cruz	
Michael Pintacu	Jra	Brush Crew		Watsonville	
lose Martinez		Brush Crew	Brush Crew		
3.		Activity Lo	g		
Time			Major Events		
0700	Weston Traile	er -Morning safety meeting. G	Set radio.		
0715	Arive at work	k area (area 2). Site walk and	site specific safety me	eting. Begin clearing activities.	
0930	Completed work in area 2. Breif meeting with Bruce to confirm completion.				
0940	Resume clearing activities in work area 6.				
1200	Lunch break				
1230	Resume clearing activities.				
1530	Return radio to Weston trailer. Perform equipment maintenance.				
1545	Complete work day				
	Work area. A	vrea 2 Grids C2G9A7, C2G9A		C2G9B7, C2G9B6, C2G9B5, C2G9B4	
				G9H5, C2G9I3, C2G9J3, C2H9A3,	
			, 020,111, 020		

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	07/12/2010	1700	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing Crew		Erik Claus		07/12/2010	
7.		Personnel Ros	ter Assigned	· ·	
N	ame	Positic	n	Home Base	
Erik Claus		Crew Boss		Watsonville	
Mike Filbin		Heavy Equipment Operator	(HEO)	Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
8.		Activity Log			
Time		,,	Major Events		
0700	Weston Trailer -N	Morning safety meeting. Get	radio.		
0718	Arrive at work a	rea (area 6). Site walk and si	te specific safety me	eeting. Begin clearing activities.	
1200	Lunch break				
1230	Resume clearing	g activities in work area 6.			
1530	Hand crew stop	Hand crew stops work for the day, turns in radio at Weston trailer and departs work area.			
1730		es end for the day. Radio retu			
	Work Area 6 Cri	ds: C2G9J3 thru C2G9J7, C20	$2013 \text{ thru} C2C0 17 \alpha$	nd C2C0H3 thru C2C0H7	
		us, czg7ju ii ii u czg7j/, cz			
9. Prepared by (Nam	e and Position)				
Michael Pintacu					

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared		
		5510167-Parker Flats	07/13/2010	1800		
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period		
Brush Clearing Crew		Erik Claus		07/13/2010		
7.		Personnel (Roster Assigned			
N	lame	Pos	sition	Home Base		
Mike Filbin		Heavy Equipment Opera	tor (HEO)	Santa Cruz		
Michael Pintacura		Brush Crew		Watsonville		
Jose Martinez		Brush Crew		Watsonville		
8.		Activity Log	n			
Time			Major Events			
0700	Weston Trailer -I	Morning safety meeting. G	,			
0716				eeting. Begin clearing and wood pickup		
1200	Lunch break					
1230		Resume clearing and wood pickup activities in work area 6.				
1530		os work for the day, turns in		r and departs work area		
1730						
1730		es end for the day. Radio retuned to the Weston trailer.				
	Work Area 6 Gr	ids: C2G9J3 thru C2G9J7, (C2G9I3 thru C2G9 I7, a	nd C2G9H3 thru C2G9H7		
9. Prepared by (Nar						
Michael Pintacu	Jra					

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510167-Parker Flats	07/14/2010	1800	
4. Unit Name/Designators		5. Unit Leader (Name and Positi	on)	6. Operational Period	
Brush Clearing Crew		Erik Claus, Crew Boss		07/14/2010	
7.		Personnel	Roster Assigned		
N	lame	Po	sition	Home Base	
Erik Claus		Crew Boss			
Mike Filbin		Heavy Equipment Opera	ator (HEO)	Santa Cruz	
Michael Pintacu	ura	Brush Crew		Watsonville	
Jose Martinez		Brush Crew		Watsonville	
8.		Activity Lo	g		
Time			Major Events		
0700	Weston Trailer -I	Morning safety meeting. G	Set radio.		
0715	Arrive at work c activities.	area (area 6). Site walk an	d site specific safety me	eeting. Begin clearing and wood pickup	
1200	Lunch break				
1230	Resume clearin	g and wood pickup activ	ities in work area 6.		
1420	Erik Claus arrive	es on site. Stop at Weston t	railer to check in and m	neet with Bruce Moe to review work	
	area maps and	area maps and needed work grids. Met with crew to review and assist for afternoon.			
1530	Hand crew stop	Hand crew stops work for the day, turns in radio at Weston trailer and departs work area.			
1730	Mowing activiti	es end for the day. Radio retuned to the Weston trailer.			
	Work Area 6 Gr	ids: C2H9A3 thru C2H9A7,	C2H9B3 thru C2H9B7, a	nd C2H9C3 thru C2H9C7	
9. Prepared by (Nar	ne and Position)				
Michael Pintacu	Jra				

		1. Project Name/Number	2. Date Prepared	3. Time Prepared		
UNIT LOG		5510167-Parker Flats	07/15/2010	1800		
4. Unit Name/Designators		5. Unit Leader (Name and Positi	ion)	6. Operational Period		
Brush Clearing Crew		Erik Claus, Crew Boss		07/15/2010		
7.		Personnel	Roster Assigned			
N	lame	Po	sition	Home Base		
Mike Filbin		Heavy Equipment Opera	ator (HEO)	Santa Cruz		
Michael Pintac	ura	Brush Crew		Watsonville		
Jose Martinez		Brush Crew		Watsonville		
8.		Activity Lo	g	i		
Time			Major Events			
0700	Weston Trailer	-Morning safety meeting. G	Get radio.			
0715	Arrive at work activities.	area (area 6). Site walk an	d site specific safety me	eeting. Begin clearing and wood pickup		
1200	Lunch break					
1230	Resume cleari	ng and wood pickup activ	ities in work area 6.			
1530	Hand crew sto	pps work for the day, turns in	n radio at Weston trailer	r and departs work area.		
1730	Mowing activi	ties end for the day. Radio	retuned to the Weston	trailer.		
	Work Area 6 G	Frids: C2H9C3 thru C2H9C7	and C2H9D3 thru C2H9	D6		
9. Prepared by (Nar	me and Position)					
Michael Pintac	ura					

		1. Project Name/Number	2. Date Prepared	3. Time Prepared
UNIT LOG		5510167-Parker Flats	07/16/2010	1800
4. Unit Name/Designators		5. Unit Leader (Name and Positi	on)	6. Operational Period
Brush Clearing (Crew	Erik Claus, Crew Boss		07/16/2010
7.		Personnel	Roster Assigned	
Ν	lame	Po	sition	Home Base
Mike Filbin		Heavy Equipment Operc	ator (HEO)	Santa Cruz
Michael Pintacu	ura	Brush Crew		Watsonville
Jose Martinez		Brush Crew		Watsonville
8.		Activity Lo	g	
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting. G	Set radio.	
0715	Arrive at work activities.	area (area 6). Site walk and	d site specific safety me	eeting. Begin clearing and wood pickup
1200	Lunch break			
1230	Resume cleari	ng and wood pickup activ	ities in work area 6.	
1530	Hand crew sto	ps work for the day, turns ir	n radio at Weston trailei	r and departs work area.
1730	Mowing activit	ties end for the day. Radio	retuned to the Weston	trailer.
	Area 6 should	be finalized on Monday 7/	19	
	Work Area 6 G	rids: C2H9C3 thru C2H9C7,	C2H9D1 thru C2H9D6,	C2H8D8 thru C2H8D0, and C2H8C8
9. Prepared by (Nar	me and Position)			
Michael Pintacu	ura			

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared
UNI	LUG	5510167-Parker Flats	07/19/2010	
4. Unit Name/Designators		5. Unit Leader (Name and Position)	6. Operational Period
Brush Clearing C	rew			07/19/2010
7.		Personnel Ro	oster Assigned	
Na	ame	Posit	ion	Home Base
Mike Filbin		Heavy Equipment Operato	or (HEO)	Santa Cruz
Jose Martinez		Brush Crew		Watsonville
Benito Martinez		Brush Crew		Watsonville
0		A oth its Loop		
8. Time		Activity Log	Major Events	
0700	Wester Trailer	Morping sofety mosting Co	Major Events	
		Morning safety meeting. Ge		
0715		ety meeting. Continued bru	shing work in drush c	ut alea 7.
1035		C2H8A2 J for limbing work.		
1107		pped work due to back pair	n. J.Martinez continue	ed with brushing work grid C2G8J3
1200	Lunch break			
1230		hing activities on grid C2H8,		
1330		oing work in issued grids, be	gan to weed whack	poison oak at tree bases, and pick up
	wood.			
1500		ntenance, return radio to W	eston trailer.	
1530	Work day comp	bleted		
	Work area: Grid	ds C2H8C2, C2H8C3, C2H8C	24, C2H8A2, C2H8A3,	C2H8A4, C2H8C6, C2H8C7
9. Prepared by (Nam	e and Position)			
Michael Pintacu	ra crew lead			

		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
UNI	T LOG	5510167-Parker Flats	07/20/2010		
4. Unit Name/Designators		5. Unit Leader (Name and Positio	n)	6. Operational Period	
Brush Clearing (Crew			07/20/2010	
7.		Personnel R	Roster Assigned		
	lame		ition	Home Base	
Mike Filbin		Heavy Equipment Operat	tor (HEO)	Santa Cruz	
Jose Martinez		Brush Crew		Watsonville	
Benito Martinez		Brush Crew		Watsonville	
0					
8. Time		Activity Log	J Major Events		
0700	Woston Trailor	Morning safety meeting. G			
0700		ety meeting. Brushing crew			
1016		ng work in grid C2G8I4 to c			
1018					
		ing activities on grid C2H84			
1200		opped work at grid C2G7J			
1230		ing activities on gridC2G7J			
1245	-	ting with E.Claus. Discussed	progress and work pla	an for the rest of the week	
1255	Resumed work				
1520		ntenance, return radio to V	Veston trailer		
1535	Completed wo	rk day			
	Work area: Grid C2G7I0, C2G7H		A1, C2G7J0, C2G8J1,	C2G8J2, C2G8J3, C2G8J4, C2G8I4,	
9. Prepared by (Nan					
Michael Pintacu	ura crew lead				

UNIT LOG		1. Project Name/Number 5510167-Parker Flats	2. Date Prepared 07/21/2010	3. Time Prepared
4. Unit Name/Designators Brush Clearing Crew		5. Unit Leader (Name and Positic	n)	6. Operational Period 07/21/2010
7.		Personnel F	Roster Assigned	
	lame		ition	Home Base
Mike Filbin		Heavy Equipment Opera	tor (HEO)	Santa Cruz
Michael Pintac	ura	Brush Crew		Watsonville
Jose Martinez		Brush Crew		Watsonville
8.		Activity Log	9	
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting. G	et radio.	
0715	Site specific sa	ifety meeting. began weed	whacking and wood p	oick up area 7
0930	Weed whacki	ng completed in area 7		
1200	Lunch break. V	worke dstpped in grid C2H8	42	
1230	Resume wood	pick up in grid C2H8A2		
1458	Completed w	ork in area 7		
1505	Site walk with	Greg to verifiy area 7 comp	lete. Clarify with Greg a	and Mike D. that north grid lines on area
	7 was comple	ted. Weston request WECI n	ot pull equipment whe	en complet with area 9. a nother area
	is being layed	out for work.		
1525	Equipment ma	aintenance, return radio to \	Weston trailer	
1537	Completed w	ork day		
		rids All grids in area 7		
9. Prepared by (Nar				
Michael Pintac	ura crew lead			

		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
UNI	T LOG	5510167-Parker Flats	07/22/2010		
4. Unit Name/Designators		5. Unit Leader (Name and Positio	n)	6. Operational Period	
Brush Clearing C	Crew			07/22/2010	
7.		Personnel R	oster Assigned		
	ame		tion	Home Base	
Mike Filbin		Heavy Equipment Operat	or (HEO)	Santa Cruz	
Michael Pintacu	ra	Brush Crew		Watsonville	
Jose Martinez		Brush Crew		Watsonville	
8.		Activity Loo			
ö. Time	1	Activity Log	Major Events		
0700	Weston Trailer -I	Morning safety meeting. Ge			
0700		ety meeting. Site walk in ar		lan for aroa	
0713		activities in grid C2G7B2			
1200		ork stopped in grid C2G6E)		
)		
1230	Resumed work	-		11 1 147 1 1 1	
1515		ntenance. Stopped work ir	i grid C2G6C0. Return	radio to weston trailer	
1535	Completed wo	rk day			
		ds C2G7C2, C2G7D2, C2G D0, C2G6D9, C2G6C0	7F2, C2G7D1, C2G7E1	, C2G7F1, C2G6F0, C2G6F9, C2G6E9,	
9. Prepared by (Nam					
Michael Pintacu	ra crew lead				

UNIT LOG		1. Project Name/Number	2. Date Prepared	3. Time Prepared		
	ILUG	5510167-Parker Flats	07/23/2010			
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period		
Brush Clearing (Crew			07/23/2010		
7.		Personnel	Roster Assigned			
N	lame	Pot	sition	Home Base		
Mike Filbin		Heavy Equipment Opera	itor (HEO)	Santa Cruz		
Michael Pintacu	ura	Brush Crew		Watsonville		
Jose Martinez		Brush Crew		Watsonville		
8.		Activity Lo	9			
Time			Major Events			
0700	Weston Trailer -	Morning safety meeting. G	Set radio.			
0715	Site specific saf	ety meeting. Began brushi	ing activities in grid C20	G6C9		
1200	Lunch break. W	/ork stopped in grid C2F6H	7 and C2F6I7			
1230	Resumed work	in grid C2F6H7 and C2F6I7				
1330	J.Martinez com	pleted work day. J.Martine	ez does equipment ma	intenance		
	M.Pintacura co	ntinues brushing activities	in grid C2F6H8			
1510	Equipment mai	ntenance. Stopped work i	n grid C2F6H9. Return r	adio to Weston trailer		
1530	Completed wo	rk day				
		ds C2G6C9, C2G6C0, C2G C2F6H7, C2F6H8, C2F6H9	66B9, C2G6B0, C2G6A9	9, C2G6A0, C2G6A8, C2G6A7, C2G6B8,		
9. Prepared by (Nan		-				
Michael Pintacu	ura crew lead					

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/23/2010	3. Time Prepared 1800	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing (Crew	Erik Claus, Crew Boss		08/23/2010	
7.		Personnel	Roster Assigned		
Ν	lame	Ро	sition	Home Base	
Vike Filbin		Heavy Equipment Opera	ator (HEO)	Santa Cruz	
Aike Burns		Heavy Equipment Opera	ator (HEO)	Ventura	
Aichael Pintacu	ura	Brush Crew		Watsonville	
ose Martinez		Brush Crew		Watsonville	
l.		Activity Lo	9		
Time			Major Events		
0700	Weston Trailer -	Morning safety meeting. G	Set radios.		
0720	Arrive at work A	area VII. Begin clearing ac	tivities. Machine working	g in northwestern, and	
	northeastern qu	uad. Hand crew limbing be	ehind tacktor northeast	ern quad.	
1200	Lunch Break				
1230	Clearing activit	ies resume. Hand crew wo	orks on tree limbing.		
1515	Hand crew cea	ases operations for the day	/ and begins equipmen	t maintenance.	
1530	Hand crew dep	oarts work area.			
1700	Mechanical ma	astication work ends for the	e day.		
1730	Mechanical eq	uipment maintenance co	mplete. Both HEO's turn	ns radios in and depart work area.	
				· · · · · · · · · · · · · · · · · · ·	
	Mork Aroon Mar	chanical martication cont	inucs in the parth half a	of the work area. Hand crew works	
				I THE WOLK ALEA. HALIG CLEW WOLKS	
	nenina equipm	uipment to prepare for second pass with the tractor.			

UNI	TLOG	1. Project Name/Number	2. Date Prepared	3. Time Prepared
4 Unit Name (Designators		5510180-Area VII	08/24/2010	1800
4. Unit Name/Designators Brush Clearing Crew		5. Unit Leader (Name and Positi Erik Claus, Crew Boss	on)	6. Operational Period 08/24/2010
0	SIEW		Dester Assigned	08/24/2010
7. N	lame		Roster Assigned	Home Base
Vike Filbin	lame	Heavy Equipment Opera		Santa Cruz
Vike Burns		Heavy Equipment Opera		Ventura
Vichael Pintacu		Brush Crew		Watsonville
	JIA			
Jose Martinez		Brush Crew		Watsonville
3.		Activity Lo	g	
Time			Major Events	
0700	Weston Trailer	-Morning safety meeting.	Set radios.	
0720	Arrive at work	Area VII. Begin clearing ac	tivities. Machine's worki	ng in northwestern, and
	northeastern o	quad. Hand crew brush cuti	ting around base of tree	es in northeast quad.
1200	Lunch Break	•	3	·
1230		vities resume. Hand crew wo	orks on brush cutting at	base of trees
1515		eases operations for the day	<u> </u>	
1515		eparts work area.		
1700		nastication work ends for the	3	
1730	iviecnanicai e	equipment maintenance co	implete. Both HEO's turn	ns radios in and depart work area.
	Mork Aroon M	ochanical mastication cont	inucs in the parth half a	of the work area. Hand areaw works
				of the work area. Hand crew works
	penind equip	ment to prepare for second	i pass with the tractor.	

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/25/2010	3. Time Prepared 1800	
4. Unit Name/Designators		5. Unit Leader (Name and Position)		6. Operational Period	
Brush Clearing (Crew	Erik Claus, Crew Boss		08/25/2010	
7.		Personnel	Roster Assigned		
N	lame		sition	Home Base	
Mike Filbin		Heavy Equipment Opera		Santa Cruz	
Mike Burns		Heavy Equipment Opera	ator (HEO)	Ventura	
Michael Pintacu	ura	Brush Crew		Watsonville	
Jose Martinez		Brush Crew		Watsonville	
Erik Claus		Crew Boss		Watsonville	
8.		Activity Lo	g		
Time			Major Events		
0700	Weston Trailer	-Morning safety meeting. G	Set radios.		
0720	Arrive at work	Area VII. Begin clearing ac	tivities. Machine's worki	ng in northwestern, and	
	northeastern o	quad. Hand crew tree limbi	ng in northwest quad.	d.	
1100	Work stop safe	ety tailboard equipment op	erations and hand crev	w operations review of procedure.	
1200	HEO Mike Burr	ns turns in radio and departs	s work area.		
1200	Lunch Break.				
1230	Clearing activ	vities resume with HEO Mike	Filbin. Hand crew works	on brush cutting at base of trees.	
1515	Hand crew ce	eases operations for the day	/ and begins equipmen	it maintenance.	
1530	Hand crew de	eparts work area.			
1700	Mechanical n	nastication work ends for th	e day.		
1730	Mechanical e	quipment maintenance co	mplete. HEO turns radio	o in and depart work area.	
			·	· · · · ·	
	Mork Aroox M	ochanical mastication cont	inues in the parth half a	of the work area. Hand crew continues	
				I THE WOLK ALEA. HALLU CLEW COLULIURS	
		ities in north half of project	aita.		
0 Dropored by (N=-	no and Desition				
9. Prepared by (Nan	ne and Position) / Boss				

UNIT LOG 4. Unit Name/Designators		1. Project Name/Number	2. Date Prepared	3. Time Prepared	
		5510180-Area VII	08/26/2010	1800	
4. Unit Name/Designators Brush Clearing Crew		5. Unit Leader (Name and Position)		6. Operational Period	
	Jiew	Erik Claus, Crew Boss		08/26/2010	
7.	1		Roster Assigned	Hama Dava	
Mike Filbin	lame	Heavy Equipment Opera	sition	Home Base Santa Cruz	
Michael Pintac	ura	Brush Crew		Watsonville	
Jose Martinez		Brush Crew		Watsonville	
Jerry Diaz		Wood Hauler		Watsonville	
0		A oth its Lo	a		
8. The s		Activity Log	0		
Time	Moster Troiler	Marning asfatu meating. C	Major Events		
0700		-Morning safety meeting. G			
0720				nd crew begines wood pickup	
		rn quad, and shuttles to stag			
0800	Wood hauler of	departs. Machine begins fin	al mowing operations i	northeast quad.	
1200	Lunch Break				
1230	Machine load	s wood in to wood hauler H	land crew resumes woo	od pickup in northeast quad.	
1300	Wood hauler o	departs. Machine resumes f	inal mowing operations	s northeast quad.	
1515	Hand crew ce	eases operations for the day	and begins equipmen	nt maintenance.	
1530	Hand crew de	eparts work area.			
1700	Mechanical m	nastication work ends for the	e day.		
1730	Mechanical e	quipment maintenance co	mplete. HEO turns radio	o in and depart work area.	
				· · · · · · · · · · · · · · · · · · ·	
	Work Area: Me	echanical mastication cont	inues in the north half c	of the work area. Hand crew continues	
	with final steps	s of cleanup and wood rem	noval.		
9. Prepared by (Nar	me and Position)				
Erik Claus, Crew	/ Boss				

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/09/2010	3. Time Prepared 1800
4. Unit Name/Designators		5. Unit Leader (Name and Positi	on)	6. Operational Period
Brush Clearing (Crew	Erik Claus, Crew Boss		08/09/2010
7.			Roster Assigned	
	lame		sition	Home Base
Erik Claus		Crew Boss		Watsonville
Mike Burns		Heavy Equipment Operc	afor (HEO)	
Michael Pintac	ura	Brush Crew		Watsonville
Jose Martinez		Brush Crew		Watsonville
8.		Activity Lo	g	
Time			Major Events	
0700	Weston Trailer	r -Morning safety meeting. G	et radio.	
0715	Arrive at work	Area VII. Site walk and site	specific safety meeting	. Begin hand clearing and limbing.
1000	HEO and E. Claus arrive at work area. Offload mastication equipment at work area.			
1100	At Weston tra	iler for initial UXO awareness	s training and HASP revi	ew w/G. Clark for Mike Burns, new HEO.
1200	HEO begins m	nechanical mastication wor	k. Hand crew breaks fo	r lunch.
1230	Hand crew re	sumes activities.		
1500	Hand crew st	ops work for day and begins	s equipment maintenar	nce. Radio handed over to UXO Tech.
1530	Hand crew de	eparts work area.		
1730	Mechanical r	nastication work ends for do	ay.	
	vvork Area: Be	eginning in the southern edg	je glius und west hear	
9. Prepared by (Nar E rik Claus, Cre w				

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/10/2010	3. Time Prepared 1800		
1. Unit Name/Desigr	nators	5. Unit Leader (Name and Positi	on)	6. Operational Period		
Brush Clearing (Crew	Erik Claus, Crew Boss		08/10/2010		
7.			Roster Assigned			
<u> </u>	lame	Ро	sition	Home Base		
Mike Burns		Heavy Equipment Operc	ator (HEO)	Ventura		
Michael Pintac	ura	Brush Crew		Watsonville		
Jose Martinez		Brush Crew		Watsonville		
3.		Activity Lo	g			
Time			Major Events			
0700	Weston Trailer	-Morning safety meeting.	Get radios.			
0715	Arrive at work	Area VII. Begin clearing ac	tivities. Mastication to fo	ocus on brush only areas for now.		
	Hand crew to	continue with tree limbing	and removals.			
1200	Lunch break					
1230	Clearing activ	rities resume				
1500	Hand crew stops work for day and begins equipment maintenance. Radio handed over to UXO Tech.					
		,				
1530	Hand crew departs work area.					
1730		nastication work ends for do	Vr			
	Work Area: Mastication work focusing on the brush only areas so maximum grid area can be turned ove					
	WORK AIEU. MIC					
	for UXO survey		,			
			,			

T LOG	1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/11/2010	3. Time Prepared 1800
		on)	6. Operational Period
Crew			08/11/2010
-			
lame		sition	Home Base
			Watsonville
		afor (HEO)	Ventura
ura			Watsonville
	Brush Crew		Watsonville
	Activity Lo	g	
		Major Events	
Arrive at wor	'k Area VII. Begin clearing ac	tivities. Mastication con	tinues in brush only areas.
Hand crew c	continues with tree limbing ar	nd removal.	
Lunch break			
Clearing activities resume			
Hand crew s	tops work for day and begins	s equipment maintenar	nce. Radio handed over to UXO Tech.
Hand crew departs work area.			
Mechanical	mastication work ends for do	а у .	
Work Area: S	ame work areas as previous	day	
VIOR AIEU: 3	and work aleas as plevious	uuy.	
J	Arrive at wor Hand crew of Lunch break Clearing act Hand crew of Mechanical	IT LOG 5510180-Area VII hators 5. Unit Leader (Name and Positi Crew Erik Claus, Crew Boss Personnel Personnel Iame Po Crew Boss Heavy Equipment Opercours Jara Brush Crew Jara Brush Crew Jara Brush Crew Jara Activity Lo Jara Activity Acea VII. Begin clearing ac Hand crew departs work area	ITLOG 55 10180-Area VII 08/11/2010 hators 5. Unit Leader (Name and Position) Crew Erik Claus, Crew Boss Personnel Roster Assigned Iame Position Crew Boss Erik Claus, Crew Boss Heavy Equipment Operator (HEO) Irea Jama Brush Crew Brush Crew Brush Crew Brush Crew Irea Irea Brush Crew Irea Irea Brush Crew Irea Irea Activity Log Irea Irea Irea Ir

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/12/2010	3. Time Prepared 1800		
I. Unit Name/Desigr	nators	5. Unit Leader (Name and Positi	on)	6. Operational Period		
Brush Clearing (Crew	Erik Claus, Crew Boss		08/12/2010		
•			Roster Assigned			
Ν	lame	Po	sition	Home Base		
1ike Burns		Heavy Equipment Operc	afor (HEO)	Ventura		
lichael Pintac	ura	Brush Crew		Watsonville		
ose Martinez		Brush Crew		Watsonville		
		Activity Lo				
Time			Major Events			
0700		er -Morning safety meeting. G				
0715		Area VII. Begin clearing activities. Mastication continues in brush only areas.				
	Hand crew continues with tree limbing and removal.					
1200	Lunch break					
1230	Clearing activities resume					
1500	Hand crew s	tops work for day and begins	s equipment maintenar	nce. Radio handed over to UXO Tech.		
1530	Hand crew o	Hand crew departs work area.				
1700	Mechanical	mastication work ends for do	а у .			
1730	Equipment n	quipment maintenance completed and HEO leaving work site.				
	Work Area: N	Aastication work wrapping u	o in brush only areas. He	and work progressing into middle of		
	Area VII.					

UN	1. Project Nar 5510180-Ar		2. Date Prepared 08/13/2010	3. Time Prepared 1800	
1. Unit Name/Desig	nators 5. Unit Leader	(Name and Position))	6. Operational Period	
Brush Clearing	Crew Erik Claus,	Crew Boss		08/13/2010	
' .			oster Assigned		
Ν	lame	Posit	ion	Home Base	
/like Burns		ipment Operato	or (HEO)	Ventura	
Aichael Pintac				Watsonville	
ose Martinez	Brush Crew	/		Watsonville	
		Activity Log			
Time			Major Events		
0700	Weston Trailer -Morning safe	ety meeting. Ge	et radios.		
0715	Arrive at work Area VII. Beg	in clearing activ	vities. Mastication worl	k in hand limbed areas on the south.	
	Hand crew working in direc	t support of ma	chine.		
1200	Lunch break				
1230	Clearing activities resume				
1500	Hand crew stops work for day and begins equipment maintenance. Radio handed over to UXO Tech.				
		,			
1530	Hand crew departs work area.				
1700	Mechanical mastication wa		·.		
1730	Equipment maintenance c				
1700					
	Work Area: South area tree line nearly complete north int				
	Work Area: South area tree	line nearly com	plete north into brush	only areas. Wood pickup remains and	
	Work Area: South area tree some final hand work in this				

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/16/2010	3. Time Prepared 1800	
1. Unit Name/Desigr	nators	5. Unit Leader (Name and Positio	on)	6. Operational Period	
Brush Clearing (Crew	Erik Claus, Crew Boss		08/16/2010	
7.			Roster Assigned		
	lame		sition	Home Base	
rik Claus		Crew Boss		Watsonville	
Aike Burns		Heavy Equipment Operc	ator (HEO)	Ventura	
/lichael Pintac	ura	Brush Crew		Watsonville	
ose Martinez		Brush Crew		Watsonville	
		Activity Lo	g	· · · · · · · · · · · · · · · · · · ·	
Time			Major Events		
0700	Weston Traile	er -Morning safety meeting. G	Set radios.		
0715	Arrive at wor	k Area VII. Begin clearing ac [.]	tivities.		
	Hand crew working in direct support of machine.				
1200	Lunch break				
1230	Clearing activities resume				
1400	Hand crew transitions from tree limbing to weed whacking around tree bases to clear veg.				
1515	Hand crew ceases clearing activities, equipment maintenance.				
1530	Hand crew c	leparts work area.			
1700	Mechanical	mastication work ends for do	ay.		
1730	Equipment m	naintenance completed and	d HEO leaving work site.		
		· · ·			
				the work area. Hand crew starting	
	tinal steps of	cleanup and beginning woo	ba removal.		

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/17/2010	3. Time Prepared 1800
. Unit Name/Desigr	nators	5. Unit Leader (Name and Positi	on)	6. Operational Period
Brush Clearing (Crew	Erik Claus, Crew Boss		08/17/2010
		Personnel	Roster Assigned	
Ν	lame	Ро	sition	Home Base
1ike Burns		Heavy Equipment Operc	ator (HEO)	Ventura
lichael Pintacu	ura	Brush Crew		Watsonville
ose Martinez		Brush Crew		Watsonville
		Activity Lo	q	
Time			Major Events	
0700	Weston Traile	er -Morning safety meeting. G	Get radios.	
0720		rk Area VII. Begin clearing ac		g in northeastern quad.
		addresses tree per specific re		
0755	Hand crew completes specific tree work and begins wood removal and weed whacking.			
1200	Lunch Break			5
1230	Hand crew resumes wood pickup activities. Machine continues in the northeastern quad.			
1518				
1530	Hand crew ceases wood pickup for the day. Hand crew departs work area.			
1700		mastication work ends for do	ער V	
1730		maintenance completed and HEO leaving work site.		
1700	Equipment			·
	Work Area: N	Mechanical mastication cont	tinues in the north half c	of the work area. Hand crew continues
	with final ste	ps of cleanup and wood rem	noval.	

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/18/2010	3. Time Prepared 1800		
4. Unit Name/Designators		5. Unit Leader (Name and Positi		6. Operational Period		
Brush Clearing (Erik Claus, Crew Boss		08/18/2010		
7.		Personnel	Roster Assigned			
Ν	lame	Position		Home Base		
Erik Claus		Crew Boss		Watsonville		
Mike Burns		Heavy Equipment Operc	ator (HEO)	Ventura		
Michael Pintac	ura	Brush Crew		Watsonville		
Jose Martinez		Brush Crew		Watsonville		
Jerry Dias		Truck Driver		Watsonville		
3.		Activity Lo	-			
Time			Major Events			
0700		r -Morning safety meeting.				
0720		k Area VII. Begin clearing ac		g in northeastern quad.		
1000		Hand crew continues with wood pickup and trailer loading.				
1030		ves to meet w/Arcadis staff		work area.		
1130	-	ives with trailer for wood hau	-			
1245	Jerry Dias departs with a trailer load of wood. Lunch Break					
1315		esumes wood pickup.				
1430	Jerry Dias ret w/Erik Claus.	Jerry Dias returns for another load of wood. Hand crew transitions to trailer loading. Quick safety brief w/Erik Claus.				
1515	Hand crew c	Hand crew completes activities for the day. Equipment maintenance.				
1700	Mechanical	mastication work ends for th	e day.			
1730	Mechanical	equipment maintenance cc	omplete. HEO turns radio	o in and depart work area.		
				of the work area. Hand crew continues		
	with final step	os of cleanup and wood rem	noval.			
9. Prepared by (Nar	me and Position)					

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/19/2010	3. Time Prepared 1800	
4. Unit Name/Desigi	nators	5. Unit Leader (Name and Positi	on)	6. Operational Period	
Brush Clearing (Crew	Erik Claus, Crew Boss		08/19/2010	
7.			Roster Assigned		
Ν	lame	Ро	sition	Home Base	
Mike Burns		Heavy Equipment Operc	ator (HEO)	Ventura	
Vichael Pintac	ura	Brush Crew		Watsonville	
Jose Martinez		Brush Crew		Watsonville	
3.		Activity Lo	g		
Time			Major Events		
0700	Weston Trail	er -Morning safety meeting. G	Get radios.		
0720	Arrive at wo	rk Area VII. Begin clearing ac	tivities. Machine workin	g in northeastern quad.	
	Hand crew continues with wood pickup.				
1200	Lunch Break	Lunch Break			
1230	Clearing activities resume. Hand crew works on tree limbing.				
1515	Hand crew ceases operations for the day and begins equipment maintenance.				
1530	Hand crew departs work area.				
1700	Mechanical mastication work ends for the day.				
1730	Mechanical	equipment maintenance cc	omplete. HEO turns radio	o in and depart work area.	
	Work Area: I	Mechanical mastication cont	tinues in the north half c	of the work area. Hand crew continues	
	with final ste	ps of cleanup and wood rem	noval.		
) Prenared by (Nar	me and Position)				

UNIT LOG		1. Project Name/Number 5510180-Area VII	2. Date Prepared 08/20/2010	3. Time Prepared 1800
1. Unit Name/Desigr		5. Unit Leader (Name and Positio	on)	6. Operational Period
Brush Clearing (Crew	Erik Claus, Crew Boss		08/20/2010
7.			Roster Assigned	
N	lame	Po:	sition	Home Base
Vike Burns		Heavy Equipment Operc		Ventura
Vichael Pintaci	ura	Brush Crew		Watsonville
Jose Martinez		Brush Crew		Watsonville
}.		Activity Lo		
Time		Morpho antata a da	Major Events	
0700		er -Morning safety meeting. G		· · · · · ·
0720		k Area VII. Begin clearing ac		
	Hand crew continues with tree limbing in northeastern quad that the machine as finished.			
1200	Lunch Break			
1230	Clearing activities resume.			
1515	Clearing operation ceases operations for the day and begin equipment maintenance.			
1530	Clearing crev	w turns in radios and departs	work area for the weel	k.
	Work Area: N	Aechanical mastication cont	inues in the north half c	of the work area. Hand crew continues
		os of cleanup and wood rem		