



KEMRON

Gilbane

BRA and Lead Evaluation Status

Fort Ord HTW BCT

9 January 2019

Basewide Range Assessment

- Preparing draft final sampling report for Units 1, 2, 3, 7, 10, 33, and WGBA.
- Responding to comments on the draft sampling results report for Units 25 and 28. No comments received on Unit 31.
- KEMRON provided updates to the HAs addressed under the current contract for the update to the Comprehensive BRA Report.
- KEMRON conducted a site reconnaissance in BLM Area B accessible areas last month and is preparing a description of the findings.

Site 39 Erosion Control

- KEMRON is monitoring Site 39 areas throughout the Impact Area MRA for erosion issues.
- KEMRON is addressing maintenance issues at erosion control sites.

Lead Evaluation Sites

- KEMRON has contacted DTSC about meeting to discuss the cleanup level for the ESD.
- KEMRON has submitted the Revised Final Technical Memorandum Lead Evaluation at Selected Sites.