














**EXPLANATION**

-  OU2 Extraction Wells
  -  Groundwater Collection Pipelines
  -  3Q2019 Backward Tracking Particle Pathlines
  -  OU2 New Ground Water Treatment Plant
  -  OU2 Landfill (Cells B-F)
  -  Roads
- Chemical of Concern (COC) Aquifer Cleanup Level (ACL) Exceedance Contour in  $\mu\text{g/L}$  for 3Q2019 OU2 A-Aquifer.
-  1,1-Dichloroethane (1,1-DCA)
  -  1,2-Dichloroethane (1,2-DCA)
  -  Tetrachloroethene (PCE)
  -  Trichloroethene (TCE)
  -  Vinyl Chloride (VC)



**OPERABLE UNIT 2  
GROUNDWATER TREATMENT SYSTEM**



January 31, 2020

