

**Analog Investigation  
SCA W140  
Seaside MRA, Former Fort Ord**

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: GENJIM/Exc. rd Grid Number 1 Date 4/13/08

Remarks: Swept Along Fence  
Line up to AREA where  
DBM WAS DONE.

Long cable was pulled  
From area.


Cable ran the Length  
of the AREA

APPROX: WT 1000 LBS

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		16
Scrap Detected	✓		16
Backhoe Digs	✓		1
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found : NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 4 LBS TRASH

Team Leader: Bruce Moe

Signature: Bruce M. Moe

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *GEN JIM/EVIL RD*

Grid Number

*2*

Date


*7/13/08*Remarks: *Swept Along Fence  
Line up to AREA where  
DBM WAS DONE.*

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>12</i>
Scrap Detected	✓		<i>12</i>
Backhoe Digs		✓	

Passed Inspection:

✓

Draw the approximate location(s) of OE items found *NONE:*

Southwest Corner

100' x 25' GRID

*TOTAL WT: 2 lbs scrap*

Team Leader:

*Bruce McG*

Signature:

*Bruce McG*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *GEN JIM/EV. rd*

Grid Number

*3*

Date

*7/13/08*

Remarks: *Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.*

### Results

Item

Yes

No

Qty

MEC Encountered

*✓*

MD Encountered

*✓*

Anomalies Detected

*✓*

*20*

Scrap Detected

*✓*

*20*

Backhoe Digs


*✓*

Passed Inspection:

*✓*

Draw the approximate location(s) of OE items found *NONE:*

*mostly trash from  
ROAD.*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 1 LB*

Team Leader:

*Bruce McG*

Signature:

*Bruce McG*



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *GEN JIM / Euc. rd*

Grid Number

*4*

Date


*4/13/08*Remarks: *Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.*

## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		
Scrap Detected	✓		
Backhoe Digs		✓	

Passed Inspection:

✓

Draw the approximate location(s) of OE items found *NONE**Trash!*

Southwest Corner

100' x 25' GRID

*TOTAL WT: 126*Team Leader: *Bruce Moe*

Signature:

*Bruce M. Moe*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *GEN JIM / Euc. rd*

Grid Number

*5*

Date

*4/13/08*

Remarks: *Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.*

### Results


Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>7</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>7</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

☒

Draw the approximate location(s) of OE items found

*Trash !*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 1/2 LB*

Team Leader:

*Bruce Moe*

Signature:

*Bruce M. Moe*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *GEN JIM / Euc. rd*

Grid Number

*6*

Date

*7/13/08*Remarks: *Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.*

## Results

Item

Yes

No

Qty

MEC Encountered

☒

MD Encountered

☒

Anomalies Detected

☒*19*

Scrap Detected

☒*19*


Backhoe Digs

☒

Passed Inspection:

☒

Draw the approximate location(s) of OE items found

*Trash!*

Southwest Corner

100' x 25' GRID

*WT: 2 Lbs*

Team Leader:

*Bruce Moe*

Signature:

*Bruce M. Moe*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: GEN JIM/Euc. rd Grid Number 7 Date 4/13/08


Remarks: Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		20
Scrap Detected	✓		20
Backhoe Digs			
Passed Inspection: ✓			

Draw the approximate location(s) of OE items found

Trash!



Southwest Corner

100' x 25' GRID

WT: 2 Lbs

Team Leader: Bruce McG

Signature: Bruce McG

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: GEN JIM / Euc. rd Grid Number B Date 4/13/08


Remarks: Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		12
Scrap Detected	✓		12
Backhoe Digs		✓	
Passed Inspection: ✓			

Draw the approximate location(s) of OE items found NONE

Trash !



Southwest Corner

100' x 25' GRID

WT: 126

Team Leader: Bruce McG

Signature: Bruce McG

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *GEN JIM/EVL RD*

Grid Number

*9*


Date

*4/13/08*Remarks: *Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.*

## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		5
Scrap Detected	✓		5
Backhoe Digs		✓	

Passed Inspection: ✓

Draw the approximate location(s) of OE items found *NONE*

Southwest Corner

100' x 25' GRID

*WT: 0 LBS*

Team Leader:

*Bruce McG*

Signature:

*Bruce McG*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: GEN JIM/EUC. rd Grid Number 40 Date 7/13/08


Remarks: Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		6
Scrap Detected	✓		6
Backhoe Digs		✓	
Passed Inspection: ✓			

Draw the approximate location(s) of OE items found NONE:

Small scrap/TRASH



Southwest Corner

100' x 25' GRID

WT: 1/4 LB

Team Leader: Bruce McG

Signature: Bruce McG

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: GEN JIM/EVL RD Grid Number 11 Date 7/13/08


Remarks: SWEEP ALONG FENCE LINE UP TO AREA WHERE DBM WAS DONE.

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found NONE

Trash. 1



Southwest Corner

100' x 25' GRID

WT: 1/2 LB

Team Leader: Bruce McG

Signature: Bruce McG



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Gen Jim/Exc. rd Grid Number 12 Date 4/13/08


Remarks: Swept Along Fence  
Line up to area where  
DBM WAS DONE.

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>8</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>8</u>
Backhoe Digs		<input checked="" type="checkbox"/>	
Passed Inspection:	<input checked="" type="checkbox"/>		

Draw the approximate location(s) of OE items found NONE

TRASH/debris!



Southwest Corner

100' x 25' GRID

WT: 1/2 Lbs

Team Leader: Bruce Nobe

Signature: Bruce N. Nobe

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *WOW AREA*Grid Number *1*Date *7-11-08***Remarks:**


*Area Full of Asphalt pieces  
AND Large Pipe buried  
through one spot.*

*Scraped area to remove  
"hot" soil.*

**Results**

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>15</i>
Scrap Detected	✓		<i>15</i>
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE FOUND.**TOTAL WT: 126*Team Leader: *Matt Lasehner*Signature: *Matt Lasehner*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number **2**Date **7-11-08**


Remarks:

ONE AREA HAD "HOT" SOIL  
SCRAPED area to clean

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓	✗	8
Scrap Detected	✓		8
Backhoe Digs	✓		1

Passed Inspection:

Draw the approximate location(s) of OE items found **NONE FOUND**

Southwest Corner

100' x 25' GRID

**TOTAL WT: 1/2 LB**Team Leader: **MATT LAUCHNOR**Signature: *Matt Lauchnor*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number **3**Date **7-11-08**


Remarks:

*25' from Fence x 100'  
LONG AREA.*

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>15</i>
Scrap Detected	✓		<i>15</i>
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE FOUND*

Southwest Corner

100' x 25' GRID

*TOTAL WT: 1/2 LB*Team Leader: *Matt Lavehner*Signature: *Matt Lavehner*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

4

Date

7-11-08

Remarks: 25' x 100' Long  
AREA ALONG FENCE.


## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		12
Scrap Detected	✓		12
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner


100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

MATT LAUCHNER

Signature:



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

5

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE.

## Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

7

Scrap Detected

✓

7


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND.



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

Matt Leuchow

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

6

Date

7-11-08

Remarks:

25' x 100' AREA ALONG  
FENCE.

Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

6

Scrap Detected

✓

6


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

Matt Larchner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

7

Date

7-11-08

Remarks:

25' x 100' AREA  
ALONG FENCE LINE  
G.T.M. BLVD.

Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

2

Scrap Detected

✓

2


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 0

Team Leader:

Matt Lauchner

Signature:



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

8

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE LINE

## Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

21

Scrap Detected

✓

21


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 166

Team Leader:

Matt Lauchner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

9

Date

7-11-08

Remarks: 25'X100' AREA  
ALONG FENCE LINE

## Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

9

Scrap Detected

✓

9


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/266

Team Leader:

Matt Lachner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

10

Date

7-11-08

Remarks: 25' x 100' AREA  
Along Fence Line

## Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

3

Scrap Detected

✓

3


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 0

Team Leader:

Matt Lavehner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

11

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE LINE

### Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

13

Scrap Detected

✓

13


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/2 LB

Team Leader:

Matt Karchner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

*12*

Date

*7-11-08*

Remarks:

*25' x 100' AREA  
Along Fence*

Results

Item

Yes

No

Qty

MEC Encountered

☒

MD Encountered

☒

Anomalies Detected

☒*10*

Scrap Detected


☒*10*

Backhoe Digs

☒

Passed Inspection:

Draw the approximate location(s) of OE items found

*NONE*

Southwest Corner


100' x 25' GRID

*TOTAL WT: 1/4 LB*

Team Leader:

*Matt Luchner*

Signature:



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

13

Date

7-11-08

Remarks: 25' x 100' AREA  
Along Force Line


## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 2 LBS

Team Leader:

Matt Haver

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

14

Date

7-11-08

Remarks:

25' x 100' AREA  
ALONG FENCE

Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

12

Scrap Detected

✓

12


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 1 LB

Team Leader:

Matt Lavehner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

15

Date

7-11-08

Remarks: 25' x 100'

Area Along Fence.

## Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

6

Scrap Detected

✓

6


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 Lb

Team Leader:

M. A. Louchner

Signature:



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

Grid Number

16

Date

7-11-08

Remarks:

Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

5

Scrap Detected

✓

5


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT : 0


Team Leader:

Matt Lavach

Signature:

W-140

30 JULY Analog  
29 grids



(GRIDS) 6-32 →

(GRIDS) 1-29

General Jim Moore Boulevard

SCA\_W040

SCA\_W132

SCA\_W005

SCA\_W048

SCA\_W133

SCA\_W140

SCA\_W125

SCA\_W162

SCA\_W039

WOW

SCA\_W140

SCA\_W016

SCA\_W017

SCA\_W134

SCA\_W048

SCA\_W003

SCA\_W165

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: N 140 Fence line Grid Number 1 Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Matt Lauchner

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY


Work Area: <u>W 140 Fenceline</u>	Grid Number <u>2</u>	Date <u>7-30-03</u>
-----------------------------------	----------------------	---------------------

Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	
Passed Inspection:			

Draw the approximate location(s) of OE items found



Team Leader: Matt Lavacher

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY


Work Area: <u>W 140 Fenceline</u>	Grid Number <u>3</u>	Date <u>7-30-08</u>
-----------------------------------	----------------------	---------------------

Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	
Passed Inspection:			

Draw the approximate location(s) of OE items found



Team Leader: Matt Lavach

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline

Grid Number 4

Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	2		12 lbs
Scrap Detected	2	<del>1</del>	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lauchner

Signature:

*[Handwritten Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W/40 Fenceline Grid Number 5 Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	4		11bs
Scrap Detected	4	5	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Team Leader:

*[Signature]*

Signature:

*[Signature]*



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: <u>W 140 Fenceline</u>	Grid Number <u>6</u>	Date <u>7-30-06</u>
-----------------------------------	----------------------	---------------------


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	3		.21bs
Scrap Detected	3	<del>4</del>	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Team Leader:

Matt Lanchester

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: <u>W 140 Fenceline</u>	Grid Number <u>7</u>	Date <u>7-30-08</u>
-----------------------------------	----------------------	---------------------


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	6		2 lbs
Scrap Detected	6	<del>7</del>	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Team Leader:

Matt Lauchner

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline

Grid Number

8

Date

7-30-08

Remarks:

### Results

Item

Yes

No

Qty

MEC Encountered

1

MD Encountered

1

Anomalies Detected

2

2165

Scrap Detected

2


1

Backhoe Digs

1

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lauchner

Signature:

[Signature]

# Weston Solutions, Inc.


## ANALOG SURVEY

Work Area: <u>W 14D Fenceline</u>	Grid Number <u>9</u>	Date <u>7-30-08</u>
-----------------------------------	----------------------	---------------------

Remarks:

Results			
Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	2		.21bs
Scrap Detected	2	3	
Backhoe Digs		/	
Passed Inspection:			

Draw the approximate location(s) of OE items found



Team Leader: Matthew Larcher

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W 140 Fenceline Grid Number 1D Date 7-30-08

Remarks:


Marker Left in place

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	3		9165
Scrap Detected	2	1	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 100' GRID

Team Leader:

Matt Larchner

Signature:

*[Handwritten Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY


Work Area: W 140 Fenceline Grid Number 11 Date 7-30-08

Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		1	
MD Encountered		1	
Anomalies Detected	2		5lbs
Scrap Detected	2	*	
Backhoe Digs		1	
Passed Inspection:			

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID  
100

Team Leader:

Matt Lachner

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline

Grid Number 12

Date 7-30-08

Remarks:


Asphalt and dirt pile  
in grid

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	4		4 lbs
Scrap Detected		1	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID  
100

Team Leader:

Matt Lachner

Signature:

*[Handwritten Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fence	Grid Number 13	Date <del>7-30-08</del> 7-30-08
-----------------------	----------------	---------------------------------


Remarks: 2 anomalies HOT Rock

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	4		2 lbs
Scrap Detected	2	1	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID  
100

Team Leader:

*[Signature]* A. V. Chene

Signature:

*[Signature]*



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W/40 Fenceline

Grid Number 14


Date 7-30-04

Remarks: 3 anomalies Hot rock

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	7		1165
Scrap Detected	4	2	
Backhoe Digs		/	
Passed Inspection:			

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lachner

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fence line

Grid Number 15

Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	15		4 lbs
Scrap Detected	15	2	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID  
100

Team Leader:

Matt Laverne

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area:

W140 Penelope

Grid Number

16

Date

7-30-06

Remarks:

Sampling well in grid

### Results

Item

Yes

No

Qty

MEC Encountered

MD Encountered

Anomalies Detected

12

.5 lbs


Scrap Detected

12

Backhoe Digs

Passed Inspection:

Draw the approximate location(s) of OE items found



Team Leader:

Matt Lauchner

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline Grid Number 17 Date 7-30-06


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	3		11bs
Scrap Detected	3	5	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader:

Matt Lachner

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY


Work Area: W140 Fonzehire Grid Number 16 Date 7-30-04

Remarks: concrete

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	3		2 lbs
Scrap Detected		/	
Backhoe Digs		/	
Passed Inspection:			

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader:

Matt Larcher

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W143 Fenceline

Grid Number 19

Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	2		2 lbs
Scrap Detected	2	<del>2</del>	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Team Leader:

*Matt Lechner*

Signature:

*[Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline Grid Number 20 Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lavender

Signature:



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fence line Grid Number 21 Date 7-30-08


Remarks: ~~W140~~

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	30		7165
Scrap Detected	30	3	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lavach

Signature:

[Signature]



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W/140 Fence line Grid Number 22 Date 7-30-08


Remarks: Hot rock 4 anomalies

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	4		1 lbs
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: Matt Lavender


Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY


Work Area: <u>W140</u>	Grid Number <u>23</u>	Date <u>7-30-08</u>		
Remarks: <del>Hot Rock</del> <u>15 anomalies Hot Rocks</u>	Results			
	Item	Yes	No	Qty
	MEC Encountered		/	
	MD Encountered		/	
	Anomalies Detected	<u>15</u>		<u>10 lbs</u>
	Scrap Detected		/	
	Backhoe Digs		/	
	Passed Inspection:			

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: <u>Matt Lechner</u>	Signature: 
----------------------------------	--

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline Grid Number 24 Date 7-30-08


Remarks: stones Debris

### Results

Item	Yes	No	Qty
MEC Encountered		<u>/</u>	
MD Encountered	<u>/</u>		<u>1</u>
Anomalies Detected	<u>2</u>		
Scrap Detected	<u>2</u>		
Backhoe Digs		<u>/</u>	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Matt Laucher

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Grid Number 25 Date 7-30-04


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected	10		2 lbs
Scrap Detected	10	<del>10</del>	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

*[Handwritten Signature]*

Signature:

*[Handwritten Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fence line Grid Number 26 Date 7-30-06

Remarks:

### Results

Item	Yes	No	Qty
------	-----	----	-----

MEC Encountered		/	
-----------------	--	---	--

MD Encountered		/	
----------------	--	---	--


Anomalies Detected		/	
--------------------	--	---	--

Scrap Detected		/	
----------------	--	---	--

Backhoe Digs		/	
--------------	--	---	--

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lauer

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W14D Fence line Grid Number 27 Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader:

Matt Larchner

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W14D Fence line Grid Number 245 Date 7-30-04


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Hauchner

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fence line Grid Number 29 Date 7-30-04


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Matt Lauchner

Signature:

[Signature]



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: W140 Fenceline Grid Number 30 Date 7-30-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		/	
MD Encountered		/	
Anomalies Detected		/	
Scrap Detected		/	
Backhoe Digs		/	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

St. Larchner

Signature:

[Signature]

Analof W-140  
July 31.

(GRIDS) 6-32 →

(GRIDS)  
1-29

General Jim Moore Boulevard

SCA\_W040

SCA\_W132

SCA\_W048

SCA\_W133

SCA\_W140

SCA\_W125

SCA\_W162

SCA\_W039

WOW

SCA\_W140

SCA\_W048

SCA\_W003


SCA\_W165

SCA\_W016

SCA\_W017

SCA\_W134








# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: <u>Seaside 2</u>	Grid Number <u>32</u>	Date <u>31 July 08</u>		
Remarks:	Results			
	Item	Yes	No	Qty
	MEC Encountered		<input checked="" type="checkbox"/>	
	MD Encountered		<input checked="" type="checkbox"/>	
	Anomalies Detected	<input checked="" type="checkbox"/>		<u>15</u>
	Scrap Detected	<input checked="" type="checkbox"/>		<u>15</u>
	Backhoe Digs		<input checked="" type="checkbox"/>	
	Passed Inspection: <u>yes</u>			

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: <u>Tony R Clark</u>	Signature: <u>T.R.C.</u>
----------------------------------	--------------------------

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2 Grid Number 31 Date 31 July 08

Remarks:


### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>7</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>7</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R. Clark

Signature:

T.R.C.

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2 Grid Number 30 Date 31 July 08


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		8
Scrap Detected	✓		8
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R Clark

Signature: T.R.C.

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2Grid Number 29Date 31 July 08


Remarks:

**Results**

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		8
Scrap Detected	✓		8
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R. Clark

Signature:

[Signature]



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2Grid Number 28Date 31 July 08


Remarks:

## Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>8</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>8</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Terry R. ClarkSignature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2Grid Number 27Date 31 July 08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		15
Scrap Detected	✓		15
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R ClarkSignature: Tony R Clark

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2Grid Number 26Date 7-31-08


Remarks:

**Results**

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		20
Scrap Detected	✓		20
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. ClarkSignature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 25

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>10</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>10</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Session 2

Grid Number 24

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		22
Scrap Detected	✓		22
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R Clark

Signature: JRC



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 23

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>14</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>14</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R. Clark

Signature:

T.R.C.

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Sesside 2Grid Number 22Date 7-31-08

Remarks:

Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

11

Scrap Detected

✓


11

Backhoe Digs

✓

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. ClarkSignature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 21

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		6
Scrap Detected	✓		6
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Scrs 2Grid Number 20Date 7-31-08


Remarks:

## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		7
Scrap Detected	✓		7
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R Clark

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2Grid Number 19Date 7-31-08


Remarks:

## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R ClarkSignature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Serside 2

Grid Number 18

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		30
Scrap Detected	✓		30
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 17

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>3</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>3</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R. Clark

Signature:

Tony R. Clark

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Scrub 2Grid Number 16Date 7-31-08

Remarks:

Results

Item

Yes

No

Qty

MEC Encountered

☒

MD Encountered

☒

Anomalies Detected

☒4

Scrap Detected

☒4


Backhoe Digs

☒

Passed Inspection:

yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R. Clark

Signature:

JRC



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 15

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		4
Scrap Detected	✓		4
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R Clark

Signature:

TRC

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2Grid Number 14Date 7-31-08

Remarks:

## Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

3

Scrap Detected

✓

3


Backhoe Digs

✓

Passed Inspection:

yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R ClarkSignature: TRC

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 13


Date 7-31-08

Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>9</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>9</u>
Backhoe Digs		<input checked="" type="checkbox"/>	
Passed Inspection: <u>yes</u>			

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 12

Date 7-31-08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		19
Scrap Detected	✓		19
Backhoe Digs	✓		1

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2

Grid Number 11


Date 7-31-08

Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		12
Scrap Detected	✓		12
Backhoe Digs		✓	
Passed Inspection: <u>yes</u>			

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tracy R. Clark

Signature:

TRC

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Senside 2Grid Number 10Date 7-31-08


Remarks:

## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		11
Scrap Detected	✓		11
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. ClarkSignature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *Seaside 2*

Grid Number *9*

Date *7-31-08*

Remarks:


*CW with propellant*

### Results

Item	Yes	No	Qty
MEC Encountered	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>1</i>
MD Encountered	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>8</i>
Scrap Detected	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>8</i>
Backhoe Digs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Signature:

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *Seaside 142*Grid Number *8*Date *7-31-08*


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>5</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>5</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

*Tony R. Clark*

Signature:

*T.R.C.*



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 1Grid Number 7Date 7-31-08


Remarks:

## Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		2
Scrap Detected	✓		2
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R Clark

Signature:

T.R.C.

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 1Grid Number 2Date 7-31-08


Remarks:

## Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>3</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>3</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

Tony R Clark

Signature:

TRC

ANA Log

1 Aug 08





# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Scrapped Grid Number 44 Date 1 Aug 08

Remarks:


40% of grid

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<u>4</u>
Scrap Detected	<input checked="" type="checkbox"/>		<u>4</u>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Scrside 2 Grid Number 43 Date 1 Aug 08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: *Seaside 2*

Grid Number *42*

Date *1 Aug 08*


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>7</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>7</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader:

*Tony R. Clark*

Signature:


*[Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: <i>Scarside 2</i>	Grid Number <i>41</i>	Date <i>1 Aug 08</i>		
Remarks:	Results			
	Item	Yes	No	Qty
	MEC Encountered		<input checked="" type="checkbox"/>	
	MD Encountered		<input checked="" type="checkbox"/>	
	Anomalies Detected	<input checked="" type="checkbox"/>		<i>6</i>
	Scrap Detected	<input checked="" type="checkbox"/>		<i>6</i>
	Backhoe Digs		<input checked="" type="checkbox"/>	
	Passed Inspection:			

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: *Tony R. Clark*

Signature: *[Signature]*

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: <u>Scrap Site 2</u>	Grid Number <u>40</u>	Date <u>1 Aug 08</u>
--------------------------------	-----------------------	----------------------


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		10
Scrap Detected	✓		10
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: <u>Tony R. Clark</u>	Signature: <u>[Signature]</u>
-----------------------------------	-------------------------------



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Scarp 2 Grid Number 39 Date 1 Aug 08

Remarks:


*Culvert in grid  
left in place*

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		11
Scrap Detected	✓		11
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2 Grid Number 38 Date 1 Aug 08

Remarks:


*Telephone pole anchor*

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		
Scrap Detected	<input checked="" type="checkbox"/>		
Backhoe Digs	<input checked="" type="checkbox"/>		

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2 Grid Number 37 Date 1 Aug 08

Remarks:


Buried cable

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		
Scrap Detected	<input checked="" type="checkbox"/>		
Backhoe Digs	<input checked="" type="checkbox"/>		<u>1</u>

Passed Inspection: yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: Tony R. Clark

Signature: [Signature]



# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Scarp 2 Grid Number 36 Date 1 Aug 08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		10
Scrap Detected	✓		10
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: Tony R. Clark

Signature: JRC

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Sesside 2 Grid Number 35 Date 1 Aug 08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		8
Scrap Detected	✓		8
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader:

Tony R. Clark

Signature:

[Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: Seaside 2 Grid Number 34 Date 1 Aug 08


Remarks:

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		15
Scrap Detected	✓		15
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: Tony R. Clark


Signature: [Signature]

# Weston Solutions, Inc.

## ANALOG SURVEY

Work Area: <u>Seaside 2</u>	Grid Number <u>33</u>	Date <u>1 Aug 08</u>		
Remarks:	Results			
	Item	Yes	No	Qty
	MEC Encountered		<input checked="" type="checkbox"/>	
	MD Encountered		<input checked="" type="checkbox"/>	
	Anomalies Detected	<input checked="" type="checkbox"/>		<u>20</u>
	Scrap Detected	<input checked="" type="checkbox"/>		<u>20</u>
	Backhoe Digs		<input checked="" type="checkbox"/>	
	Passed Inspection: <u>yes</u>			

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 25' GRID

Team Leader: <u>Tony R. Clark</u>	Signature: <u>[Signature]</u>
-----------------------------------	-------------------------------