MR Status Fort Ord MR BCT 9 October 2019

BLM AREA B

Security Measures and Outreach

- The website and kiosks were updated with current trail closure information on 7/3/2019.
- Boundary fence around Unit B was removed in September, after all planned subsurface removals within the unit was completed. Trails within Unit A and Unit B are closed.
- Roads are subject to temporary closure during subsurface removal operations.

Digital Geophysical Mapping (DGM)

• DGM in subsurface removal areas of Unit B roads was completed 9/24.

Subsurface MEC Removal

- All planned subsurface removals have been completed in:
 - o Units B-3E and B-3E-NE
 - o Units B-3W and C
 - o Unit B-2A
 - o Unit B
- Subsurface MEC removal on the 12-ft wide trail footprints has been completed on:
 - o Unit A: Trails 69, 67, 68, 65 and 66
- Subsurface removal on additional road segments is in progress. Unit B perimeter fence was removed. DGM was completed. Target reacquisition and intrusive investigation are in progress. Analog process will be used in DGM data gap areas.

IMPACT AREA

FIELD ACTIVITIES

Impossible Canyon Road and Wildcat Ridge Road Fuel Break Work

• Subsurface removal activities were completed 6/17. Fuel break markers were installed.

Fuel Breaks Additional Verification

- The Metal Mapper (MM) 2x2 dynamic survey was conducted from 10/22/2018 to 4/16/2019 (25.5 acres).
- 437 preliminary cued targets in 3 road grids were previously excavated (completed 1/10). This information will be used to refine the classification process.
- The MM 2x2 cued survey is complete in 81% of the work area as of 10/3. As of 10/3, 8,070 cued targets have been identified for intrusive investigation; 6,690 have been investigated.

Range 48 Northern Portion Near-surface MEC Removal

 Near-surface MEC removal (up to 6 inches in depth): 25 of 148 grids were completed from 1/15 to 2/28. Fieldwork was temporarily suspended due to habitat conservation requirements. Work resumed 6/12. Overall 84% complete as of 10/3. DGM will be conducted.

Target/Debris Disposal

- Demolition operation was conducted on 9/18 and 10/2. One is planned for 10/9.
- Nine off-site shipments of MD have been completed to date.

OTHER ACTIVITIES


Impact Area North Perimeter Fence Construction


Fence construction was completed on 8/12. Fuel break markers will be installed.


MMRP SITE SECURITY PROGRAM


Update for October 9, 2019 BCT


- Trespass Incident Reports
 - o Last 24 days (9/11/2019 10/4/2019): 1
 - On 10/2/2019 at 1:45 p.m. UXO crews discovered a bicyclist inside the Impact Area (Watkins Gate Road x Chinook Road). Kemron staff caught up to the bicyclist upon his exit from the Impact Area and gave him a warning. POMPD was contacted but did not send an officer.
 - o Year to Date: 29
- Munitions Incident Reports
 - o Last 24 days (9/11/2019 10/4/2019): 0
 - o Year to Date: 6
- Community Education Participants— Year to Date: 240
- Munitions Recognition and Safety Training Participants Year to Date: 247














Mag and Dig Ops MEC Removal Status