

Table 3.1
Rare Plant Survey Results Relative to 2006 Well Locations

Well Identification	Adjacent to Existing Road	2006 RP/HS Segment Identification	1998	2004	2005	2006
Wells Installed in 2006 Before the Rare Plant Survey						
EW-OU1-60-A	Yes	1	MS	---	n	n
EW-OU1-62-A	Yes	1	n	---	n	n
EW-OU1-63-A	Yes	1	n	---	n	n
EW-OU1-66-A	Yes	1	MS	---	n	n
MW-OU1-61-A	Yes	1	MS	---	n	n
MW-OU1-64-A1	Yes	1	n	---	n	n
MW-OU1-64-A2	Yes	1	n	---	n	n
MW-OU1-65-A	Yes	1	MS	---	n	n
MW-OU1-67-A	Yes	1	n	---	n	n
MW-OU1-68-A	Yes	1	n	---	n	n
Wells Installed in 2006 After the Rare Plant Survey						
EW-OU1-71-A	No	6	n	n	---	n
EW-OU1-72-A	No	7	n	n	n	n
IW-OU1-73-A	No	4	n	---	n	n
IW-OU1-74-A	Yes	4	n	---	n	n
MW-OU1-82-A	No	9	n	---	n	n
MW-OU1-83-A	No	8	n	n	n	n
MW-OU1-84-A	Yes	4	n	---	n	n
MW-OU1-85-A	No	7	n	n	n	n
MW-OU1-86-A	No	6	n	n	---	n
MW-OU1-87-A	Yes	3	n	n	n	n
MW-OU1-88-A	No	3	n	n	---	n

Notes:

--- not surveyed

EW - extraction well

IW - injection well

MS - Monterey spineflower

MW - monitoring well

n - area was surveyed; but no rare plants were detected.

RP/HS - rare plant/habitat survey