

**Analog Investigation**  
**SCA W140**  
**Seaside MRA, Former Fort Ord**



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION  
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R. Clark</i>	DATE	<i>25 July 08</i>
GRID ID	<i>DATA GAPS ALONG FENCELINE WITHIN ROADWAY ALIGNMENT W/140 MRS-1</i>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<i>Schonstedt</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)




UXO Technician Inspector Signature *[Signature]*

Date *25 July 08*

UXO QC Specialist Signature *[Signature]*

Date *25 July 08*

*DM Kear*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

*(2) Barbed wire 116 ←*



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION  
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>25 July 08</i>
GRID ID	<i>DATA GAPS ALONG FENCELINE WITHIN ROADWAY ALIGNMENT WITH MRS-2</i>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<i>Sch</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)




UXO Technician Inspector Signature *T.R. Clark* Date *25 July 08*

UXO QC Specialist Signature *D. Kean* Date *7/25/08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.  
*(3) wire clips 1462*



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION  
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<u>Tony R Clark</u>	DATE	<u>25 July 08</u>
GRID ID	<u>Data Gps Along Fence Line within Roadway Alignment w/40 MRS-3</u>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<u>Sch</u>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)




UXO Technician Inspector Signature

Date 25 July 08

UXO QC Specialist Signature

Date 25 July 08

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

- (1) Barbed wire 12b L
- (4) wire clips



QUALITY CONTROL (QC-3) ANALOG QC INSPECTION  
Seaside MRA, Former Fort Ord, CA

UXO TECHNICIAN NAME	<i>Tony R Clark</i>	DATE	<i>25 July 08</i>
GRID ID	<i>Data Gaps Along Fenceline within Roadway Alignment W140 MRS-4</i>		
SCA'S IN GRID			
INSTRUMENT(S) USED	<i>ScK</i>		

Indicate area inspected with analog instrument (grid is 100 ft x 100 ft)




UXO Technician Inspector Signature *[Signature]*

Date *25 July 08*

UXO QC Specialist Signature *[Signature]*

Date *25 July 08*

List any findings. GPS locations of MEC/MD. Add additional pages if needed.

*(2) wire chips 116 L*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: GEN JIM / EUC. rd Grid Number 2 Date 4/13/08


Remarks: *Swept along fence line up to area where DBM was done.*

*Long cable was pulled from area. Cable ran the length of the area*

*APPROX: WT 1000 LBS*

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		16
Scrap Detected	✓		16
Backhoe Digs	✓		1
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found : *NONE*



Southwest Corner 100' x 25' GRID

*TOTAL WT: 4 LBS TRASH*

Team Leader: Bruce Moe Signature: Bruce M. Moe

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *GEN JIM/EV. rd*

Grid Number *2*

Date *7/13/08*


Remarks: *Swept ALONG fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.*

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>12</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>12</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE:*



*TOTAL WT: 2 lbs scrap*

Team Leader: *Bruce McG*

Signature: *Bruce McG*

# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: *GEN JIM / Euc. rd*    Grid Number *3*    Date *7/13/08*

Remarks: *Swept Along Fence  
Line up to area where  
DBM was done.*

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>20</i>
Scrap Detected	✓		<i>20</i>
Backhoe Digs		✓	
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found *NONE:*

*mostly trash from  
Road.*



Southwest Corner      100' x 25' GRID

*TOTAL WT: 1 LB*

Team Leader: *Bruce McG*      Signature: *Bruce McG*



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *GEN JIM / Euc. rd*

Grid Number *4*

Date *4/13/08*

Remarks: *Swept ALONG FENCE  
LINE UP TO AREA WHERE  
DBM WAS DONE.*


Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		
Scrap Detected	<input checked="" type="checkbox"/>		
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE*

*Trash!*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 126*

Team Leader: *Bruce McG*

Signature: *Bruce McG*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *GEN JIM / Euc. rd*    Grid Number: *5*    Date: *4/13/08*

Remarks: *Swept along fence line up to area where DBM was done.*


**Results**

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		7
Scrap Detected	✓		7
Backhoe Digs		✓	

Passed Inspection: ✓

Draw the approximate location(s) of OE items found

*Trash!*



Southwest Corner    100' x 25' GRID

*TOTAL WT: 1/2 LB*

Team Leader: *Bruce Moore*

Signature: *Bruce Moore*

# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: GEN JIM / Euc. rd Grid Number 6 Date 7/13/08

Remarks: Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		19
Scrap Detected	✓		19
Backhoe Digs		✓	
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found

Trash!



Southwest Corner 100' x 25' GRID

WT: 2 Lbs

Team Leader: Bruce Moore

Signature: Bruce M. Moore

# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: GEN JIM / Euc. rd Grid Number 7 Date 7/13/08

Remarks: Swept ALONG FENCE LINE UP TO AREA WHERE DBM WAS DONE.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		20
Scrap Detected	✓		20
Backhoe Digs			
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found

Trash!



Southwest Corner 100' x 25' GRID

WT: 2 Lbs

Team Leader: Bruce McG Signature: Bruce McG

# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: GEN JIM / Euc. rd Grid Number B Date 4/13/08

Remarks: Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		12
Scrap Detected	✓		12
Backhoe Digs		✓	
Passed Inspection: ✓			

Draw the approximate location(s) of OE items found NONE

Trash!



Southwest Corner 100' x 25' GRID

WT: 126

Team Leader: Bruce McG

Signature: Bruce McG

# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: GEN JIM / Euc. rd Grid Number 9 Date 4/13/08

Remarks: Swept Along Fence  
LINE UP TO AREA WHERE  
DBM WAS DONE.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		5
Scrap Detected	✓		5
Backhoe Digs		✓	
Passed Inspection: ✓			

Draw the approximate location(s) of OE items found NONE



Southwest Corner 100' x 25' GRID

WT: 0 Lbs

Team Leader: Bruce Mac Signature: Bruce M. Mac

# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: GEN JIM/EUC. RD Grid Number 10 Date 4/13/08

Remarks: SWEEP ALONG FENCE LINE UP TO AREA WHERE DBM WAS DONE.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		6
Scrap Detected	✓		6
Backhoe Digs		✓	
Passed Inspection: ✓			

Draw the approximate location(s) of OE items found NONE:

Small scrap/trash



WT: 1/4 LB  
Team Leader: Bruce McG Signature: Bruce McG

# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: GEN JIM / EUC. RD Grid Number 19 Date 4/13/08

Remarks: Swept Along Fence Line up to area where DBM was done.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	
Passed Inspection:	✓		

Draw the approximate location(s) of OE items found NONE

Trash. 1



WT: 1/2 L6

Team Leader: Bruce Moe

Signature: Bruce M. Moe



# Weston Solutions, Inc.

# ANALOG SURVEY


Work Area: *Gen Jim/Eve rd* Grid Number *12* Date *4/13/08*

Remarks: *Swept along fence line up to area where DBM was done.*

Results			
Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>8</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>8</i>
Backhoe Digs		<input checked="" type="checkbox"/>	
Passed Inspection:	<input checked="" type="checkbox"/>		

Draw the approximate location(s) of OE items found *NONE*

*TRASH/debris!*



Southwest Corner 100' x 25' GRID

*WT: 1/2 Lbs*

Team Leader: *Bruce Nobe* Signature: *Bruce Nobe*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *WOW AREA*

Grid Number *1*

Date *7-11-08*

Remarks:


*Area full of asphalt pieces  
AND large pipe buried  
through one spot.  
  
Scraped area to remove  
"hot" soil.*

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>15</i>
Scrap Detected	✓		<i>15</i>
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE FOUND.*



TOTAL WT: *126*

Team Leader: *Matt Lasehner*

Signature: *Matt Lasehner*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number **2**

Date **7-11-08**

Remarks:


*ONE AREA HAD "HOT" SOIL  
SCRAPED AREA TO CLEAN*

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓	<i>J</i>	<i>8</i>
Scrap Detected	✓		<i>8</i>
Backhoe Digs	✓		<i>1</i>

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE FOUND*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 1/2 LB*

Team Leader: *Matt Lauchnor*

Signature: *Matt Lauchnor*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number **3**

Date **7-11-09**

Remarks:


*25' from Fence x 100'  
LONG AREA.*

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		15
Scrap Detected	✓		15
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE FOUND*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 4266*

Team Leader: *Matt Lovelace*

Signature: *Matt Lovelace*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

4

Date

7-11-08

Remarks: 25' x 100' Long  
AREA ALONG FENCE.


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		12
Scrap Detected	✓		12
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

MATT LAUCHNER

Signature:

Matt Lauchner

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

5

Date

7-11-08


Remarks: 25' x 100' AREA  
ALONG FENCE.

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		7
Scrap Detected	✓		7
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE FOUND.*



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

*Matt Lushon*

Signature:

*Matt Lushon*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

6

Date

7-11-08

Remarks:

25' x 100' AREA ALONG  
FENCE.

Results

Item

Yes

No

Qty

MEC Encountered

✓

MD Encountered

✓

Anomalies Detected

✓

6

Scrap Detected

✓

6


Backhoe Digs

✓

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

Matt Larchner

Signature:

Matt Larchner

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

7

Date

7-11-08

Remarks:

25' x 100' AREA  
ALONG FENCE LINE  
G.J.M. BLVD.


Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		2
Scrap Detected	✓		2
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 0

Team Leader:

Matt Lauchner

Signature:

Matt Lauchner



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

8

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE LINE


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		21
Scrap Detected	✓		21
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 166

Team Leader: Matt Lauchner

Signature:

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

9

Date

7-11-08

Remarks: 25' X 100' AREA  
ALONG FENCE LINE


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

*none found*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 1/266*

Team Leader:

*Matt Lavchner*

Signature:

*Matt Lavchner*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

10

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE LINE


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		3
Scrap Detected	✓		3
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE FOUND



Southwest Corner

100' x 25' GRID

TOTAL WT: 0

Team Leader:

Matt Lavehner

Signature:

Matt Lavehner

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

11

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE LINE


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		13
Scrap Detected	✓		13
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/2 Lb

Team Leader:

Matt Karchner

Signature:

Matt Karchner

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number *12*

Date *7-11-08*


Remarks: *25' x 100' AREA  
ALONG FENCE*

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>10</i>
Scrap Detected	✓		<i>10</i>
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found *NONE*



Southwest Corner

100' x 25' GRID

*TOTAL WT: 1/4 LB*

Team Leader: *Matt Luchner*

Signature: *Matt Luchner*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

13

Date

7-11-08

Remarks: 25' x 100' AREA  
ALONG FENCE LINE


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		9
Scrap Detected	✓		9
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 2 LBS

Team Leader:

MATT HANCOCK

Signature:

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

14

Date

7-11-08

Remarks:

25' x 100' AREA  
ALONG FENCE


Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		12
Scrap Detected	✓		12
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 1 LB

Team Leader:

MITT LAUGHED

Signature:

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

15

Date

7-11-08

Remarks: 25' x 100'  
AREA ALONG FENCE.


### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		6
Scrap Detected	✓		6
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found

NONE



Southwest Corner

100' x 25' GRID

TOTAL WT: 1/4 LB

Team Leader:

MARTIN LAUCHNER

Signature:



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number

*16*

Date

*7-11-08*

Remarks:

Results

Item

Yes

No

Qty

MEC Encountered

MD Encountered

Anomalies Detected

*5*

Scrap Detected


*5*

Backhoe Digs

Passed Inspection:

Draw the approximate location(s) of OE items found

*NONE*



Southwest Corner

100' x 25' GRID

*TOTAL WT : 0*

Team Leader:

*Matt Lovelace*

Signature:

*Matt Lovelace*