

**Analog Investigation  
Various SCAs  
Seaside MRA, Former Fort Ord**

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 3*      Grid Number *W014*      Date *7/25/2008*

Remarks:


*Fence & gate within grid. All anomalies detected <sup>were</sup> on <sup>the</sup> surface. No digging required.*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>27</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>27</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*



FIGM

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 3*

Grid Number *W057*

Date *7/25/2008*

Remarks:


*located*  
*Telephone pole ^ within*  
*grid. All anomalies*  
*detected were scrap*  
*& located on the surface.*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>15</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>15</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Handwritten Signature]*



W057

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 3*

Grid Number *W055*

Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Handwritten Signature]*



W 055

# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: *Seaside 3*      Grid Number *W143*      Date *7/25/2008*

Remarks:

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	
Passed Inspection:			


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*      Signature: *[Signature]*





W143

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 2*

Grid Number *W129*

Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Pass of Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature





W129

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 2*

Grid Number *W 158*

Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*

891M



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 2*

Grid Number *W161*

Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*

W161



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 2*

Grid Number *W159*

Date *7/25/2008*

Remarks:


*Electrical tower  
located adjacent to  
the grid.*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*





W159

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 2*      Grid Number *W041*      Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature:





M841

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: <sup>OK</sup> Seaside #2

Grid Number W125

Date 7/25/2008


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: Jack Kristensen

Signature: 



W125

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 1*

Grid Number *W162*

Date *7/25/2008*

Remarks:


*Fence located within grid.*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*



MI62

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 1*

Grid Number *W035*

Date *7/25/2008*

Remarks:


*Within one foot of fence.*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*



560M



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 1*      Grid Number *W037*      Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*



W037

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 1*      Grid Number *W130*      Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Handwritten Signature]*



W130

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 1*      Grid Number *W151*      Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	

Passed Inspection:


Draw the approximate location(s) of OE items found




Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature:





M151

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 1*

Grid Number *W123*

Date *7/25/2008*

Remarks:


*Electrical tower adjacent to the grids*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Pulse Inspection:


Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristenson*

Signature:







W123

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 4*      Grid Number *W122*      Date *7/25/2008*


Remarks:

Results

Item	Yes	No	Qty
MEC Items Encountered		<input checked="" type="checkbox"/>	
MD Items Encountered		<input checked="" type="checkbox"/>	
Airborne Items Detected		<input checked="" type="checkbox"/>	
Shovel Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	


Phase II Inspection:

Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*      Signature: *JK*



221M

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 4*      Grid Number *W118*      Date *7/25/2008*

Remarks:


*Mainly followed fence & gate. ~~#~~ Scrapped found on the surface no digging required, most likely dragged into the area when the fenced was moved.*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>2</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>2</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Signature]*



811M

# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: *Seaside 4*      Grid Number *119*      Date *7/25/2008*

Remarks:  
*Followed fence line.  
Fence located in this  
grid*

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	
Passed Inspection:			


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Jack Kristensen*      Signature: *[Signature]*

W11A



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 4*

Grid Number *W111*

Date *7/25/2008*


Remarks: *located  
Fence 1 within grid*

### Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected		<input checked="" type="checkbox"/>	
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

Signature: *[Handwritten Signature]*



1111



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 4 W074jm* Grid Number: *W074* Date: *7/25/04*

Remarks:


*Fence & gate located within grid. Scrap metal located on the surface. No digging required.*

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓	<del>✓</del>	<i>8</i>
Scrap Detected	✓	-	<i>8</i>
Backhoe Dig		✓	

Photo Inspection:


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: *Jack Kristensen*

*[Signature]*



Mexico

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *Seaside 4*

Grid Number: *W066*

Date: *7/25/2008*


Remarks:

Results:

Item	Yes	No	Qty
MBP (Plastic lined)		<input checked="" type="checkbox"/>	
MBP (Unplastic lined)		<input checked="" type="checkbox"/>	
Approx. # of items		<input checked="" type="checkbox"/>	
Number of items		<input checked="" type="checkbox"/>	
Backfill (Dip)		<input checked="" type="checkbox"/>	


Draw the approximate location(s) of OE items found:


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' (approx)

Team Leader: *Jack Kristensen*





Mobile

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number W039

Date 7-28

Remarks:


### Results

Item	Yes	No	Qty
MEC Encountered		X	
MD Encountered		X	
Anomalies Detected		X	
Scrap Detected		X	
Backhoe Digs		X	

Passed Inspection:

Draw the approximate location(s) of OE items found

2' x 14'



Team Leader:

*[Signature]*  
MATT LAUCHNER

Signature:

*[Signature]*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area:

Grid Number W124

Date 7-28

Remarks:


Results

Item	Yes	No	Qty
MEC Encountered		X	
MD Encountered		X	
Anomalies Detected		X	
Scrap Detected		X	
Backhoe Digs		X	

Passed Inspection:

Draw the approximate location(s) of OE items found

2' x 12'



Southwest Corner

100' x 25' GRID

Team Leader:

*[Handwritten Signature]*  
**MATT LAUCHNER**

Signature:

*[Handwritten Signature]*