## Analog Investigation Roadway Alignment Area West of General Jim Moore Blvd Seaside MRA, Former Fort Ord

## Weston Solutions, Inc.

## ANALOG SURVEY


Work Area: Seaside MRS Grid Number WOW Date 17 June 2008

Remarks:

White area indicates analog sweep area

| Results            |     |    |                 |
|--------------------|-----|----|-----------------|
| Item               | Yes | No | Qty             |
| MEC Encountered    |     | x  |                 |
| MD Encountered     |     | x  |                 |
| Anomalies Detected | x   |    | 75              |
| Scrap Detected     | х   |    | 15lb            |
| Backhoe Digs       |     | X  | With the second |

Draw the approximate location(s) of OE items found



Team Leader: Matt Lauchner

## **ANALOG SURVEY** Weston Solutions, Inc. 7.29.08 Work Area: WOW Grid Number Date Remarks: All DATA GAPS Results Yes No Qty Item FOR WOW AREA. MEC Encountered MD Encountered 3 Anomalies Detected 3 Scrap Detected Backhoe Digs Passed Inspection: Draw the approximate location(s) of OE items found: NONE FOOND TOTAL DIGS 3.

Southwest Corner

Team Leader: JACK KUSTENSEN

Signature:

100' x 25' GRID

