

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number W146

Date 8/7/08

Remarks:

AREA IS CLEAN  
NO CONTACTS.

Results

Item	Yes	No	Qty
------	-----	----	-----

MEC Encountered		✓	
-----------------	--	---	--

MD Encountered		✓	
----------------	--	---	--


Anomalies Detected		✓	
--------------------	--	---	--

Scrap Detected		✓	
----------------	--	---	--

Backhoe Digs		✓	
--------------	--	---	--

Passed Inspection: ✓

Draw the approximate location(s) of OE items found



Southwest Corner


100' x 25' GRID

Team Leader:

Matthew Lauchner

Signature:

N →



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *SEA-1*

Grid Number *W134*

Date *Sept 8, 08*

Remarks:

*DATA GAP IS SIDE OF SAND HILL.*


*Scrap - cans, wire, nails, fence posts*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		<i>67</i>
Scrap Detected	<input checked="" type="checkbox"/>		<i>67</i>
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 25' GRID

Team Leader: *Tony R. Clark*

Signature: *[Signature]*

# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: SEA-4      Grid Number: <sup>A2</sup> W119      Date: 8 Sep 08

Remarks: map 45  
Scrap - small pieces at metal

Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		7
Scrap Detected	✓		7
Backhoe Digs		✓	
Passed Inspection: <i>yes</i>			

Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Tony R. Clark*      Signature: *T.R. Clark*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-4

Grid Number: <sup>A30</sup> W113

Date 8 Sep 08

Remarks: Map 42


Scrap small pieces of metal

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		2
Scrap Detected	✓		2
Backhoe Digs		✓	

Passed Inspection: ✓

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID


Team Leader: Tony Clark

Signature: [Signature]

~~W077~~  
✓W113

~~Student~~

SEAS



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-4

Grid Number: <sup>A69</sup> W070

Date 8 Sep 08


Remarks: Map 37  
Scrap Links

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		37
Scrap Detected	✓		37
Backhoe Digs		✓	

Passed Inspection: yes


Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: Tony R. Clark

Signature: [Signature]



WB70 ✓  
SER 4



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1      Grid Number: <sup>A43</sup>W037      Date: 8 Sept 08


Remarks: Map Page 9  
Sift Area  
Very heavy contamination of  
links + blanks

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		
Scrap Detected	✓		
Backhoe Digs		✓	

Passed Inspection:

Draw the approximate location(s) of OE items found




Southwest Corner      100' x 100' GRID

Team Leader: *[Signature]*      Signature: *[Signature]*

WD37 ✓

SEAL

~~Can be done if ~~done~~  
Surveyed w/ EM61 a/b  
done~~



sits in previous  
4' deep excavation

# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: SEA-4      Grid Number: <sup>A 73</sup> W066      Date: 8 Sep 08

Remarks: Map 36  
MO- Empty brass casings  
Scrap links

Results			
Item	Yes	No	Qty
MEC Encountered			
MD Encountered	✓		4
Anomalies Detected	✓		7
Scrap Detected	✓		3
Backhoe Digs		✓	
Passed Inspection: ✓			


Draw the approximate location(s) of OE items found



Southwest Corner      100' x 100' GRID

Team Leader: *Tony R. Clark*      Signature: *[Signature]*

Wobb ✓



SEAT 4



# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: SEA-3      Grid Number: <sup>A26</sup> W062      Date: 8 Sep 08

Remarks: Map 33  
Scrap misc metal debris  
1 large chunk of steel.

Results			
Item	Yes	No	Qty
MEC Encountered		✓	✓
MD Encountered		✓	
Anomalies Detected	✓		29
Scrap Detected	✓		29
Backhoe Digs		✓	
Passed Inspection: <i>yes</i>			

Draw the approximate location(s) of OE items found




Southwest Corner      100' x 100' GRID

Team Leader: *Tony R Clark*

Signature: *[Signature]*

SEAS



11062 ✓

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number: <sup>A18</sup> W040

Date

8. Sep 08

Remarks:

Map Page -19


Scrap nails, wire, bolts, nuts

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		17
Scrap Detected	✓		17
Backhoe Digs		✓	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 100' GRID

Team Leader:

*Tony R. Clark*

Signature:

*Tony R. Clark*

SEA 1

W040





# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number: <sup>A47</sup> W020

Date 8 Sep 08

Remarks: Map Page 15

S:fr area

MD- Brass- expended


Scrap Links

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered	✓	.	2
Anomalies Detected	✓		4
Scrap Detected	✓		✓
Backhoe Digs		✓	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: *Tony R. Clark*

Signature: *[Signature]*

W020

SEA 1



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number: <sup>A 41</sup> W022

Date 8 Sep 08

Remarks: Map Page 10


Scrap Nails & rebar

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		5
Scrap Detected	✓		5
Backhoe Digs		✓	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found



Southwest Corner 100' x 100' GRID

Team Leader: *Tony R Clark*

Signature: *JRL*

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number: <sup>A29</sup> W146

Date 8 Sep 08


Remarks: Map Page 3  
Md - Expanded blanks only  
Scrap wire

### Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered	✓		6
Anomalies Detected	✓		10
Scrap Detected	✓		4
Backhoe Digs		✓	

Passed Inspection: yes

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader: Tony R Clark

Signature: [Signature]

with

SEA



# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number: <sup>A28</sup> W155

Date: <sup>8</sup> Sep 08

Remarks:


*Map Page 3*

Results

Item	Yes	No	Qty
MEC Encountered		<input checked="" type="checkbox"/>	
MD Encountered		<input checked="" type="checkbox"/>	
Anomalies Detected	<input checked="" type="checkbox"/>		1
Scrap Detected		<input checked="" type="checkbox"/>	
Backhoe Digs		<input checked="" type="checkbox"/>	

Passed Inspection: *yes*

Draw the approximate location(s) of OE items found




Southwest Corner 100' x 100' GRID

Team Leader:

*Tony R. Clark*

Signature:

*[Signature]*



MISS ✓  
SEA ✓

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-1

Grid Number: <sup>A19</sup> W149

Date

8 Sep 08

Remarks:

Map Page - 1


Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected		✓	
Scrap Detected		✓	
Backhoe Digs		✓	

Passed Inspection:

yes

Draw the approximate location(s) of OE items found



Southwest Corner

100' x 100' GRID

Team Leader:

Tony R. Clark


Signature:





W149 ✓

SEPA1



# Weston Solutions, Inc.


# ANALOG SURVEY

Work Area: SEA-1      Grid Number: <sup>A20</sup>W030      Date: 8 Sep 08

Remarks: Map Page 1  
Scrap = Wire


Results			
Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		1
Scrap Detected	✓		1
Backhoe Digs		✓	
Passed Inspection: Yes			

Draw the approximate location(s) of OE items found




Southwest Corner      100' x 100' GRID

Team Leader: Tony R. Clark      Signature: [Signature]



W020 ✓

SEA 1



View Analog GPS

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-2

Grid Number W160

Date 9-23-8


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		4
Scrap Detected	✓	①	
Backhoe Digs		✓	

Passed Inspection: Yes

Draw the approximate location(s) of OE items found



~~SCOUT WEST CO. INC.~~

~~002222 CR15~~

Team Leader: Matt Larchner

Signature: Matt Larchner

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: SEA-2

Grid Number W160

Date 9-23-08

Remarks:


Hot soil noted  
by circle

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		25
Scrap Detected	✓		
Backhoe Digs	✓		

Passed Inspection: ✓

Draw the approximate location(s) of OE items found



Southwest Corner

100 X 100 GRID

Team Leader: Matt Lawchner

Signature: [Handwritten Signature]

# Weston Solutions, Inc.

# ANALOG SURVEY

Work Area: *SEA-2*

Grid Number *W160*

Date *9-23-8*


Remarks:

Results

Item	Yes	No	Qty
MEC Encountered		✓	
MD Encountered		✓	
Anomalies Detected	✓		<i>15</i>
Scrap Detected	✓		
Backhoe Digs		✓	

Passed Inspection: ✓

Draw the approximate location(s) of OE items found



*subplots/area*

*000205/CRB*

Team Leader: *MATT Lowchaver*

Signature: *Matt*