









UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 13 2008									
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA points		REPORT NO 13135.004.001-QC 018									
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean										
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)								
					0.00								
WORK PERFORMED TODAY													
<p>Conducted Quality Assurance operations with FOR A's 3rd party QA Jesse Sipult of SCA points throughout Seaside 1-4.</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Seaside 1</td> <td>10,26,38,45,92,115,128,135,144,152,155,162,172,177,196,203,205,215,222,240</td> </tr> <tr> <td>Seaside 2</td> <td>247,254,269,284,290,297,306</td> </tr> <tr> <td>Seaside3</td> <td>331,354,360</td> </tr> <tr> <td>Seaside 4</td> <td>379,392,407,438,457,488,516,521,526,532</td> </tr> </table>						Seaside 1	10,26,38,45,92,115,128,135,144,152,155,162,172,177,196,203,205,215,222,240	Seaside 2	247,254,269,284,290,297,306	Seaside3	331,354,360	Seaside 4	379,392,407,438,457,488,516,521,526,532
Seaside 1	10,26,38,45,92,115,128,135,144,152,155,162,172,177,196,203,205,215,222,240												
Seaside 2	247,254,269,284,290,297,306												
Seaside3	331,354,360												
Seaside 4	379,392,407,438,457,488,516,521,526,532												
 _____ UXOQCS Donald Kean				13 June 2008 _____ DATE									



UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 11 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygons in the Pink line		REPORT NO 13135.004.001-QC 016	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>Conducted Quality Control operations of SCA Polygons along the Pink line.</p> <p>W48 94 anomalies</p> <p>Total number of anomalies 94</p>					
 _____ UXOQCS Donald Kean				 _____ DATE	


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 10 2008	
TITLE AND LOCATION		REPORT NO			
ESCA No. W9128F-07-2-01621		Special Case Area Polygons and points Seaside 1 and 4		13135.004.001-QC 015	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>Quality Control operations of SCA Polygons and points were conducted Seaside 1 and 4</p> <p>Total number of anomalies 104</p>					
 _____ UXOQCS Donald Kean				06/10/08 _____ DATE	


UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE June 09 2008	
TITLE AND LOCATION		REPORT NO			
ESCA No. W9128F-07-2-01621 Special Case Area points Seaside 2,3,4		13135.004.001-QC 014			
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> : </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> </div> <div style="border: 1px solid black; padding: 5px;"> Quality Control operations of SCA points were conducted throughout Seaside 2, 3 and 4 Total number of anomalies 88 </div>					
 UXOQCS Donald Kean				06/09/08 DATE	


UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE June 06 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points Seaside 1-4		REPORT NO 13135.004.001-QC 013	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<p>Quality Control operations of SCA points were conducted throughout Seaside 1-4</p> <p>Total number of anomalies 123</p>					
 UXOQCS Donald Kean				 DATE	

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE June 05 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points and SCA points		REPORT NO 13135.004.001-QC 012	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<p>Quality Control operations were conducted in the following Polygon Special Case Areas (SCA);</p> <p>W166 4 anomalies; W114 28 anomalies; W110 10 anomalies; and WOW 166 anomalies</p> <p>This is the second time anomalies have been investigated in these Polygons</p> <p>Seaside SCA points 51 anomalies.</p> <p>Total number of anomalies 259</p>					
 UXOQCS Donald Kean				06/05/08 DATE	


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 04 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points		REPORT NO 13135.004.001-QC 011	
CONTRACTOR <div style="text-align: center;">Weston Solutions, Inc.</div>			UXOQCS <div style="text-align: center;">Donald Kean</div>		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; height: 20px; margin-bottom: 10px;"></div> <p>There were no Quality Control operations conducted today.</p> <p>Conducted data verification of anomalies dug and Quality Control checked.</p>					
<div style="display: flex; justify-content: space-between; align-items: flex-end;"> <div style="text-align: center;">  <hr style="width: 100%;"/> UXOQCS Donald Kean </div> <div style="text-align: center;">  <hr style="width: 100%;"/> DATE </div> </div>					


UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE June 03 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points in W078,W141,W145,W160 and SEA-2 A32 SCA pts		REPORT NO 13135.004.001-QC 010	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>Quality Control checks were conducted in the following SCA polygons:</p> <p>W078 16 Anomalies; W141 120 Anomalies; W145 4 Anomalies; W158 25 Anomalies W160 78 Anomalies; and SEA-2 A32 SCA points 257 and 258</p> <p>Total number of points checked 245</p>					
 UXOQCS Donald Kean				03 June 2008 DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 02 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points in the WOW		REPORT NO 13135.004.001-QC 009	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; width: 100%; height: 20px; margin-bottom: 10px;"></div> <p>There was no Quality Control field operations conducted today.</p> <p>Cross checked QC dig log book with daily dig sheets</p>					
 UXOQCS Donald Kean				<div style="text-align: right;">02 June 2008</div> DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE May 30 2008						
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points in the WOW		REPORT NO 13135.004.001-QC 008						
CONTRACTOR <div style="text-align: center;">Weston Solutions, Inc.</div>			UXOQCS <div style="text-align: center;">Donald Kean</div>							
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)					
				PRECIP (IN) <div style="text-align: center;">0.00</div>						
WORK PERFORMED TODAY										
<div style="margin-bottom: 10px;">:</div> <table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <tr> <td style="width: 20%; height: 20px;"></td> <td style="width: 20%; height: 20px;"></td> <td style="width: 20%; height: 20px;"></td> <td style="width: 20%; height: 20px;"></td> <td style="width: 20%; height: 20px;"></td> </tr> </table> <p>Quality Control checks were conducted in the Wow and W160 today.</p> <p>Total numbers of anomalies checked were: 335 W160 7anomalies, WOW 328 anomalies. For details of results check dig sheets for 5/30/08</p>										
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> <div style="font-size: 1.2em; font-family: cursive;">30 May 08</div> DATE </div> </div>										

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE May 29 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Polygon points in the WOW		REPORT NO 13135.004.001-QC 007	
CONTRACTOR <div style="text-align: center;">Weston Solutions, Inc.</div>			UXOQCS <div style="text-align: center;">Donald Kean</div>		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECP (IN) 0.00	
WORK PERFORMED TODAY					
<div style="margin-bottom: 10px;">:</div> <div style="border: 1px solid black; height: 20px; width: 100%; margin-bottom: 10px;"></div> <p>Quality Control checks were conducted in the Wow today.</p> <p>Total numbers of anomalies checked were: 170</p>					
<div style="display: inline-block; text-align: left;"> _____ UXOQCS Donald Kean </div>				<div style="display: inline-block; text-align: left;"> _____ DATE </div>	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE May 28 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Points- Seaside #1		REPORT NO 13135.004.001-QC 006	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; width: 100%; height: 100%;"></div> <p>There was no QC-1 conducted today.</p>					
 _____ UXOQCS Donald Kean				28 May 08. _____ DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE May 27 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Points- Seaside #1		REPORT NO 13135.004.001-QC 005	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; width: 100%; height: 20px; margin-bottom: 10px;"></div> <p>The following SCA Polygon anomalies were QC checked today</p> <p>W160 65 Anomalies W114 28 Anomalies W15 27 Anomalies W 166 6 Anomalies</p> <p>Total SCA Polygon anomalies cleared 126</p>					
 UXOQCS Donald Kean				27 May 08 DATE	

UXO QUALITY CONTROL REPORT

(ATTACH ADDITIONAL SHEETS IF NECESSARY)

DATE May 23 2008

ESCA No. W9128F-07-2-01621

TITLE AND LOCATION

Special Case Area Points- Seaside #1

REPORT NO 13135.004.001-QC 004

CONTRACTOR

Weston Solutions, Inc.

UXOQCS

Donald Kean

EQUIPMENT USED
EM-41 CART
SCHONSTEDT

WEATHER
SUNNY/CLOUDY

MAX TEMP (F)	MIN TEMP (F)	PRECIP (IN)
		0.00

WORK PERFORMED TODAY

The following SCA Polygon anomalies were QC checked today

W160 62 Anomalies

W158 24 Anomalies

Total SCA Polygon anomalies cleared 86
See attached sheet for anomaly numbers.

Also the following SCA points in A32 Seaside 2 were QC checked and cleared:

SCA Pt 264 (9413)

SCA Pt 259 (9410)

SCA Pt 263 (9412)

SCA Pt 260 (9411)

UXOQCS
Donald Kean

27 May 08
DATE

UXO QUALITY CONTROL REPORT

(ATTACH ADDITIONAL SHEETS IF NECESSARY)

DATE May 22 2008

ESCA No. W9128F-07-2-01621

TITLE AND LOCATION
Special Case Area Points- Seaside #1

REPORT NO 13135.004.001-QC 003

CONTRACTOR

Weston Solutions, Inc.

UXOQCS

EQUIPMENT USED
EM-61 CART
SCHONSTEDTWEATHER
SUNNY/CLOUDY

Donald Kean


MAX TEMP (F)	MIN TEMP (F)	PRECIP (IN)
67	52	0.00

WORK PERFORMED TODAY


The following SCA Polygon anomalies were QC checked today


W110 37 anomalies
W090 4 anomalies
W091 18 anomalies
W68 14 anomalies
W159 6 anomalies

Total SCA polygon Anomalies cleared 79
See attached sheet for anomaly numbers


UXOQCS
Donald Kean

23 May 2008
DATE

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE May 21 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Points- Seaside #1		REPORT NO 13135.004.001-QC 002	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F) 61	MIN TEMP (F) 53
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<div style="border: 1px solid black; width: 100%; height: 15px; margin-bottom: 10px;"></div> <p>There were no SCA points Quality control checked today. Bill Raasch was escorting the dirt stabilization crew.</p>					
 _____ UXOQCS Donald Kean				22 May 08 _____ DATE	

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE May 20 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Special Case Area Points- Seaside #1		REPORT NO 13135.004.001-QC 001	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F) 67	MIN TEMP (F) 52
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
The following SCA Points in Seaside 1 were Quality Control checked with the following results:					
SCA Pt-9464-Passed SCA Pt-9464-Passed SCA Pt-6466-Passed SCA Pt-9469-Passed SCA Pt-9061-Passed SCA Pt-9463-Passed SCA Pt-9217-Passed SCA Pt-9467-Passed SCA Pt-9468-Passed SCA Pt-9294-Passed SCA Pt-9295-Passed SCA Pt-9296-Passed SCA Pt-9297-Passed SCA Pt-9298-Passed SCA Pt-9378-Passed SCA Pt-9029-Passed SCA Pt-9008-Passed SCA Pt-9379-Passed SCA Pt-9380-Passed SCA Pt-9381-Passed SCA Pt-9382-Passed SCA Pt-9009-Passed SCA Pt-9496-Passed SCA Pt-9497-Passed SCA Pt-9088-Passed	SCA Pt-9087-Passed SCA Pt-9343-Passed SCA Pt-9344-Passed SCA Pt-9345-Passed SCA Pt-9346-Passed SCA Pt-9347-Passed SCA Pt-9498-Passed SCA Pt-9499-Passed SCA Pt-9422-Passed SCA Pt-9506-Passed SCA Pt-9086-Passed SCA Pt-9420-Passed SCA Pt-9421-Passed SCA Pt-9534-Passed SCA Pt-9065-Passed SCA Pt-9066-Passed SCA Pt-9067-Passed SCA Pt-9068-Passed SCA Pt-9069-Passed SCA Pt-9070-Passed SCA Pt-9071-Passed SCA Pt-9072-Passed SCA Pt-9073-Passed SCA Pt-9074-Passed SCA Pt-9075-Passed	SCA Pt-9076-Passed SCA Pt-9390-Passed SCA Pt-9391-Passed SCA Pt-9493-Passed SCA Pt-9010-Passed SCA Pt-9219-Passed SCA Pt-9220-Passed SCA Pt-9221-Passed SCA Pt-9222-Passed SCA Pt-9223-Passed SCA Pt-9224-Passed SCA Pt-9225-Passed SCA Pt-9226-Passed SCA Pt-9227-Passed SCA Pt-9228-Passed SCA Pt-9230-Passed SCA Pt-9091-Passed SCA Pt-9233-Passed SCA Pt-9500-Passed SCA Pt-9501-Passed SCA Pt-9218-Passed SCA Pt-9229-Passed SCA Pt-9231-Passed SCA Pt-9232-Passed SCA Pt-9234-Passed	SCA Pt-9235-Passed SCA Pt-9236-Passed SCA Pt-9237-Passed SCA Pt-9502-Passed SCA Pt-9001-Passed SCA Pt-9052-Passed SCA Pt-9503-Passed SCA Pt-9053-Passed SCA Pt-9348-Passed SCA Pt-9445-Passed SCA Pt-9446-Passed SCA Pt-9447-Passed SCA Pt-9448-Passed SCA Pt-9449-Passed SCA Pt-9450-Passed SCA Pt-9022-Passed SCA Pt-9023-Passed SCA Pt-9062-Passed SCA Pt-9470-Passed SCA Pt-9019-Passed SCA Pt-9094-Passed		
Total SCA points cleared 96					
 UXOQCS Donald Kean				21 May 08 DATE	

UXO QUALITY CONTROL REPORT

(ATTACH ADDITIONAL SHEETS IF NECESSARY)

DATE July 30 2008

ESCA No. W9128F-07-2-01621

TITLE AND LOCATION

Fort Ord Seaside 1-4 SCA Polygons

REPORT
NO

13135.004.001-QC 054

CONTRACTOR

Weston Solutions, Inc.

UXOQCS

Donald Kean

EQUIPMENT USED
EM-61 CART
SCHONSTEDTWEATHER
SUNNY/CLOUDY

MAX TEMP (F)

MIN TEMP (F)

PRECIP (IN)

0.00

WORK PERFORMED TODAY

:

No QC-1 operations were conducted today.
Data input into PDA's and dig sheet verification

UXOQCS
Donald Kean

DATE

UXO QUALITY CONTROL REPORT

(ATTACH ADDITIONAL SHEETS IF NECESSARY)

DATE July 29 2008

ESCA No. W9128F-07-2-01621

TITLE AND LOCATION
Fort Ord Seaside 1-4 SCA Polygons

REPORT NO 13135.004.001-QC 053

CONTRACTOR

Weston Solutions, Inc.

UXOQCS

Donald Kean

EQUIPMENT USED
EM-61 CART
SCHONSTEDT

WEATHER
SUNNY/CLOUDY

MAX TEMP (F)

MIN TEMP (F)

PRECIP (IN)

0.00


WORK PERFORMED TODAY

No QC-1 operations were conducted today.
Data input into PDA's and dig sheet verification


UXOQCS
Donald Kean


DATE

29 July 08.

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 28 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 052	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN)	0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; width: 100%; height: 20px; margin-bottom: 10px;"></div> <p>No QC-1 operations were conducted today. Data input into PDA's and dig sheet verification</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 28 July 08 _____ DATE </div> </div>					

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 25 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 051	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<div style="border: 1px solid black; width: 100%; height: 100%; position: relative;"> <div style="position: absolute; top: 0; left: 0; width: 100%; height: 100%; background-color: #f0f0f0; border: 1px solid black;"></div> <div style="position: absolute; top: 10px; left: 10px; width: 80%; height: 80%; border: 1px solid black;"></div> </div> <p>No QC-1 operations were conducted today. Data input into PDA's and dig sheet verification.</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;"> <div style="border-top: 1px solid black; width: 100%;"></div> UXOQCS Donald Kean </div> <div style="text-align: center;"> <div style="border-top: 1px solid black; width: 100%;"></div> DATE </div> </div>					


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 24 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 050	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted today in SCA polygon W140.</p> <p>Quality Assurance with Jesse Sipult and Dan McKinnon from ERRG of the data gap of the WOW, see attached map.</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 24 July 08 _____ DATE </div> </div>					







THIS AREA COULD
NOT BE MAPPED BY
BED. SO MAG AND DIG
OPERATIONS WERE
CONDUCTED IN THIS AREA.



ON 24 JULY 2008
FORA 3rd PARTY QA personnel from ERRG
conducted Quality Assurance of the "MAG & DIG" area.


D. Kean
D. Kean
LXOQCS
24 July 2008


UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 22 2008	
TITLE AND LOCATION		REPORT NO			
ESCA No. W9128F-07-2-01621 Fort Ord Seaside 1-4 SCA Polygons		13135.004.001-QC 048			
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W074; W034; W123; and W140</p>					
 UXOQCS Donald Kean				22 July 08 DATE	


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 21 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 047	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W018; W111; W132; W157; and W161</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;">  _____ DATE </div> </div>					


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 20 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 046	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons: W048</p> <p>QC-3 operations have been completed for Seaside 1 and is now ready for QA.</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;">  _____ DATE </div> </div>					


UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 19 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 045	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons: W140</p>					
 UXOQCS Donald Kean				 DATE 19 July 08	


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 18 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 044	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W005; W37; W140; W141; W161; W048; W125; W127; W128; W129; and W160</p>					
 UXOQCS Donald Kean				18 July 08 DATE	


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 17 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 043	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				0.00	PRECIP (IN)
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W48; W57; W122; W131; W132; W133; W134; W138; and W18</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 17 July 08 _____ DATE </div> </div>					


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 16 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 042	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W11; W35; W47; W48; W87; W125; W126; W127; W128; W129; W157; and W160</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 16 July 08 _____ DATE </div> </div>					


UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 15 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 041	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <ul style="list-style-type: none"> W14; W41; W42; W43; W45; W46; W48; W49 W55; W67; W101; W111; W112; W118; W119; W120; W124; W131; W142; W143; W162; W163; W164 					
 _____ UXOQCS Donald Kean				15 July 2008 _____ DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 14 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 040	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W003; W056; W057; W135; W066; W122; and W080</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 14 July 2008 _____ DATE </div> </div>					

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 13 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 039	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W005; W34; W35; W37; W130; and W55.</p> <p>Also QC-1 was conducted on SCA points in Seaside 4.</p>					
 _____ UXOQCS Donald Kean				7/13/2008 _____ DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 12 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons		REPORT NO 13135.004.001-QC 038	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W74; W58; W59; and W87.</p>					
 _____ UXOQCS Donald Kean				07/12/2008 _____ DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 11 2008	
TITLE AND LOCATION		REPORT NO			
ESCA No. W9128F-07-2-01621 Fort Ord Seaside 1-4 SCA Polygons and points		13135.004.001-QC 037			
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygon: W160.</p> <p>QC-1 conducted on SCA point 281 in Seaside 2</p>					
 _____ UXOQCS Donald Kean				7/11/2008 _____ DATE	

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 10 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 036	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 operations were conducted in the following SCA polygons:</p> <p>W48; W123; W112; W151; W152; W067; W087; and W160.</p> <p>QC-1 conducted on SCA points 173 and 174 in Seaside 1</p> <p>QC seed -ESCA-SEA-002 was recovered by the dig team in SCA polygon W160</p>					
 _____ UXOQCS Donald Kean				07/10/08 _____ DATE	

UXO QUALITY CONTROL REPORT

(ATTACH ADDITIONAL SHEETS IF NECESSARY)

DATE July 09 2008

ESCA No. W9128F-07-2-01621

TITLE AND LOCATION
Fort Ord Seaside 1-4 SCA Polygons

REPORT NO 13135.004.001-QC 035

CONTRACTOR

Weston Solutions, Inc.

UXOQCS

Donald Kean

EQUIPMENT USED
EM-61 CART
SCHONSTEDT

WEATHER
SUNNY/CLOUDY

MAX TEMP (F)

MIN TEMP (F)

PRECIP (IN)

0.00


WORK PERFORMED TODAY


QC-1 operations were conducted in the following SCA polygons:
W124;
W48; and
W74


UXOQCS
Donald Kean


DATE


09 July 08



UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 08 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 034	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-6I CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-3 was accomplished on the WOW today</p>					
 _____ UXOQCS Donald Kean				7/08/08 DATE	



UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE July 03 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 032	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 was accomplished 178 targets in W048</p> <p>QC blind Seed ESCA- SEA 015 was recovered by the dig team in W048 flag # 3671</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 03 July 08 _____ DATE </div> </div>					


UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 02 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 031	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					PRECIP (IN) 0.00
WORK PERFORMED TODAY					
<p>QC-1 was accomplished on 59 targets in W34 and 135 targets in W048</p>					
 _____ UXOQCS Donald Kean				02 July 08 _____ DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE July 01 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 030	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 was accomplished on 128 anomalies in W118, W119 and W120</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 01 Jul 08 _____ DATE </div> </div>					

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE June 30 2008	
TITLE AND LOCATION		REPORT NO		13135.004.001-QC 029	
ESCA No. W9128F-07-2-01621		Fort Ord Seaside 1-4 SCA Polygons and points			
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
				PRECIP (IN) 0.00	
WORK PERFORMED TODAY					
<p>QC-1 was accomplished on 184 anomalies in W111</p>					
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;">  _____ UXOQCS Donald Kean </div> <div style="text-align: center;"> 30 June 08 _____ DATE </div> </div>					

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 27 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 028	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 was accomplished on 81 anomalies in W048</p>					
 UXOQCS Donald Kean				 DATE	

UXO QUALITY CONTROL REPORT (ATTACH ADDITIONAL SHEETS IF NECESSARY)				DATE June 26 2008	
ESCA No. W9128F-07-2-01621		TITLE AND LOCATION Fort Ord Seaside 1-4 SCA Polygons and points		REPORT NO 13135.004.001-QC 027	
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 was accomplished on 370 targets at the WOW</p> <p>QC-1 was accomplished on the following SCA Points;</p> <p style="margin-left: 40px;">164; 167; 209; 210; 317; 318; and 319</p>					
 _____ UXOQCS Donald Kean				 _____ DATE	

UXO QUALITY CONTROL REPORT <small>(ATTACH ADDITIONAL SHEETS IF NECESSARY)</small>				DATE June 25 2008	
TITLE AND LOCATION		REPORT NO			
ESCA No. W9128F-07-2-01621 Fort Ord Seaside 1-4 SCA Polygons and points		13135.004.001-QC 026			
CONTRACTOR Weston Solutions, Inc.			UXOQCS Donald Kean		
EQUIPMENT USED EM-61 CART SCHONSTEDT		WEATHER SUNNY/CLOUDY		MAX TEMP (F)	MIN TEMP (F)
					0.00
WORK PERFORMED TODAY					
<p>QC-1 was accomplished on 137 targets at the WOW</p>					
 UXOQCS Donald Kean				25 June 08 DATE	

Fort Ord SCA Quality Control Report Page 1 of 1

Page 1 of 1