



Photo 6. Well location EW-OU1-71-A before oak tree was trimmed on the south (background) side of the well location. See photo 21 for post-trimming view.



Photo 7. Oaks trees located at well location MW-B (MW-OU1-86-A) before trimming. See photo 23 for post-trimming view.



Photo 8. Well location MW-D (MW-OU1-85-A) after oak tree was trimmed.



Photo 9. Before and after clearing to allow drill rig access to well location MW-F (MW-OU1-83-A).



Photo 10. Well location MW-E (MW-OU1-84-A) before and after clearing.