

Photo 32. Well location MW-D (MW-OU1-85-A) after drilling was completed.



Photo 34. Well location EW-OU1-71-A after drilling was completed. The pallet in this picture was subsequently removed.



Photo 33. Well location MW-B (MW-OU1-86-A) after drilling was completed.



Photo 35. Well location MW-C (EW-OU1-87-A) after drilling was completed.

Attachment A

FONR OU-1 Environmental Monitoring Report Site Pictures

Page 8